

| No | Phone | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comment |
|----|----------------------------|-------------|-------------------|------------------------|--|
| 1 | Apple iPhone | A' | ✓ | 0-07-0258-0.07 | 3.0 (7A341) |
| 2 | Apple iPhone 3G | A' | ✓ | 0-07-0258-0.07 | 4.2.1 (8C148) |
| 3 | Apple iPhone 3GS | A' | ✓ | 0-07-0258-0.07 | 6.1.2 (10B146) |
| 4 | Apple iPhone 4 | A' | ✓ | 0-07-0258-0.07 | 6.1.3 (10B329) |
| 5 | Apple iPhone 4S | A' | ✓ | 0-07-0258-0.07 | 6.1.3 (10B329) |
| 6 | Apple iPhone 5 | A' | ✓ | 0-07-0258-0.08 | 6.1.3 (10B329) |
| 7 | Apple iPhone 5c | A' | ✓ | 0-07-0258-0.08 | 7.0.2 (11A501) |
| 8 | Apple iPhone 5s | A' | ✓ | 0-07-0258-0.08 | 7.0.3 (11B511) |
| 9 | Apple iPhone 6 | A' | ✓ | 0-07-0258-0.08 | 8.0.2 (12A405) |
| 10 | Apple iPhone 6s | A' | ✓ | 0-07-0258-0.08 | 10.0.1 (14A403) |
| 11 | Apple iPhone 7 | A' | ✓ | 0-07-0258-0.08 | 10.0.3 (14A551) |
| 12 | Apple iPhone SE | A' | ✓ | 0-07-0258-0.08 | 9.3.1 (13E238) |
| 13 | BlackBerry 8100 Pearl | F | ✓ | 0-07-0258-0.02 | V4.5.0.69 (PI2.7.0.72) |
| 14 | BlackBerry 8110 Pearl | F | ✓ | 0-07-0258-0.02 | V4.5.0.55 (PI 2.7.0.68) |
| 15 | BlackBerry 8300 Curve | F | ✓ | 0-07-0258-0.02 | V4.5.0.182 |
| 16 | BlackBerry 8310 Curve | F | ✓ | 0-07-0258-0.02 | V4.5.0.180 (PI 2.7.0.105) |
| 17 | BlackBerry 8520 Curve | F | ✓ | 0-07-0258-0.01 | V4.6.1.286 PI 4.2.0.122 |
| 18 | BlackBerry 8800 | A' | ✓ | 0-07-0258-0.02 | V4.5.0.174 (PI 2.7.0.105) |
| 19 | BlackBerry 8900 Curve | E | ✓ | 0-07-0258-0.01 | V5.0.0.411 PL5.2.0.31 |
| 20 | BlackBerry 9100 Pearl | E | ✓ | 0-07-0258-0.01 | V5.0.0.696 (Platform 6.2.0.57) |
| 21 | BlackBerry 9105 Pearl | E | ✓ | 0-07-0258-0.01 | V5.0.0.696 (Platform 6.2.0.57) |
| 22 | BlackBerry 9320 Curve | E | ✓ | 0-07-0258-0.01 | v7.1.0.398 (Platform 9.49.0.31) |
| 23 | BlackBerry 9360 Curve | E | ✓ | 0-07-0258-0.01 | v7.1.0.234 (Platform 9.6.0.36) |
| 24 | BlackBerry 9380 Curve | E | ✓ | 0-07-0258-0.01 | v7.1.0.470 (Platform 9.32.0.108) |
| 25 | BlackBerry 9500 Storm | F | ✓ | 0-07-0258-0.01 | v4.7.0.41 PI 4.0.0.40 |
| 26 | BlackBerry 9520 Storm2 | F | ✓ | 0-07-0258-0.01 | V5.0.0.497 PI 4.2.0.220 |
| 27 | BlackBerry 9700 Bold | F | ✓ | 0-07-0258-0.01 | v5.0.0.979 PI 5.1.0.177 |
| 28 | BlackBerry 9780 Bold | F | ✓ | 0-07-0258-0.01 | v6.0.0.534 PI 6.6.0.220 |
| 29 | BlackBerry 9800 Torch | F | ✓ | 0-07-0258-0.01 | v6.0.0.534 PI 6.6.0.200 |
| 30 | BlackBerry 9810 Torch | F | ✓ | 0-07-0258-0.01 | V7.0.0.261 PL 5.0.0.469 |
| 31 | BlackBerry 9860 Torch | A' | ✓ | 0-07-0258-0.01 | V7.0.0.261 PL 5.0.0.464 |
| 32 | BlackBerry 9900 Bold Touch | E | ✓ | 0-07-0258-0.01 | v7.0.0.585 (Platform 5.0.0.734) |
| 33 | BlackBerry Q5 | A' | ✓ | 0-07-0258-0.01 | 10.2.0.429 |
| 34 | BlackBerry Q10 | A' | ✓ | 0-07-0258-0.01 | v10.2.1.537 |
| 35 | BlackBerry Q20 Classic | A' | ✓ | 0-07-0258-0.01 | v10.3.2.2836 |
| 36 | BlackBerry Z10 | A' | ✓ | 0-07-0258-0.01 | 10.0.10.90 |
| 37 | CAT (Caterpillar) B15 | E | | | Android 4.1.2 1375548110 |
| 38 | CAT (Caterpillar) B30 | B | ✓ | 0-07-0258-0.01 | 0-07-0258-0.01 |
| 39 | HTC 7 Mozart | A' | ✓ | 0-07-0258-0.01 | WinPhone 7.5 Radio 5.71.09.02a_22.51.50.21U |
| 40 | HTC 7 Pro | B | ✓ | 0-07-0258-0.01 | WinPhone 7.5 Radio 5.71.09.02a_22.51.50.21U |
| 41 | HTC Desire | A' | ✓ | 0-07-0258-0.01 | Android OS 2.2.2 sw. Nr. 2.29.110.6 |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

| No | Phone | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comment |
|----|------------------------------|-------------|-------------------|------------------------|--|
| 42 | HTC Desire HD | A' | ✓ | 0-07-0258-0.01 | Android 2.3.5 sw: 3.12..405.1 |
| 43 | HTC Desire S | A' | ✓ | 0-07-0258-0.01 | Android OS 2.3.5 2.10.401.8 |
| 44 | HTC Desire X | A' | ✓ | 0-07-0258-0.01 | Android OS 4.1.1 sw. Nr. 2.23.118.2 |
| 45 | HTC Desire Z | B | ✓ | 0-07-0258-0.01 | Android OS 2.3.3 sw. Nr. 2.42.405.5 |
| 46 | HTC Desire 310 | A' | ✓ | 0-07-0258-0.01 | Android OS 4.2.2 sw. Nr. 1.00.118.4 |
| 47 | HTC EVO 3D X515m | A' | ✓ | 0-07-0258-0.01 | Android OS 4.0.3 sw. Nr. 3.28.401.1 |
| 48 | HTC Incredible S | A' | ✓ | 0-07-0258-0.01 | Android OS 2.2.1 sw. Nr. 1.36.405.1 |
| 49 | HTC Legend | F | ✓ | 0-07-0258-0.01 | Android OS 2.2 sw. Nr. 3.14.161.1 |
| 50 | HTC Magic | F | ✓ | 0-07-0258-0.02 | 1.5 |
| 51 | HTC Hero / T-Mobile G2 Touch | B | ✓ | 0-07-0258-0.02 | FW: 1.5 1.0.0.A6288 |
| 52 | HTC One | A' | ✓ | 0-07-0258-0.01 | Android 4.2.2 2.24.111.5 |
| 53 | HTC ONE mini | A' | ✓ | 0-07-0258-0.01 | Android 4.4.2 3.10.401.6 |
| 54 | HTC One S | A' | ✓ | 0-07-0258-0.01 | Android 4.1.1 3.16.111.7 |
| 55 | HTC One V | A' | ✓ | 0-07-0258-0.01 | Android 4.0.3 2.22.111.1 |
| 56 | HTC One X | A' | ✓ | 0-07-0258-0.01 | Android 4.0.4 sw. Nr. 2.17.401.2 |
| 57 | HTC Sensation | A' | ✓ | 0-07-0258-0.01 | Android OS 4.0.3 sw. Nr. 3.32.111.11 |
| 58 | HTC Tattoo | F | ✓ | 0-07-0258-0.02 | SW 1.67.405.70 |
| 59 | HTC Touch2 | E | ✓ | 0-07-0258-0.02 | 1.28.407.4 (66092) |
| 60 | HTC Touch 3G | F | ✓ | 0-07-0258-0.02 | 2.32.407.2 (44800) |
| 61 | HTC Touch Cruise | F | ✓ | 0-07-0258-0.02 | 3.13.407.0 GER |
| 62 | HTC Touch Diamond | F | ✓ | 0-07-0258-0.02 | Build 19588.1.1.4 Radio 0.93.25.NS16 |
| 63 | HTC Touch DIAMOND 2 | F | ✓ | 0-07-0258-0.02 | Radio 1.19.407.1 (51489) GER |
| 64 | HTC Touch Dual | F | ✓ | 0-07-0258-0.02 | 1.31.407.09 Radio 1.58.16.27 |
| 65 | HTC Touch HD | E | ✓ | 0-07-0258-0.02 | ROM: 1.14.407.3 (22273) GER |
| 66 | HTC HD mini | E | ✓ | 0-07-0258-0.01 | ROM: 1.36.479.1 (94538) WWE |
| 67 | HTC HD2 | A' | ✓ | 0-07-0258-0.01 | 3.14.407.2 (04666) GER |
| 68 | HTC HD7 | A' | ✓ | 0-07-0258-0.01 | WinPhone 7.5 Radio sw:5.71.09.02a_22.51.50.21U |
| 69 | HTC Touch Pro | F | ✓ | 0-07-0258-0.02 | 1.60.161.1 WWE |
| 70 | HTC Touch Pro2 | B | ✓ | 0-07-0258-0.02 | Radio 2.07.407.1 (80303) GER |
| 71 | HTC Wildfire | E | ✓ | 0-07-0258-0.01 | Android 2.2.1 2.24.162.1 |
| 72 | HTC Windows Phone 8X | A' | ✓ | 0-07-0258-0.01 | WinPhone 8 Radio sw:1.14b.32.19.06_15.42.32.19 |
| 73 | HUAWEI Ascend P1 U9200 | A' | ✓ | 0-07-0258-0.01 | Android 4.0.3 U9200-1V100R001C00B219 |
| 74 | LG BL20 New Chocolate | F | | | BL20 V10d |
| 75 | LG E960 Nexus 4 | A' | ✓ | 0-07-0258-0.01 | Android 4.4.2 KOT49H |
| 76 | LG Nexus 5 | A' | ✓ | 0-07-0258-0.01 | Android 4.4.4 KTU84P |
| 77 | LG G2 D802 | A' | ✓ | 0-07-0258-0.01 | Android 4.2.2 D80210a-262-01 |
| 78 | LG G2 mini LTE (D620r) | A' | ✓ | 0-07-0258-0.01 | Android 4.4.2 V10c-260-01 |
| 79 | LG GC900 Viewty Smart | E | | | GC900AT_V10b |
| 80 | LG GD900 Crystal | F | ✓ | 0-07-0258-0.01 | GD900AT_V10c |
| 81 | LG GM750 | E | ✓ | 0-07-0258-0.01 | V10b |
| 82 | LG GT500 | E | ✓ | 0-07-0258-0.01 | GT500-V10i |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

| No | Phone | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comment |
|-----|------------------------------------|-------------|-------------------|------------------------|---|
| 83 | LG KF 750 Secret | F | | | KF750-V10a-24042008 |
| 84 | LG KM 900 Arena | E | | | KM900AT_V10t |
| 85 | LG KP500 Cookie | F | | | KP500AT_V10d |
| 86 | LG KU 990 | F | | | n.a. |
| 87 | LG P710 Optimus L7 II | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 SW LG-P71010e-EUR-XX |
| 88 | LG P760 Optimus L9 | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 SW LG-P76020c-EUR-XX |
| 89 | LG P880 Optimus 4X HD | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 SW LG-P88020a-232-10 |
| 90 | LG P970 | A' | ✓ | 0-07-0258-0.01 | Android 2.3.4 SW LG-P970-V20b |
| 91 | LG Optimus 2X (P990 Optimus Speed) | A' | ✓ | 0-07-0258-0.01 | Android 2.2.2 SW LGE LGP990-V10e |
| 92 | Microsoft Lumia 532 Dual SIM | A' | ✓ | 0-07-0258-0.01 | WinPhone 8.1 Update SW 20c9.00076.0001 |
| 93 | Microsoft Lumia 550 | A' | ✓ | 0-07-0258-0.01 | WinPhone10 Mobile SW 01078.00037.16082.41022 |
| 94 | Motorola DEFY (MB525) | F | ✓ | 0-07-0258-0.01 | 34.906.1.mb525.t-Mobile.en.DE |
| 95 | Motorola DEFY+ (MB526) | F | ✓ | 0-07-0258-0.01 | Android 2.3.6 45.0.2310.MB526.Retail.en.DE |
| 96 | Motorola Milestone | F | ✓ | 0-07-0258-0.01 | Android 2.2.1 |
| 97 | Motorola Motoluxe (XT615) | A' | ✓ | 0-07-0258-0.01 | Android 2.3.7 NK: 1_67C_4035 |
| 98 | Motorola RAZR i XT890 | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 9.8.21-50_SMI-26.1358455837 |
| 99 | Motorola RAZR XT910 | A' | ✓ | 0-07-0258-0.01 | Android 4.0.4 U_04.10.00R |
| 100 | Nokia 113 | F | | | V03.32 |
| 101 | Nokia 208.1 | F | | | V06.01 |
| 102 | Nokia 500 | F | ✓ | 0-07-0258-0.01 | Symbian Belle 111.020.0059 |
| 103 | Nokia 515 | F | | | V 07.01 |
| 104 | Nokia 2330 classic | F | | | V 06.46 |
| 105 | Nokia 2700 classic | F | ✓ | 0-07-0258-0.04 | V 07.15 |
| 106 | Nokia 2730 classic | F | | | V 10.40 |
| 107 | Nokia 3109c | F | | | V07.21 |
| 108 | Nokia 3110c | F | | | V04.91 |
| 109 | Nokia 3720 classic | F | | | V09.10 |
| 110 | Nokia 5230 | F | ✓ | 0-07-0258-0.04 | V 12.0.089 |
| 111 | Nokia 5530 XpressMusic | F | | | V 11.0.054 |
| 112 | Nokia 5630 XpressMusic | E | | | V 012.008 |
| 113 | Nokia 5730 XpressMusic | F | ✓ | 0-07-0258-0.01 | 100.48.122 |
| 114 | Nokia 5800 XpressMusic | F | ✓ | 0-07-0258-0.04 | V 20.0.012 |
| 115 | Nokia 6300 | E | | | V 04.70 |
| 116 | Nokia 6300i | E | | | V03.41 |
| 117 | Nokia 6301 | E | | | V 04.61 |
| 118 | Nokia 6500c | E | ✓ | 0-07-0258-0.01 | V 03.21 |
| 119 | Nokia 6700 classic | E | ✓ | 0-07-0258-0.01 | V 07.60 |
| 120 | Nokia 6710 Navigator | F | ✓ | 0-07-0258-0.04 | 021.013 |
| 121 | Nokia 6720 classic | F | ✓ | 0-07-0258-0.01 | 032.001 |
| 122 | Nokia 7900 Prism | E | ✓ | 0-07-0258-0.01 | V03.40 |
| 123 | Nokia 8600 Luna | F | | | V03.52 |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

| No | Phone | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comment |
|-----|----------------------------|-------------|-------------------|------------------------|---|
| 124 | Nokia 8800 | F | | | V03.60 |
| 125 | Nokia Asha 300 | E | ✓ | 0-07-0258-0.04 | V 07.57 |
| 126 | Nokia Asha 311 | E | ✓ | 0-07-0258-0.01 | V 05.92 |
| 127 | Nokia C1-01 | F | | | V 06.15a |
| 128 | Nokia C2-01 | F | ✓ | 0-07-0258-0.04 | V 11.40 |
| 129 | Nokia C3-00 | E | ✓ | 0-07-0258-0.04 | V 08.63 |
| 130 | Nokia C3-01 Touch and Type | F | ✓ | 0-07-0258-0.04 | V 07.15 |
| 131 | Nokia C5 | E | ✓ | 0-07-0258-0.01 | V 062.001 |
| 132 | Nokia C5-00 5MP | E | ✓ | 0-07-0258-0.01 | V 073.001 |
| 133 | Nokia C5-03 | F | ✓ | 0-07-0258-0.04 | V 23.0.015 |
| 134 | Nokia C6 | F | ✓ | 0-07-0258-0.04 | V 42.0.004 |
| 135 | Nokia C7-00 | A' | ✓ | 0-07-0258-0.01 | V 012.003 |
| 136 | Nokia E5-00 | E | ✓ | 0-07-0258-0.04 | V 071.003 |
| 137 | Nokia E6-00 | E | ✓ | 0-07-0258-0.01 | Symbian Belle V 111.140.0058 |
| 138 | Nokia E7-00 | A' | ✓ | 0-07-0258-0.01 | Symbian Belle V 111.030.0609 |
| 139 | Nokia E50 | F | | | V06.27.1.0 |
| 140 | Nokia E51 | E | ✓ | 0-07-0258-0.04 | 411.34.001 |
| 141 | Nokia E52 | E | | | 033.002 |
| 142 | Nokia E55 | E | | | 034.001 |
| 143 | Nokia E61i | A' | | | V 1.0633.22.05 |
| 144 | Nokia E66 | F | | | V 102.07.81 |
| 145 | Nokia E71 | E | | | V 007.49.4 |
| 146 | Nokia E72 | A' | | | 081.003 |
| 147 | Nokia E75 | F | | | 110.48.125 |
| 148 | Nokia Lumia 520 | A' | ✓ | 0-07-0258-0.01 | Win Phone 8.0 SW 2.0.242020.8 |
| 149 | Nokia Lumia 610 | A' | ✓ | 0-07-0258-0.01 | Win Phone 7.5 Radio sw:1.0.66.00 |
| 150 | Nokia Lumia 625 | A' | ✓ | 0-07-0258-0.01 | Windows Phone 8.0 Radio sw:3.2.28038.7 |
| 151 | Nokia Lumia 635 | A' | ✓ | 0-07-0258-0.01 | Win Phone 8.1 Update Radio sw:201c1.00401.0001 |
| 152 | Nokia Lumia 800 | A' | ✓ | 0-07-0258-0.01 | Win Phone 7.5 Radio sw:1.6.00.24 |
| 153 | Nokia Lumia 820 | A' | ✓ | 0-07-0258-0.01 | Win Phone 8.0 Radio sw:1.0.202075.3 |
| 154 | Nokia Lumia 900 | A' | ✓ | 0-07-0258-0.01 | Win Phone 7.5 Radio sw:2.1.75.25 |
| 155 | Nokia Lumia 920 | A' | ✓ | 0-07-0258-0.01 | Win Phone 8.0 Radio sw:1.0.202075.3 |
| 156 | Nokia Lumia 925 | A' | ✓ | 0-07-0258-0.01 | Win Phone 8.0 Radio sw:3.2.04033.1 |
| 157 | Nokia Lumia 930 | A' | ✓ | 0-07-0258-0.01 | WinPhone8.1UpdateRadio sw:201c110.00039.0001 |
| 158 | Nokia Lumia 1020 (909) | B | ✓ | 0-07-0258-0.01 | Windows Phone 8.0 Radio sw:3.2.04047.1 |
| 159 | Nokia N8 | A' | ✓ | 0-07-0258-0.01 | Symbian Belle V 111.040.1511 |
| 160 | Nokia N9 | A' | ✓ | 0-07-0258-0.01 | V 40.2012.21-3.342.01.1_PR_342 |
| 161 | Nokia N78 | F | ✓ | 0-07-0258-0.04 | V 12.26 |
| 162 | Nokia N79 | F | ✓ | 0-07-0258-0.04 | V 11.049 |
| 163 | Nokia N97 | F | ✓ | 0-07-0258-0.01 | V 22.0.110 |
| 164 | Nokia N97 mini | F | ✓ | 0-07-0258-0.01 | v 30.0.004 |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

| No | Phone | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comment |
|-----|---------------------------------|-------------|-------------------|------------------------|---|
| 165 | Nokia N900 | F | ✓ | 0-07-0258-0.01 | V21.2011.38-1 |
| 166 | Nokia X6 | F | ✓ | 0-07-0258-0.04 | V 40.0.002 |
| 167 | Nokia X7-00 | A' | ✓ | 0-07-0258-0.01 | Symbian Belle V 111.040.1511 |
| 168 | Samsung Ace S5830 | E | ✓ | 0-07-0258-0.01 | Android 2.3.3 sw S5830XWKP5 |
| 169 | Samsung B550H Xcover 550 | A' | ✓ | 0-07-0258-0.01 | B550HXXUAOE6 |
| 170 | Samsung B2100 | F | | | B2100XXHL1 |
| 171 | Samsung B2700 | F | | | B2700XXIB2 |
| 172 | Samsung B3410 | F | | | B3410XXIK4 |
| 173 | Samsung B7330 OmniaPro | E | ✓ | 0-07-0258-0.01 | B7330XXIG2 |
| 174 | Samsung B7610 OmniaPro | F | ✓ | 0-07-0258-0.01 | B7610XXIK2 |
| 175 | Samsung C6625 | E | | | C6625BUIE1 |
| 176 | Samsung E2121B | F | | | E2121BXXK1 |
| 177 | Samsung G386F Galaxy Core LTE | A' | ✓ | 0-07-0258-0.01 | Android 4.2.2 JDQ39.G386FXXUANB4 |
| 178 | Samsung G388F Galaxy Xcover 3 | A' | ✓ | 0-07-0258-0.01 | Android 4.4.4 KTU84P.G388FXXU1AOG4 |
| 179 | Samsung G800F Galaxy S5 mini | A' | ✓ | 0-07-0258-0.01 | Android 4.4.2 KOT49H.G800FXXU1ANJ2 |
| 180 | Samsung i7500 Galaxy | F | ✓ | 0-07-0258-0.01 | I7500XXJB2 |
| 181 | Samsung I8000 Omnia II | A' | ✓ | 0-07-0258-0.01 | I8000XXII6 |
| 182 | Samsung I8150 Galaxy W | A' | ✓ | 0-07-0258-0.01 | Android 2.3.6 I8150XXLMI |
| 183 | Samsung I8160 Galaxy Ace 2 | A' | ✓ | 0-07-0258-0.01 | I8160XXLI2 |
| 184 | Samsung I8190 Galaxy S III mini | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 I8190XXAMG4 |
| 185 | Samsung i8320 Vodafone 360 H1 | F | ✓ | 0-07-0258-0.01 | i8320BUIK1 |
| 186 | Samsung I8700 Omnia 7 | A' | ✓ | 0-07-0258-0.01 | Windows Phone 7.5 Radio sw:2424.11.9.1 |
| 187 | Samsung I8750 Ativ S | A' | ✓ | 0-07-0258-0.01 | Windows Phone 8.0 Radio sw: 2424.13.5.1 |
| 188 | Samsung i8910 Omnia HD | B | ✓ | 0-07-0258-0.01 | I8910XXJA1 |
| 189 | Samsung I9000 Galaxy S | A' | ✓ | 0-07-0258-0.01 | I9000XXJW4 |
| 190 | Samsung I9001 Galaxy S Plus | A' | ✓ | 0-07-0258-0.01 | Android 2.3.6 I9001XXXPK |
| 191 | Samsung I9100 Galaxy S II | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 I9100XXMS2 |
| 192 | Samsung I9195 Galaxy S 4 mini | A' | ✓ | 0-07-0258-0.01 | Android 4.2.2 I9195XXUBM7 |
| 193 | Samsung I9300 Galaxy S III | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 sw: I9300XXELL4 |
| 194 | Samsung I9305 Galaxy S III Lte | A' | ✓ | 0-07-0258-0.01 | Android 4.4.4 KTU84P.I9305XXUFOA1 |
| 195 | Samsung I9505 Galaxy S4 | A' | ✓ | 0-07-0258-0.01 | Android 4.2.2 sw: JDQ39.I9505XXUAMDM |
| 196 | Samsung J320F Galaxy J3 (2016) | A' | ✓ | 0-07-0258-0.01 | Android 5.1.1 LMY47V.J320FXXS0AQA1 |
| 197 | Samsung S3650 Corby | F | | | S3650XXII3 |
| 198 | Samsung S5230 Avilla | F | | | S5230BVIE3 |
| 199 | Samsung S5260 Star II | E | ✓ | 0-07-0258-0.01 | S5260XXKC4 |
| 200 | Samsung S5360 Galaxy Y | E | ✓ | 0-07-0258-0.01 | Android 2.3.6 sw: S5360XXLE1 |
| 201 | Samsung S5570i Galaxy Mini | F | ✓ | 0-07-0258-0.01 | Android 2.3.6 sw: S5570IXLX6 |
| 202 | Samsung S5690 Galaxy Xcover | A' | | | Android 2.3.6 sw: S5690XXLL1 |
| 203 | Samsung S6500 Galaxy mini 2 | E | ✓ | 0-07-0258-0.01 | Android 2.3.6 sw: S6500XXLK2 |
| 204 | Samsung S7220 | F | ✓ | 0-07-0258-0.01 | S7220XXIB7 |
| 205 | Samsung S7500 Galaxy Ace Plus | A' | ✓ | 0-07-0258-0.01 | Android 2.3.6 S7500XXLK1 |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

| No | Phone | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comment |
|-----|---------------------------------------|-------------|-------------------|------------------------|---|
| 206 | Samsung S7560 Galaxy Trend (Ace II X) | A' | ✓ | 0-07-0258-0.01 | Android 4.0.4 S7560XXAMF1 |
| 207 | Samsung S7580 Galaxy Trend Plus | A' | ✓ | 0-07-0258-0.01 | Android 4.2.2 JDQ39.S7580XXUBOA1 |
| 208 | Samsung S7710 Galaxy Xcover 2 | A' | | | Android 4.1.2 S7710XXAMB5 |
| 209 | Samsung S8000 Jet | F | ✓ | 0-07-0258-0.01 | S8000XIF5 |
| 210 | Samsung S8300V | E | ✓ | 0-07-0258-0.01 | S8300BUI6 |
| 211 | Samsung S8500 Wave | A' | ✓ | 0-07-0258-0.01 | S8500XXLA1 |
| 212 | Samsung S8530 Wave II | A' | ✓ | 0-07-0258-0.01 | S8530XXLA1 |
| 213 | Samsung S8600 Wave 3 | A' | ✓ | 0-07-0258-0.01 | S8600XLD1 |
| 214 | Samsung SGH-F480 | E | | | F480BOHE3 |
| 215 | Samsung SGH-F700v | F | | | F700AMGJ8 |
| 216 | Samsung SGH-G600 | F | | | |
| 217 | Samsung SGH-U700v | F | | | U700V.002 |
| 218 | Samsung SGH-i900 OMNIA 8GB | E | | | i900XXIB2 |
| 219 | Samsung SGH-i900 OMNIA 16GB | E | | | i900BOHH2 |
| 220 | Samsung Xcover 271 (B2710) | F | ✓ | 0-07-0258-0.01 | B2710BOJJ3 |
| 221 | SONY Xperia E (C1505) | A' | ✓ | 0-07-0258-0.01 | Android 4.1.1 sw 11.3.A.2.23 |
| 222 | SONY Xperia J (ST26i) | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 sw 11.2.A.0.31 |
| 223 | SONY Xperia M (C1905) | A' | ✓ | 0-07-0258-0.01 | Android 4.3 sw 15.4.A.1.9 |
| 224 | SONY Xperia P (LT22i) | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 sw 6.2.A.0.400 |
| 225 | SONY Xperia S (LT26) | A' | ✓ | 0-07-0258-0.01 | Android 4.0.4 sw 6.1.A.2.45 |
| 226 | SONY Xperia SP (C5303) | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 sw 12.0.A.1.257 |
| 227 | SONY Xperia T (LT30p) | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 sw 9.1.A.0.489 |
| 228 | SONY Xperia Tipo (ST21i) | E | ✓ | 0-07-0258-0.01 | Android 4.0.4 sw 11.0.A.22 |
| 229 | SONY Xperia U (ST25i) | E | | | Android 4.0.4 sw 6.1.1.B.1.10 |
| 230 | SONY Xperia Z1 Compact (D5503) | A' | | | Android 4.4.4 sw 14.4.A.0.118 |
| 231 | SONY Xperia Z3 Compact (D5803) | A' | | | Android 6.0.1 sw 23.5.A.1.291 |
| 232 | Sony Ericsson Aino | F | ✓ | 0-07-0258-0.05 | R7BA084 |
| 233 | Sony Ericsson C510 | F | ✓ | 0-07-0258-0.05 | R1FA035 |
| 234 | Sony Ericsson C902 | E | ✓ | 0-07-0258-0.05 | R3E004 |
| 235 | Sony Ericsson Elm | F | ✓ | 0-07-0258-0.05 | R7CA061 |
| 236 | Sony Ericsson G502 | F | | | R1EA033 |
| 237 | Sony Ericsson Satio (Idou) | F | ✓ | 0-07-0258-0.05 | R1BB041 |
| 238 | Sony Ericsson W960i | F | ✓ | 0-07-0258-0.05 | R6G04 |
| 239 | Sony Ericsson Vivaz | E | | | 1224-4699_R2AK006 |
| 240 | Sony Ericsson Xperia Arc (LT15i) | A' | ✓ | 0-07-0258-0.01 | Android 4.0.4 sw 4.1.B.0.587 |
| 241 | Sony Ericsson Xperia Arc S (LT18i) | A' | ✓ | 0-07-0258-0.01 | Android 4.0.4 sw 4.1.B.0.587 |
| 242 | Sony Ericsson Xperia neo V (MT11i) | A' | ✓ | 0-07-0258-0.01 | Android 4.0.4 sw 4.1.B.0.587 |
| 243 | Sony Ericsson Xperia ray | E | ✓ | 0-07-0258-0.01 | Android 4.0.4 sw 4.1.B.0.587 |
| 244 | Sony Ericsson Xperia X1 | F | ✓ | 0-07-0258-0.02 | 1.00.161.2 |
| 245 | Sony Ericsson Xperia X2 | F | ✓ | 0-07-0258-0.01 | R1AA035 |
| 244 | Sony Ericsson Xperia X8 | F | | | Android 2.1-update1 |
| 245 | Sony Ericsson Xperia X10 | A' | ✓ | 0-07-0258-0.01 | Android 2.3.3 3.0.1.G.0.75 |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com