

| No | Phone | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comments |
|----|----------------------------|-------------|-------------------|------------------------|--|
| 1 | Apple iPhone | A/E | ✓ | 0-07-0258-0.07 | 3.0 (7A341) |
| 2 | Apple iPhone 3G | E | ✓ | 0-07-0258-0.07 | 4.2.1 (8C148) |
| 3 | Apple iPhone 3GS | E | ✓ | 0-07-0258-0.07 | 6.1.2 (10B146) |
| 4 | Apple iPhone 4 | A/E | ✓ | 0-07-0258-0.07 | 7.0 (11A465) |
| 5 | Apple iPhone 4S | A/E | ✓ | 0-07-0258-0.07 | 7.1.1 (11D201) |
| 6 | Apple iPhone 5 | E | ✓ | 0-07-0258-0.08 | 7.0 (11A465) |
| 7 | Apple iPhone 5c | A' | ✓ | 0-07-0258-0.08 | 7.1.1 (11D201) |
| 8 | Apple iPhone 5s | A' | ✓ | 0-07-0258-0.08 | 7.1.1 (11D201) |
| 9 | Apple iPhone 6 | A' | ✓ | 0-07-0258-0.08 | 8.0.2 (12A405) |
| 10 | Apple iPhone 6s | A' | ✓ | 0-07-0258-0.08 | 10.0.1 (14A403) |
| 11 | Apple iPhone 7 | A' | ✓ | 0-07-0258-0.08 | 10.0.3 (14A551) |
| 12 | Apple iPhone 8 | A' | ✓ | 0-07-0258-0.08 | 11.0.3 (15A432) |
| 13 | Apple iPhone SE | A' | ✓ | 0-07-0258-0.02 | 9.3.1 (13E238) |
| 14 | BlackBerry 8100 Pearl | F | ✓ | 0-07-0258-0.02 | V4.5.0.69 (PI2.7.0.72) |
| 15 | BlackBerry 8110 Pearl | F | ✓ | 0-07-0258-0.02 | V4.5.0.55 (PI 2.7.0.68) |
| 16 | BlackBerry 8520 Curve | F | ✓ | 0-07-0258-0.01 | V4.6.1.286 PI 4.2.0.122 |
| 17 | BlackBerry 8800 | A' | ✓ | 0-07-0258-0.02 | V4.5.0.174 (PI 2.7.0.105) |
| 18 | BlackBerry 9100 Pearl | E | ✓ | 0-07-0258-0.01 | V5.0.0.696 (Platform 6.2.0.57) |
| 19 | BlackBerry 9105 Pearl | E | ✓ | 0-07-0258-0.01 | V5.0.0.696 (Platform 6.2.0.57) |
| 20 | BlackBerry 9320 Curve | E | ✓ | 0-07-0258-0.01 | v7.1.0.714 (Platform 9.49.0.76) |
| 21 | BlackBerry 9360 Curve | E | ✓ | 0-07-0258-0.01 | v7.1.0.234 (Platform 9.6.0.36) |
| 22 | BlackBerry 9500 Storm | F | ✓ | 0-07-0258-0.01 | v4.7.0.41 PI 4.0.0.40 |
| 23 | BlackBerry 9520 Storm2 | F | ✓ | 0-07-0258-0.01 | V5.0.0.497 PI 4.2.0.220 |
| 24 | BlackBerry 9700 Bold | F | ✓ | 0-07-0258-0.01 | v5.0.0.979 PI 5.1.0.178 |
| 25 | BlackBerry 9780 Bold | F | ✓ | 0-07-0258-0.01 | v6.0.0.668 PI 6.6.0.236 |
| 26 | BlackBerry 9800 Torch | F | ✓ | 0-07-0258-0.01 | v6.0.0.534 PI 6.6.0.200 |
| 27 | BlackBerry 9860 Torch | E | ✓ | 0-07-0258-0.01 | V7.1.0.746 PL 5.1.0.546 |
| 28 | BlackBerry 9900 Bold Touch | E | ✓ | 0-07-0258-0.01 | v7.0.0.585 (Platform 5.0.0.734) |
| 29 | BlackBerry Q5 | A' | ✓ | 0-07-0258-0.01 | v10.2.1.537 |
| 30 | BlackBerry Q10 | E | ✓ | 0-07-0258-0.01 | v10.2.1.3175 |
| 31 | BlackBerry Q20 Classic | A' | ✓ | 0-07-0258-0.01 | v10.3.2.2836 |
| 32 | BlackBerry Z10 | A' | ✓ | 0-07-0258-0.01 | v10.2.1.2102 |
| 33 | BlackBerry Z30 | A' | ✓ | 0-07-0258-0.01 | 10.2.1.3062 |
| 34 | CAT (Caterpillar) B30 | F | ✓ | 0-07-0258-0.01 | |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: info@bury.com, Internet: www.bury.com

| No | Phone | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comments |
|----|---|-------------|-------------------|------------------------|--|
| 35 | HTC 7 Mozart | E | ✓ | 0-07-0258-0.01 | Win7.5 Radio 5.71.09.02a_22.51.50.21U |
| 36 | HTC 7 Pro | F | ✓ | 0-07-0258-0.01 | Win7.5 Radio 5.71.09.02a_22.51.50.21U |
| 37 | HTC Desire S | E | ✓ | 0-07-0258-0.01 | Android OS 2.3.5 2.10.401.8 |
| 38 | HTC Desire X | E | ✓ | 0-07-0258-0.01 | Android OS 4.1.1 sw. Nr. 2.23.118.2 |
| 39 | HTC Desire Z | F | ✓ | 0-07-0258-0.01 | Android OS 2.3.3 sw. Nr. 2.42.405.5 |
| 40 | HTC Desire 310 | A' | ✓ | 0-07-0258-0.01 | Android OS 4.2.2 sw. Nr. 1.00.118.4 |
| 41 | HTC EVO 3D X515m | A' | ✓ | 0-07-0258-0.01 | Android OS 4.0.3 sw. Nr. 3.28.401.1 |
| 42 | HTC Incredible S | A' | ✓ | 0-07-0258-0.01 | Android OS 4.0.4 sw. Nr. 4.10.405.1 |
| 43 | HTC Legend | E | ✓ | 0-07-0258-0.01 | Android OS 2.2 sw. Nr. 3.14.161.1 |
| 44 | HTC Magic | F | ✓ | 0-07-0258-0.02 | 1.5 |
| 45 | HTC One | A' | ✓ | 0-07-0258-0.01 | Android 4.2.2 4.20.111.21 |
| 46 | HTC One S | A' | ✓ | 0-07-0258-0.01 | Android 4.1.1 3.16.111.10 |
| 47 | HTC One V | A' | ✓ | 0-07-0258-0.01 | Android 4.0.3 2.22.111.10 |
| 48 | HTC Sensation | A' | ✓ | 0-07-0258-0.01 | Android OS 4.0.3 sw. Nr. 3.33.111.51 |
| 49 | HTC Touch2 | E | ✓ | 0-07-0258-0.02 | 1.28.407.4 (66092) |
| 50 | HTC Touch DIAMOND 2 | F | ✓ | 0-07-0258-0.02 | Radio 1.19.407.1 (51489) GER |
| 51 | HTC Touch Dual | F | ✓ | 0-07-0258-0.02 | 1.31.407.09 Radio 1.58.16.27 |
| 52 | HTC Touch HD | F | ✓ | 0-07-0258-0.02 | ROM: 1.14.407.3 (22273) GER |
| 53 | HTC HD mini | E | ✓ | 0-07-0258-0.01 | ROM: 1.36.479.1 (94538) WWE |
| 54 | HTC HD2 | A' | ✓ | 0-07-0258-0.01 | 3.14.407.2 (04666) GER |
| 55 | HTC HD7 | A' | ✓ | 0-07-0258-0.01 | Win7.5 Radio sw:5.71.09.02a_22.51.50.21U |
| 56 | HTC Touch Pro2 | B | ✓ | 0-07-0258-0.02 | Radio 2.07.407.1 (80303) GER |
| 57 | HTC Wildfire | E | ✓ | 0-07-0258-0.01 | Android 2.2.1 2.24.162.1 |
| 58 | HTC Windows Phone 8X | A' | ✓ | 0-07-0258-0.01 | Win8 Radio sw:1.14b.32.19.06_15.42.32.19 |
| 59 | HUAWEI Ascend P1 U9200 | A' | ✓ | 0-07-0258-0.01 | Android 4.0.3 U9200-1V100R001C00B219 |
| 60 | LG E960 Nexus 4 | A' | ✓ | 0-07-0258-0.01 | Android 4.4.3 KTU84L |
| 61 | LG Nexus 5 | A' | ✓ | 0-07-0258-0.01 | Android 4.4.4 KTU84P |
| 62 | LG G2 D802 | A' | ✓ | 0-07-0258-0.01 | Android 4.2.2 D80210a-262-01 |
| 63 | LG KM 900 Arena | E | | | KM900AT_V10t |
| 64 | LG P710 Optimus L7 II | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 SW LG-P71010e-EUR-XX |
| 65 | LG P760 Optimus L9 | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 SW LG-P76020c-EUR-XX |
| 66 | LG P880 Optimus 4X HD | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 SW LG-P88020c-232-10 |
| 67 | LG P970 | A' | ✓ | 0-07-0258-0.01 | Android 2.3.4 SW LG-P970-V20h |
| 68 | LG Optimus 2X (P990 Optimus Speed) | A' | ✓ | 0-07-0258-0.01 | Android 2.2.2 SW LGE LGP990-V10e |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: info@bury.com, Internet: www.bury.com

| No | Phone | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comments |
|-----|------------------------------|-------------|-------------------|------------------------|--|
| 69 | Microsoft Lumia 532 Dual SIM | A' | ✓ | 0-07-0258-0.01 | Win8.1 Update SW 20c9.00076.0001 |
| 70 | Microsoft Lumia 535 | A' | ✓ | 0-07-0258-0.01 | Win8.1 Update SW 20c9.00076.0001 |
| 71 | Microsoft Lumia 535 Dual SIM | A' | ✓ | 0-07-0258-0.01 | Win8.1 Update SW 20c9.00076.0001 |
| 72 | Microsoft Lumia 550 | A' | ✓ | 0-07-0258-0.01 | Win10 MobileSW 01078.00037.16082.41022 |
| 73 | Microsoft Lumia 640 Dual SIM | A' | ✓ | 0-07-0258-0.01 | Win8.1 Update 2 SW 20c9.00072.0001 |
| 74 | Motorola DEFY (MB525) | F | ✓ | 0-07-0258-0.01 | 34.906.1.mb525.t-Mobile.en.DE |
| 75 | Motorola DEFY+ (MB526) | F | ✓ | 0-07-0258-0.01 | Android 2.3.6 45.0.2310.MB526.Retail.en.DE |
| 76 | Motorola Milestone | F | ✓ | 0-07-0258-0.01 | Android 2.2.1 |
| 77 | Motorola Motoluxe (XT615) | E | ✓ | 0-07-0258-0.01 | Android 2.3.7 NK: 1_67C_4035 |
| 78 | Motorola RAZR i XT890 | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 9.8.21-50_SMI-26.1358455837 |
| 79 | Nokia 208.1 | E | | | V06.01 |
| 80 | Nokia 500 | E | | | Symbian Belle 111.020.0059 |
| 81 | Nokia 515 | E | | | V 07.01 |
| 82 | Nokia Asha 300 | E | | | V 07.57 |
| 83 | Nokia Asha 311 | E | ✓ | 0-07-0258-0.01 | V 05.92 |
| 84 | Nokia C2-01 | E | ✓ | 0-07-0258-0.04 | V 11.40 |
| 85 | Nokia C3-00 | E | ✓ | 0-07-0258-0.04 | V 08.63 |
| 86 | Nokia C3-01 Touch and Type | E | | | V 07.15 |
| 87 | Nokia C5-00 SMP | E | | | V 073.001 |
| 88 | Nokia C5-03 | E | | | V 23.0.015 |
| 89 | Nokia C6 | F | | | V 42.0.004 |
| 90 | Nokia C7-00 | E | | | V 012.003 |
| 91 | Nokia E5-00 | E | ✓ | 0-07-0258-0.04 | V 071.003 |
| 92 | Nokia E6-00 | E | ✓ | 0-07-0258-0.01 | Symbian Belle V 111.140.0058 |
| 93 | Nokia E7-00 | A' | | | Symbian Belle V 111.030.0609 |
| 94 | Nokia E72 | E | | | 081.003 |
| 95 | Nokia Lumia 520 | A' | ✓ | 0-07-0258-0.01 | Win8.0 SW 2.0.242020.8 |
| 96 | Nokia Lumia 610 | F | ✓ | 0-07-0258-0.01 | Win7.5 Radio sw:1.0.66.00 |
| 97 | Nokia Lumia 625 | A' | ✓ | 0-07-0258-0.01 | Win8.0 Radio sw:3.2.28038.7 |
| 98 | Nokia Lumia 635 | A' | ✓ | 0-07-0258-0.01 | Win8.1 Update Radio sw:201c1.00401.0001 |
| 99 | Nokia Lumia 820 | A' | ✓ | 0-07-0258-0.01 | Win8.0 Radio sw:1.0.202158.3 |
| 100 | Nokia Lumia 900 | A' | ✓ | 0-07-0258-0.01 | Win7.5 Radio sw:2.1.75.25 |
| 101 | Nokia Lumia 920 | A' | ✓ | 0-07-0258-0.01 | Win8.0 Radio sw:1.0.202158.3 |
| 102 | Nokia Lumia 925 | A' | ✓ | 0-07-0258-0.01 | Win8.0 Radio sw:3.2.04033.1 |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

| No | Phone | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comments |
|-----|---------------------------------|-------------|-------------------|------------------------|--|
| 103 | Nokia Lumia 930 | A' | ✓ | 0-07-0258-0.01 | Win8.1 UpdateRadio sw:201c110.00039.0001 |
| 104 | Nokia Lumia 1020 (909) | A' | ✓ | 0-07-0258-0.01 | Win8.0 Radio sw:3.2.04047.1 |
| 105 | Nokia N8 | F | ✓ | 0-07-0258-0.01 | Symbian Belle V 111.040.1511 |
| 106 | Nokia N9 | E | ✓ | 0-07-0258-0.01 | V 40.2012.21-3.342.01.1_PR_342 |
| 107 | Nokia N78 | F | ✓ | 0-07-0258-0.04 | V 12.26 |
| 108 | Nokia N79 | F | ✓ | 0-07-0258-0.04 | V 11.049 |
| 109 | Nokia N97 | F | ✓ | 0-07-0258-0.01 | V 22.0.110 |
| 110 | Nokia N900 | F | ✓ | 0-07-0258-0.01 | V21.2011.38-1 |
| 111 | Nokia X6 | F | ✓ | 0-07-0258-0.01 | V 40.0.002 |
| 112 | Nokia X7-00 | A' | | | Symbian Belle V 111.040.1511 |
| 113 | Samsung B550H Xcover 550 | E | ✓ | 0-07-0258-0.01 | B550HXXUAOE6 |
| 114 | Samsung B2100 | F | | | B2100XXHL1 |
| 115 | Samsung B2700 | F | | | B2700XXIB2 |
| 116 | Samsung B7330 OmniaPro | E | ✓ | 0-07-0258-0.01 | B7330XXIG2 |
| 117 | Samsung B7610 OmniaPro | F | ✓ | 0-07-0258-0.01 | B7610XXIK2 |
| 118 | Samsung C6625 | E | | | C6625BUIE1 |
| 119 | Samsung G386F Galaxy Core LTE | A' | ✓ | 0-07-0258-0.01 | Android 4.2.2 JDQ39.G386FXXUANB4 |
| 120 | Samsung G388F Galaxy Xcover 3 | A' | ✓ | 0-07-0258-0.01 | Android 4.4.4 KTU84P.G388FXXU1AOG4 |
| 121 | Samsung G800F Galaxy S5 mini | A' | ✓ | 0-07-0258-0.01 | Android 4.4.2 KOT49H.G800FXXU1ANJ2 |
| 122 | Samsung G900F Galaxy S5 | A' | ✓ | 0-07-0258-0.01 | Android 4.4.2 KOT49H.G900FXXU1ANCE |
| 123 | Samsung G903F Galaxy S5 Neo | A' | ✓ | 0-07-0258-0.01 | Android 6.0.1 MMB29K.G903FXXU1BPF4 |
| 124 | Samsung G920F Galaxy S6 | A' | ✓ | 0-07-0258-0.01 | Android 5.0.2 LRX22G.G920FXXU1AOCV |
| 125 | Samsung G925F Galaxy S6 edge | A' | ✓ | 0-07-0258-0.01 | Android 5.0.2 LRX22G.G925FXXU1AOCV |
| 126 | Samsung G930F Galaxy S7 | A' | ✓ | 0-07-0258-0.01 | Android 6.0.1 MMB29K.G930FXXU1APC8 |
| 127 | Samsung i7500 Galaxy | E | ✓ | 0-07-0258-0.01 | I7500XXMC3 |
| 128 | Samsung I8000 Omnia II | F | ✓ | 0-07-0258-0.01 | I8000XXII6 |
| 129 | Samsung I8150 Galaxy W | E | ✓ | 0-07-0258-0.01 | Android 2.3.6 I8150XXLMI |
| 130 | Samsung I8160 Galaxy Ace 2 | E | ✓ | 0-07-0258-0.01 | I8160XXLL2 |
| 131 | Samsung I8190 Galaxy S III mini | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 I8190XXAMG4 |
| 132 | Samsung i8320 Vodafone 360 H1 | F | ✓ | 0-07-0258-0.01 | i8320BUIK1 |
| 133 | Samsung I8700 Omnia 7 | A' | | | Win7.5 Radio sw:2424.13.5.1 |
| 134 | Samsung I8750 Ativ S | A' | ✓ | 0-07-0258-0.01 | Win8.0 Radio sw: 2424.13.5.1 |
| 135 | Samsung i8910 Omnia HD | B | ✓ | 0-07-0258-0.01 | I8910XXJA1 |
| 136 | Samsung I9000 Galaxy S | A' | ✓ | 0-07-0258-0.01 | I9000XXJW4 |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

| No | Phone | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comments |
|-----|--|-------------|-------------------|------------------------|--|
| 137 | Samsung I9001 Galaxy S Plus | A' | ✓ | 0-07-0258-0.01 | Android 2.3.6 I9001XXKPO |
| 138 | Samsung I9100 Galaxy S II | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 I9100XXMS2 |
| 139 | Samsung I9195 Galaxy S 4 mini | A' | ✓ | 0-07-0258-0.01 | Android 4.2.2 I9195XXUBMJ7 |
| 140 | Samsung I9300 Galaxy S III | A' | ✓ | 0-07-0258-0.01 | Android 4.3 I9300XXUGNA8 |
| 141 | Samsung I9305 Galaxy S III Lte | A' | ✓ | 0-07-0258-0.01 | Android 4.4.4 KTU84P.I9305XXUFOA1 |
| 142 | Samsung I9505 Galaxy S4 | A' | ✓ | 0-07-0258-0.01 | Android 4.2.2 JDQ39.I9505XXUAMDM |
| 143 | Samsung J320F Galaxy J3 (2016) | A' | ✓ | 0-07-0258-0.01 | Android 5.1.1 LMY47V.J320FXXS0AQA1 |
| 144 | Samsung S5230 Avilla | E | | | S5230BVIE3 |
| 145 | Samsung S5260 Star II | E | | | S5260XXKC4 |
| 146 | Samsung S5570i Galaxy Mini | F | ✓ | 0-07-0258-0.01 | Android 2.3.6 sw: S5570IXXLD6 |
| 147 | Samsung S5690 Galaxy Xcover | A' | | | Android 2.3.6 sw: S5690XXLL1 |
| 148 | Samsung S6500 Galaxy mini 2 | E | ✓ | 0-07-0258-0.01 | Android 2.3.6 sw: S6500XXLK2 |
| 149 | Samsung S7220 | E | ✓ | 0-07-0258-0.01 | S7220XXIB7 |
| 150 | Samsung S7500 Galaxy Ace Plus | E | ✓ | 0-07-0258-0.01 | Android 2.3.6 S7500XXMC2 |
| 151 | Samsung S7560 Galaxy Trend Ace II X | A' | ✓ | 0-07-0258-0.01 | Android 4.0.4 S7560XXAMEA |
| 152 | Samsung S7580 Galaxy Trend Plus | A' | ✓ | 0-07-0258-0.01 | Android 4.2.2 JDQ39.S7580XXUBOA1 |
| 153 | Samsung S7710 Galaxy Xcover 2 | A' | | | Android 4.1.2 S7710XXAMB5 |
| 154 | Samsung S8000 Jet | E | ✓ | 0-07-0258-0.01 | S8000XXIF5 |
| 155 | Samsung S8300V | E | ✓ | 0-07-0258-0.01 | S8300BUIC6 |
| 156 | Samsung S8500 Wave | E | ✓ | 0-07-0258-0.01 | S8500XXLA1 |
| 157 | Samsung S8530 Wave II | A' | | | S8530XXLA1 |
| 158 | Samsung S8600 Wave 3 | A' | ✓ | 0-07-0258-0.01 | S8600XXLD1 |
| 159 | Samsung SGH-i900 OMNIA 8GB | F | | | i900XXIB2 |
| 160 | Samsung Xcover 271 (B2710) | F | ✓ | 0-07-0258-0.01 | B2710BOJJ3 |
| 161 | SONY Xperia E (C1505) | E | ✓ | 0-07-0258-0.01 | Android 4.1.1 sw 11.3.A.2.23 |
| 162 | SONY Xperia J (ST26i) | A' | ✓ | 0-07-0258-0.01 | Android 4.1.2 sw 11.2.A.0.31 |
| 163 | SONY Xperia M (C1905) | A' | ✓ | 0-07-0258-0.01 | Android 4.3 sw 15.4.A.1.9 |
| 164 | SONY Xperia P (LT22i) | A' | | | Android 4.1.2 sw 6.2.A.1.100 |
| 165 | SONY Xperia S (LT26) | A' | ✓ | 0-07-0258-0.01 | Android 4.0.4 sw 6.1.A.2.45 |
| 166 | SONY Xperia SP (C5303) | A' | ✓ | 0-07-0258-0.01 | Android 4.3 sw 12.1.A.1.201 |
| 167 | SONY Xperia T (LT30p) | A' | ✓ | 0-07-0258-0.01 | Android 4.3 sw 9.2.A.1.205 |
| 168 | SONY Xperia U (ST25i) | E | | | Android 4.0.4 sw 6.1.1.B.1.10 |
| 169 | SONY Xperia Z (C6603) | | | | Android 4.2.2 sw 10.3.1.A.2.87 |
| 170 | SONY Xperia Z1 Compact (D5503) | A' | | | Android 4.4.4 sw 14.4.A.0.118 |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: info@bury.com, Internet: www.bury.com

| No | Phone | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comments |
|-----|---|-------------|-------------------|------------------------|--|
| 171 | SONY Xperia Z3 Compact (D5803) | A' | | | Android 6.0.1 sw 23.5.A.1.291 |
| 172 | Sony Ericsson Aino | F | ✓ | 0-07-0258-0.05 | R7BA084 |
| 173 | Sony Ericsson C902 | E | ✓ | 0-07-0258-0.05 | R3E004 |
| 174 | Sony Ericsson Elm | E | ✓ | 0-07-0258-0.05 | R7CA061 |
| 175 | Sony Ericsson Satio (Idou) | F | ✓ | 0-07-0258-0.05 | R1BB041 |
| 176 | Sony Ericsson Xperia Arc (LT15i) | A' | | | Android 4.0.4 sw 4.1.B.0.587 |
| 177 | Sony Ericsson Xperia Arc S (LT18i) | A' | | | Android 4.0.4 sw 4.1.B.0.587 |
| 178 | Sony Ericsson Xperia neo V (MT11i) | E | | | Android 4.0.4 sw 4.1.B.0.587 |
| 179 | Sony Ericsson Xperia ray | E | | | Android 4.0.4 sw 4.1.B.0.587 |
| 180 | Sony Ericsson Xperia X10 | A' | | | Android 2.3.3 3.0.1.G.0.75 |
| 181 | Xiaomi Mi 4 LTE | A' | | | Android 6.0.1 MMB29M MIUI 7.3 |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.