

No	Phone	Set of tips	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
1	Apple iPhone	A/E	✓	0-07-0258-0.07	3.0 (7A341)
2	Apple iPhone 3G	E	✓	0-07-0258-0.07	4.2.1 (8C148)
3	Apple iPhone 3GS	E	✓	0-07-0258-0.07	6.1.2 (10B146)
4	Apple iPhone 4	A/E	✓	0-07-0258-0.07	7.0 (11A465)
5	Apple iPhone 4S	A/E	✓	0-07-0258-0.07	7.1.1 (11D201)
6	Apple iPhone 5	E	✓	0-07-0258-0.08	7.0 (11A465)
7	Apple iPhone 5c	A'	✓	0-07-0258-0.08	7.1.1 (11D201)
8	Apple iPhone 5s	A'	✓	0-07-0258-0.08	7.1.1 (11D201)
9	Apple iPhone 6	A'	✓	0-07-0258-0.08	8.0.2 (12A405)
10	Apple iPhone 6s	A'	✓	0-07-0258-0.08	10.0.1 (14A403)
11	Apple iPhone 7	A'	✓	0-07-0258-0.02	10.0.3 (14A551)
12	Apple iPhone SE	A'	✓	0-07-0258-0.02	9.3.1 (13E238)
13	BlackBerry 8100 Pearl	F	✓	0-07-0258-0.02	V4.5.0.69 (PI2.7.0.72)
14	BlackBerry 8110 Pearl	F	✓	0-07-0258-0.02	V4.5.0.55 (PI 2.7.0.68)
15	BlackBerry 8520 Curve	F	✓	0-07-0258-0.01	V4.6.1.286 PI 4.2.0.122
16	BlackBerry 8800	A'	✓	0-07-0258-0.02	V4.5.0.174 (PI 2.7.0.105)
17	BlackBerry 9100 Pearl	E	✓	0-07-0258-0.01	V5.0.0.696 (Platform 6.2.0.57)
18	BlackBerry 9105 Pearl	E	✓	0-07-0258-0.01	V5.0.0.696 (Platform 6.2.0.57)
19	BlackBerry 9320 Curve	E	✓	0-07-0258-0.01	v7.1.0.714 (Platform 9.49.0.76)
20	BlackBerry 9360 Curve	E	✓	0-07-0258-0.01	v7.1.0.234 (Platform 9.6.0.36)
21	BlackBerry 9500 Storm	F	✓	0-07-0258-0.01	v4.7.0.41 PI 4.0.0.40
22	BlackBerry 9520 Storm2	F	✓	0-07-0258-0.01	V5.0.0.497 PI 4.2.0.220
23	BlackBerry 9700 Bold	F	✓	0-07-0258-0.01	v5.0.0.979 PI 5.1.0.178
24	BlackBerry 9780 Bold	F	✓	0-07-0258-0.01	v6.0.0.668 PI 6.6.0.236
25	BlackBerry 9800 Torch	F	✓	0-07-0258-0.01	v6.0.0.534 PI 6.6.0.200
26	BlackBerry 9860 Torch	E	✓	0-07-0258-0.01	V7.1.0.746 PL 5.1.0.546
27	BlackBerry 9900 Bold Touch	E	✓	0-07-0258-0.01	v7.0.0.585 (Platform 5.0.0.734)
28	BlackBerry Q5	A'	✓	0-07-0258-0.01	v10.2.1.537
29	BlackBerry Q10	E	✓	0-07-0258-0.01	v10.2.1.3175
30	BlackBerry Q20 Classic	A'	✓	0-07-0258-0.01	v10.3.2.2836
31	BlackBerry Z10	A'	✓	0-07-0258-0.01	v10.2.1.2102
32	BlackBerry Z30	A'	✓	0-07-0258-0.01	10.2.1.3062
33	CAT (Caterpillar) B30	F	✓	0-07-0258-0.01	
34	HTC 7 Mozart	E	✓	0-07-0258-0.01	WinPhone 7.5 Radio 5.71.09.02a_22.51.50.21U
35	HTC 7 Pro	F	✓	0-07-0258-0.01	WinPhone 7.5 Radio 5.71.09.02a_22.51.50.21U
36	HTC Desire S	E	✓	0-07-0258-0.01	Android OS 2.3.5 2.10.401.8
37	HTC Desire X	E	✓	0-07-0258-0.01	Android OS 4.1.1 sw. Nr. 2.23.118.2
38	HTC Desire Z	F	✓	0-07-0258-0.01	Android OS 2.3.3 sw.Nr. 2.42.405.5
39	HTC Desire 310	A'	✓	0-07-0258-0.01	Android OS 4.2.2 sw. Nr. 1.00.118.4
40	HTC EVO 3D X515m	A'	✓	0-07-0258-0.01	Android OS 4.0.3 sw. Nr. 3.28.401.1
41	HTC Incredible S	A'	✓	0-07-0258-0.01	Android OS 4.0.4 sw. Nr. 4.10.405.1

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468\*, Faxline: (0) 180-6-842 329\* \*(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

No	Phone	Set of tips	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
42	HTC Legend	E	✓	0-07-0258-0.01	Android OS 2.2 sw. Nr. 3.14.161.1
43	HTC Magic	F	✓	0-07-0258-0.02	1.5
44	HTC One	A'	✓	0-07-0258-0.01	Android 4.2.2 4.20.111.21
45	HTC One S	A'	✓	0-07-0258-0.01	Android 4.1.1 3.16.111.10
46	HTC One V	A'	✓	0-07-0258-0.01	Android 4.0.3 2.22.111.10
47	HTC Sensation	A'	✓	0-07-0258-0.01	Android OS 4.0.3 sw. Nr. 3.33.111.51
48	HTC Touch2	E	✓	0-07-0258-0.02	1.28.407.4 (66092)
49	HTC Touch DIAMOND 2	F	✓	0-07-0258-0.02	Radio 1.19.407.1 (51489) GER
50	HTC Touch Dual	F	✓	0-07-0258-0.02	1.31.407.09 Radio 1.58.16.27
51	HTC Touch HD	F	✓	0-07-0258-0.02	ROM: 1.14.407.3 (22273) GER
52	HTC HD mini	E	✓	0-07-0258-0.01	ROM: 1.36.479.1 (94538) WWE
53	HTC HD2	A'	✓	0-07-0258-0.01	3.14.407.2 (04666) GER
54	HTC HD7	A'	✓	0-07-0258-0.01	WinPhone 7.5 Radio sw:5.71.09.02a_22.51.50.21U
55	HTC Touch Pro2	B	✓	0-07-0258-0.02	Radio 2.07.407.1 (80303) GER
56	HTC Wildfire	E	✓	0-07-0258-0.01	Android 2.2.1 2.24.162.1
57	HTC Windows Phone 8X	A'	✓	0-07-0258-0.01	WinPhone 8 Radio sw:1.14b.32.19.06_15.42.32.19
58	HUAWEI Ascend P1 U9200	A'	✓	0-07-0258-0.01	Android 4.0.3 U9200-1V100R001C00B219
59	LG E960 Nexus 4	A'	✓	0-07-0258-0.01	Android 4.4.3 KTU84L
60	LG Nexus 5	A'	✓	0-07-0258-0.01	Android 4.4.4 KTU84P
61	LG G2 D802	A'	✓	0-07-0258-0.01	Android 4.2.2 D80210a-262-01
62	LG KM 900 Arena	E			KM900AT_V10t
63	LG P710 Optimus L7 II	A'	✓	0-07-0258-0.01	Android 4.1.2 SW LG-P71010e-EUR-XX
64	LG P760 Optimus L9	A'	✓	0-07-0258-0.01	Android 4.1.2 SW LG-P76020c-EUR-XX
65	LG P880 Optimus 4X HD	A'	✓	0-07-0258-0.01	Android 4.1.2 SW LG-P88020c-232-10
66	LG P970	A'	✓	0-07-0258-0.01	Android 2.3.4 SW LG-P970-V20h
67	LG Optimus 2X (P990 Optimus Speed)	A'	✓	0-07-0258-0.01	Android 2.2.2 SW LGE LGP990-V10e
68	Microsoft Lumia 532 Dual SIM	A'	✓	0-07-0258-0.01	WinPhone 8.1 Update SW 20c9.00076.0001
69	Microsoft Lumia 535	A'	✓	0-07-0258-0.01	WinPhone 8.1 Update SW 20c9.00076.0001
70	Microsoft Lumia 535 Dual SIM	A'	✓	0-07-0258-0.01	WinPhone 8.1 Update SW 20c9.00076.0001
71	Microsoft Lumia 550	A'	✓	0-07-0258-0.01	WinPhone 10 Mobile SW 01078.00037.16082.41022
72	Microsoft Lumia 640 Dual SIM	A'	✓	0-07-0258-0.01	WinPhone 8.1 Update 2 SW 20c9.00072.0001
73	Motorola DEFY (MB525)	F	✓	0-07-0258-0.01	34.906.1.mb525.t-Mobile.en.DE
74	Motorola DEFY+ (MB526)	F	✓	0-07-0258-0.01	Android 2.3.6 45.0.2310.MB526.Retail.en.DE
75	Motorola Milestone	F	✓	0-07-0258-0.01	Android 2.2.1
76	Motorola Motoluxe (XT615)	E	✓	0-07-0258-0.01	Android 2.3.7 NK: 1_67C_4035
77	Motorola RAZR i XT890	A'	✓	0-07-0258-0.01	Android 4.1.2 9.8.21-50_SMI-26.1358455837
78	Nokia 208.1	E			V06.01
79	Nokia 500	E			Symbian Belle 111.020.0059
80	Nokia 515	E			V 07.01
81	Nokia Asha 300	E			V 07.57
82	Nokia Asha 311	E	✓	0-07-0258-0.01	V 05.92

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468\*, Faxline: (0) 180-6-842 329\* \*(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

No	Phone	Set of tips	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
83	Nokia C2-01	E	✓	0-07-0258-0.04	V 11.40
84	Nokia C3-00	E	✓	0-07-0258-0.04	V 08.63
85	Nokia C3-01 Touch and Type	E			V 07.15
86	Nokia C5-00 5MP	E			V 073.001
87	Nokia C5-03	E			V 23.0.015
88	Nokia C6	F			V 42.0.004
89	Nokia C7-00	E			V 012.003
90	Nokia E5-00	E	✓	0-07-0258-0.04	V 071.003
91	Nokia E6-00	E	✓	0-07-0258-0.01	Symbian Belle V 111.140.0058
92	Nokia E7-00	A'			Symbian Belle V 111.030.0609
93	Nokia E72	E			081.003
94	Nokia Lumia 520	A'	✓	0-07-0258-0.01	Windows Phone 8.0 SW 2.0.242020.8
95	Nokia Lumia 610	F	✓	0-07-0258-0.01	Windows Phone 7.5 Radio sw:1.0.66.00
96	Nokia Lumia 625	A'	✓	0-07-0258-0.01	Windows Phone 8.0 Radio sw:3.2.28038.7
97	Nokia Lumia 635	A'	✓	0-07-0258-0.01	WinPhone 8.1 Update Radio sw:201c1.00401.0001
98	Nokia Lumia 820	A'	✓	0-07-0258-0.01	WinPhone 8.0 Radio sw:1.0.202158.3
99	Nokia Lumia 900	A'	✓	0-07-0258-0.01	WinPhone 7.5 Radio sw:2.1.75.25
100	Nokia Lumia 920	A'	✓	0-07-0258-0.01	WinPhone 8.0 Radio sw:1.0.202158.3
101	Nokia Lumia 925	A'	✓	0-07-0258-0.01	WinPhone 8.0 Radio sw:3.2.04033.1
102	Nokia Lumia 930	A'	✓	0-07-0258-0.01	WinPhone8.1UpdateRadio sw:201c110.00039.0001
103	Nokia Lumia 1020 (909)	A'	✓	0-07-0258-0.01	Windows Phone 8.0 Radio sw:3.2.04047.1
104	Nokia N8	F	✓	0-07-0258-0.01	Symbian Belle V 111.040.1511
105	Nokia N9	E	✓	0-07-0258-0.01	V 40.2012.21-3.342.01.1_PR_342
106	Nokia N78	F	✓	0-07-0258-0.04	V 12.26
107	Nokia N79	F	✓	0-07-0258-0.04	V 11.049
108	Nokia N97	F	✓	0-07-0258-0.01	V 22.0.110
109	Nokia N900	F	✓	0-07-0258-0.01	V21.2011.38-1
110	Nokia X6	F	✓	0-07-0258-0.01	V 40.0.002
111	Nokia X7-00	A'			Symbian Belle V 111.040.1511
112	Samsung B550H Xcover 550	E	✓	0-07-0258-0.01	B550HXXUAE6
113	Samsung B2100	F			B2100XXHL1
114	Samsung B2700	F			B2700XXIB2
115	Samsung B7330 OmniaPro	E	✓	0-07-0258-0.01	B7330XXIG2
116	Samsung B7610 OmniaPro	F	✓	0-07-0258-0.01	B7610XXIK2
117	Samsung C6625	E			C6625BUIE1
118	Samsung G386F Galaxy Core LTE	A'	✓	0-07-0258-0.01	Android 4.2.2 JDQ39.G386FXXU1ANB4
119	Samsung G388F Galaxy Xcover 3	A'	✓	0-07-0258-0.01	Android 4.4.4 KTU84P.G388FXXU1AOG4
120	Samsung G800F Galaxy S5 mini	A'	✓	0-07-0258-0.01	Android 4.4.2 KOT49H.G800FXXU1ANJ2
121	Samsung G900F Galaxy S5	A'	✓	0-07-0258-0.01	Android 4.4.2 KOT49H.G900FXXU1ANCE
122	Samsung G903F Galaxy S5 Neo	A'	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G903FXXU1BPF4
123	Samsung G920F Galaxy S6	A'	✓	0-07-0258-0.01	Android 5.0.2 LRX22G.G920FXXU1AOCV

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468\*, Faxline: (0) 180-6-842 329\* \*(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

No	Phone	Set of tips	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
124	Samsung G925F Galaxy S6 edge	A'	✓	0-07-0258-0.01	Android 5.0.2 LRX22G.G925FXXU1AOCV
125	Samsung G930F Galaxy S7	A'	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G930FXXU1APC8
126	Samsung i7500 Galaxy	E	✓	0-07-0258-0.01	I7500XXMC3
127	Samsung I8000 Omnia II	F	✓	0-07-0258-0.01	I8000XXII6
128	Samsung I8150 Galaxy W	E	✓	0-07-0258-0.01	Android 2.3.6 I8150XXLMI
129	Samsung I8160 Galaxy Ace 2	E	✓	0-07-0258-0.01	I8160XXLL2
130	Samsung I8190 Galaxy S III mini	A'	✓	0-07-0258-0.01	Android 4.1.2 I8190XXAMG4
131	Samsung i8320 Vodafone 360 H1	F	✓	0-07-0258-0.01	i8320BUIK1
132	Samsung I8700 Omnia 7	A'			Windows Phone 7.5 Radio sw:2424.13.5.1
133	Samsung I8750 Ativ S	A'	✓	0-07-0258-0.01	Windows Phone 8.0 Radio sw: 2424.13.5.1
134	Samsung i8910 Omnia HD	B	✓	0-07-0258-0.01	I8910XXJA1
135	Samsung I9000 Galaxy S	A'	✓	0-07-0258-0.01	I9000XXJW4
136	Samsung I9001 Galaxy S Plus	A'	✓	0-07-0258-0.01	Android 2.3.6 I9001XXKPO
137	Samsung I9100 Galaxy S II	A'	✓	0-07-0258-0.01	Android 4.1.2 I9100XXMS2
138	Samsung I9195 Galaxy S 4 mini	A'	✓	0-07-0258-0.01	Android 4.2.2 I9195XXUBMJ7
139	Samsung I9300 Galaxy S III	A'	✓	0-07-0258-0.01	Android 4.3 I9300XXUGNA8
140	Samsung I9305 Galaxy S III Lte	A'	✓	0-07-0258-0.01	Android 4.4.4 KTU84P.I9305XXUFOA1
141	Samsung I9505 Galaxy S4	A'	✓	0-07-0258-0.01	Android 4.2.2 JDQ39.I9505XXUAMDM
142	Samsung S5230 Avilla	E			S5230BVIE3
143	Samsung S5260 Star II	E			S5260XXKC4
144	Samsung S5570i Galaxy Mini	F	✓	0-07-0258-0.01	Android 2.3.6 sw: S5570IXXLD6
145	Samsung S5690 Galaxy Xcover	A'			Android 2.3.6 sw: S5690XXLL1
146	Samsung S6500 Galaxy mini 2	E	✓	0-07-0258-0.01	Android 2.3.6 sw: S6500XXLK2
147	Samsung S7220	E	✓	0-07-0258-0.01	S7220XXIB7
148	Samsung S7500 Galaxy Ace Plus	E	✓	0-07-0258-0.01	Android 2.3.6 S7500XXMC2
149	Samsung S7560 Galaxy Trend (Ace II X)	A'	✓	0-07-0258-0.01	Android 4.0.4 S7560XXAMEA
150	Samsung S7580 Galaxy Trend Plus	A'	✓	0-07-0258-0.01	Android 4.2.2 JDQ39.S7580XXUBOA1
151	Samsung S7710 Galaxy Xcover 2	A'			Android 4.1.2 S7710XXAMB5
152	Samsung S8000 Jet	E	✓	0-07-0258-0.01	S8000XXIF5
153	Samsung S8300V	E	✓	0-07-0258-0.01	S8300BUIK6
154	Samsung S8500 Wave	E	✓	0-07-0258-0.01	S8500XXLA1
155	Samsung S8530 Wave II	A'			S8530XXLA1
156	Samsung S8600 Wave 3	A'	✓	0-07-0258-0.01	S8600XXLD1
157	Samsung SGH-i900 OMNIA 8GB	F			i900XXIB2
158	Samsung Xcover 271 (B2710)	F	✓	0-07-0258-0.01	B2710BOJJ3
159	SONY Xperia E (C1505)	E	✓	0-07-0258-0.01	Android 4.1.1 sw 11.3.A.2.23
160	SONY Xperia J (ST26i)	A'	✓	0-07-0258-0.01	Android 4.1.2 sw 11.2.A.0.31
161	SONY Xperia M (C1905)	A'	✓	0-07-0258-0.01	Android 4.3 sw 15.4.A.1.9
162	SONY Xperia P (LT22i)	A'			Android 4.1.2 sw 6.2.A.1.100
163	SONY Xperia S (LT26)	A'	✓	0-07-0258-0.01	Android 4.0.4 sw 6.1.A.2.45
164	SONY Xperia SP (C5303)	A'	✓	0-07-0258-0.01	Android 4.3 sw 12.1.A.1.201

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32258 Löhne, Hotline: (0) 180-6-842 468\*, Faxline: (0) 180-6-842 329\* \*(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

No	Phone	Set of tips	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
165	SONY Xperia T (LT30p)	A'	✓	0-07-0258-0.01	Android 4.3 sw 9.2.A.1.205
166	SONY Xperia U (ST25i)	E			Android 4.0.4 sw 6.1.1.B.1.10
167	SONY Xperia Z (C6603)				Android 4.2.2 sw 10.3.1.A.2.87
168	SONY Xperia Z1 Compact (D5503)	A'			Android 4.4.4 sw 14.4.A.0.118
169	SONY Xperia Z3 Compact (D5803)	A'			Android 6.0.1 sw 23.5.A.1.291
170	Sony Ericsson Aino	F	✓	0-07-0258-0.05	R7BA084
171	Sony Ericsson C902	E	✓	0-07-0258-0.05	R3E004
172	Sony Ericsson Elm	E	✓	0-07-0258-0.05	R7CA061
173	Sony Ericsson Satio (Idou)	F	✓	0-07-0258-0.05	R1BB041
174	Sony Ericsson Xperia Arc (LT15i)	A'			Android 4.0.4 sw 4.1.B.0.587
175	Sony Ericsson Xperia Arc S (LT18i)	A'			Android 4.0.4 sw 4.1.B.0.587
176	Sony Ericsson Xperia neo V (MT11i)	E			Android 4.0.4 sw 4.1.B.0.587
177	Sony Ericsson Xperia ray	E			Android 4.0.4 sw 4.1.B.0.587
178	Sony Ericsson Xperia X10	A'			Android 2.3.3 3.0.1.G.0.75
179	Xiaomi Mi 4 LTE	A'			Android6.0.1 MMB29M MIUI7.3 by xiaomi.eu (6.3.24)

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468\*, Faxline: (0) 180-6-842 329\* \*(20ct/call),  
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working

*The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.*