

No	Type	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
1	Apple iPhone	✓	✓	✓		✓	1.0.2(1C28)
2	Apple iPhone 3G	✓	✓	✓		✓	4.0.1 (8A306)
3	Apple iPhone 3GS	✓	✓	✓	✓	✓	6.0 (10A403)
4	Apple iPhone 4	✓	✓	✓	✓	✓	7.0.2 (11A501)
5	Apple iPhone 4S	✓	✓	✓	✓	✓	7.0 (11A465)
6	Apple iPhone 5	✓	✓	✓	✓	✓	7.0 (11A465)
7	Apple iPhone 5c	✓	✓	✓	✓	✓	7.0.2 (11A501)
8	Apple iPhone 5s	✓	✓	✓	✓	✓	7.0.3 (11B511)
9	Apple iPhone 6	✓	✓	✓	✓	✓	8.0.2 (12A405)
10	Apple iPhone 6s	✓	✓	✓	✓	✓	10.0.1 (14A403)
11	Apple iPhone 6 Plus	✓	✓	✓	✓	✓	8.0.2 (12A405)
12	Apple iPhone 6s Plus	✓	✓	✓	✓	✓	9.1 (13B143)
13	Apple iPhone 7	✓	✓	✓	✓	✓	10.0.3 (14A551)
14	Apple iPhone 7 Plus	✓	✓	✓	✓	✓	10.0.3 (14A551)
15	Apple iPhone SE	✓	✓	✓	✓	✓	9.3.2 (13F69)
16	BlackBerry 7290	✓	✓	✓		✓	V3.8.0.105
17	BlackBerry 7100g	✓	✓	✓		✓	V4.0.0.140
18	BlackBerry 7100v	✓	✓	✓		✓	V4.0.2.16
19	BlackBerry 7100t	✓	✓	✓		✓	V3.8.0128
20	BlackBerry 8100 Pearl	✓	✓	✓	✓	✓	V4.2.0.64
21	BlackBerry 8120 Pearl	✓	✓	✓	✓	✓	V4.3.0.35
22	BlackBerry 8220 Pearl Flip	✓	✓	✓	✓	✓	V4.6.0.94
23	BlackBerry 8300 Curve	✓	✓	✓	✓	✓	OS 5.1.342
24	BlackBerry 8310 Curve	✓	✓	✓	✓	✓	V4.2.2.146
25	BlackBerry 8520 Curve	✓	✓	✓	✓	✓	V4.6.1.286 PI 4.2.0.122
26	BlackBerry 8700c	✓	✓	✓		✓	V4.1.0.170
27	BlackBerry 8700g	✓	✓	✓		✓	V4.1.0258
28	BlackBerry 8707v	✓	✓	✓		✓	V4.1.0.316
29	BlackBerry 8800	✓	✓	✓	✓	✓	V4.2.1.43
30	BlackBerry 8900 Curve	✓	✓	✓	✓	✓	V4.6.1.38
31	BlackBerry 9000 Bold	✓	✓	✓	✓	✓	V4.6.0.111 (Platform 4.0.0.129)
32	BlackBerry 9100 Pearl	✓	✓	✓	✓	✓	v5.0.0.449 (Platform 6.2.0.6)
33	BlackBerry 9105 Pearl	✓	✓	✓	✓	✓	v5.0.0.623 (Platform 6.2.0.43)
34	BlackBerry 9300 Curve 3G	✓	✓	✓	✓	✓	v5.0.0.716 (Platform 6.3.0.13)
35	BlackBerry 9360 Curve	✓	✓	✓	✓	✓	v7.0.0.353 (Platform 8.0.0.388)
36	BlackBerry 9500 Storm	✓	✓	✓	✓	✓	v4.7.0.78 PI 4.0.0.98
37	BlackBerry 9520 Storm2	✓	✓	✓	✓	✓	V5.0.0.306 PI 4.2.0.113
38	BlackBerry 9530 Storm	✓	✓	✓	✓	✓	v4.7.0.47 PI 4.0.0.53
39	BlackBerry 9630	✓	✓	✓	✓	✓	v4.7.1.20 PI 4.1.0.15
40	BlackBerry 9700 Bold	✓	✓	✓	✓	✓	v5.0.0.296 PI 5.1.0.83
41	BlackBerry 9780 Bold	✓	✓	✓	✓	✓	v6.0.0.359 PI 6.5.0.93

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

No	Type	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
42	BlackBerry 9800 Torch	✓	✓	✓	✓	✓	v6.0.0.100 PI 6.4.0.47
43	BlackBerry 9860 Torch	✓	✓	✓	✓	✓	V7.0.0.503 PL 5.0.0.694
44	BlackBerry 9900 Bold Touch	✓	✓	✓	✓	✓	v7.0.0.387 (Platform 5.0.0.572)
45	BlackBerry Z30	✓	✓	✓	✓	✓	10.2.1.3062
46	HP iPAQ 514 Voice Messenger	✓	✓	✓	✓	✓	Version 5.2.1237(Build 17742.0.2.2)
47	HP H 6340	✓	✓	✓		✓	
48	HP iPAQ HW 6510	✓	✓	✓		✓	1.06.12GER
49	HP iPAQ HW 6515	✓	✓	✓		✓	1.01.00 WWE
50	HP iPAQ HW 6915	✓	✓	✓		✓	1.01.00 GER
51	HTC 4550 Kaiser / TyTN II	✓	✓	✓	✓	✓	Rom 1.56.161.4 Radio 1.27.12.11
52	HTC Hermes	✓	✓	✓	✓	✓	Build 14847.2.0.0, Radio 0.93.03
53	HTC Desire	✓	✓	✓		✓	Android OS 2.1 update1 sw. Nr. 1.15.110.11
54	HTC Desire HD	✓	✓	✓		✓	Android OS 2.2.1 sw. Nr. 1.72.405.3
55	HTC Desire S	✓	✓	✓		✓	AndroidOS 2.3.3 1.32.161.2 CL28209 release-keys
56	HTC Desire X	✓	✓	✓		✓	Android OS 4.1.1 sw. Nr. 2.23.118.2
57	HTC Desire Z	✓	✓	✓		✓	Android OS 2.2.1 sw. Nr. 1.72.405.2
58	HTC EVO 3D X515m	✓	✓	✓		✓	Android OS 2.3.4 sw. Nr. 1.20.401.2
59	HTC Incredible S	✓	✓	✓		✓	Android OS 2.2.1 sw. Nr. 1.36.405.1
60	HTC Magic	✓	✓	✓		✓	1.5
61	HTC MTeor	✓	✓	✓		✓	Build 14927.2.2.0, Radio 0.72.01, RIL 2.002
62	HTC T-Mobile G1	✓	✓	✓		✓	FW: 1.1
63	HTC One	✓	✓	✓		✓	Android 4.2.2 2.24.111.5
64	HTC One S	✓	✓	✓		✓	Android 4.1.1 3.16.111.5
65	HTC One V	✓	✓	✓		✓	Android 4.0.3 sw. Nr. 2.22.111.1
66	HTC One X	✓	✓	✓		✓	Android 4.0.4 sw. Nr. 2.17.401.2
67	HTC Sensation	✓	✓	✓		✓	Android OS 2.3.4 sw. Nr. 1.45.111.2
68	HTC Touch	✓	✓	✓	✓	✓	1.11.405.18 WWE, Radio 02.93.90
69	HTC Touch2	✓	✓	✓		✓	1.28.407.4 (66092)
70	HTC Touch 3G	✓	✓	✓	✓	✓	2.32.407.2 (44800)
71	HTC Touch Cruise	✓	✓	✓	✓	✓	3.13.407.0 GER
72	HTC Touch Diamond	✓	✓	✓	✓	✓	Build 19588.1.1.4, Radio 0.93.25.NS16
73	HTC Touch DIAMOND 2	✓	✓	✓		✓	Radio 1.19.407.1 (51489) GER
74	HTC Touch Dual	✓	✓	✓	✓	✓	1.31.407.09 Radio 1.58.16.27
75	HTC Touch HD	✓	✓	✓	✓	✓	ROM: 1.14.407.3 (22273) GER
76	HTC HD mini	✓	✓	✓		✓	ROM: 1.07.407.1 (85429) GER
77	HTC HD2	✓	✓	✓		✓	1.43.111.2 (70315) GER
78	HTC Touch Pro	✓	✓	✓	✓	✓	1.60.161.1 WWE
79	HTC Touch Pro2	✓	✓	✓		✓	Radio 1.19.407.1 (51489) GER
80	HTC TyTN	✓	✓	✓	✓	✓	Build 14954.2.3.0 Radio 0.96.00.00
81	HTC Wildfire	✓	✓	✓		✓	Android 2.2.1 2.24.162.1
82	HTC Windows Phone 8X	✓	✓	✓	✓	✓	WinPhone 8 sw:1.14b.32.19.06_15.42.32.19

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

No	Type	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
83	HTC MDA Compact	✓	✓	✓		✓	
84	HTC MDA Compact II	✓	✓	✓	✓	✓	
85	HTC MDA Compact III	✓	✓	✓	✓	✓	OS 5.1.342
86	HTC MDA II	✓					4.20.0
87	HTC MDA III	✓	✓	✓		✓	
88	HTC MDA IV	✓	✓	✓		✓	0.90.00
89	HTC SDA I	✓	✓	✓	✓	✓	V4.21.1088
90	HTC SDA Music	✓	✓	✓	✓	✓	
91	HTC SDA II	✓	✓	✓	✓	✓	
92	HTC SPV C-500	✓	✓	✓	✓	✓	1337.0.32.0.03.18
93	HTC SPV C-600	✓	✓	✓	✓	✓	4.0.13.10_00.17.00
94	HTC SPV C-700	✓	✓	✓	✓	✓	1.06.00.00
95	HTC SPV M-500	✓	✓	✓		✓	1.05.10
96	HTC SPV M-2000	✓	✓	✓		✓	
97	HTC SPV M-5000	✓	✓	✓		✓	
98	HTC VPA Compact	✓	✓	✓		✓	1.05.00
99	HTC VPA III	✓	✓	✓		✓	
100	HTC XDA II	✓					1.10.00
101	HTC XDA II i	✓					
102	HTC XDA II s	✓	✓	✓		✓	
103	HTC XDA III	✓	✓	✓		✓	1.10.00
104	HTC XDA Mini S	✓	✓	✓	✓	✓	01.09.10
105	HTC XDA Orbit 2	✓	✓	✓	✓	✓	1.25.206.3 WWE
106	HTC Qtek 9090	✓	✓	✓		✓	1.06.00
107	HTC Qtek 9100	✓	✓	✓	✓	✓	1.6.7.1
108	HTC Qtek 2020	✓					1.14.00
109	HTC Qtek 8310	✓	✓	✓		✓	
110	HTC Qtek S100	✓	✓	✓		✓	
111	HTC X-Phone II	✓	✓	✓	✓	✓	2.037.21
112	HTC I-mate SP3	✓	✓	✓	✓	✓	V4.21.1088
113	HTC I-mate SP3i	✓	✓	✓	✓	✓	
114	HTC I-mate JAM	✓	✓	✓		✓	V 1.03.00
115	HUAWEI Ascend P1 U9200	✓	✓	✓	✓	✓	Android 4.0.3 U9200-1V100R001C00B219
116	LG BL20 New Chocolate	✓	✓			✓	BL20 V10d
117	LG BL40 New Chocolate	✓	✓	✓		✓	BL40-MSM76XX-V10a-SEP-21-2009-XX
118	LG GC900 Viewty Smart	✓	✓	✓		✓	GC900AT_V10b
119	LG GD900 Crystal	✓	✓	✓		✓	GD900AT_V10c
120	LG GT500	✓	✓			✓	GT500-V10i
121	LG KC550	✓	✓	✓		✓	KC55AT-00-V10b-234-10-TSC-MAY-28-2008
122	LG KF 750 Secret	✓	✓	✓		✓	KF750-V10a-24042008
123	LG KG 810	✓	✓	✓		✓	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

No	Type	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
124	LG KG 800	✓	✓	✓		✓	
125	LG KM 900 Arena	✓	✓	✓		✓	KM900AT_V10t
126	LG KP500 Cookie	✓	✓	✓		✓	KP500AT_V10d
127	LG KU 580	✓	✓	✓		✓	KU580-V10b-NOV-22-2007
128	LG P710 Optimus L7 II	✓	✓	✓		✓	Android 4.1.2 SW LG-P71010e-EUR-XX
129	LG P760 Optimus L9	✓	✓	✓		✓	Android 4.1.2 SW LG-P76020c-EUR-XX
130	LG P880 Optimus 4X HD	✓	✓	✓		✓	Android 4.1.2 SW LG-P88020a-232-10
131	LG P970	✓	✓	✓		✓	Android 2.2.2 SW LG-P970-V10b
132	LG Optimus 2X (P990 Optimus Speed)	✓	✓	✓		✓	Android 2.2.2 SW LGE LGP990-V10e
133	Microsoft Lumia 532 Dual SIM	✓	✓	✓		✓	WinPhone 8.1 Update SW 20c9.00076.0001
134	Microsoft Lumia 535	✓	✓	✓		✓	WinPhone 8.1 Update SW 20c9.00076.0001
135	Microsoft Lumia 535 Dual SIM	✓	✓	✓		✓	WinPhone 8.1 Update SW 20c9.00076.0001
136	Microsoft Lumia 550	✓	✓	✓		✓	WinPhone 10 Mobile SW 01078.00037.16082.41022
137	Microsoft Lumia 640 Dual SIM	✓	✓	✓		✓	WinPhone 8.1 Update 2 SW 20c9.00072.0001
138	Microsoft Lumia 640 XL	✓	✓	✓		✓	WinPhone 8.1 Update 2 SW 401c3.00009.0001
139	Microsoft Lumia 650	✓	✓	✓		✓	WinPhone 10 Mobile SW 01078.00037.16082.41010
140	Microsoft Lumia 950	✓	✓	✓		✓	WinPhone 10 Mobile SW 01078.00038.16025.39025
141	Microsoft Lumia 950 XL	✓	✓	✓		✓	WinPhone 10 Mobile SW 01078.00038.16082.36021
142	Motorola A835	✓	✓	✓	✓	✓	TALINT_0_7232.07.02P
143	Motorola C390	✓	✓	✓	✓	✓	R368_G_0B_AQ0_05I
144	Motorola ROKR E1	✓	✓	✓	✓	✓	R373_G_0E.30.42R
145	Motorola E550	✓	✓	✓	✓	✓	
146	Motorola E770v	✓	✓	✓	✓	✓	R25221_U_85.83.E1P
147	Motorola E1070	✓	✓	✓	✓	✓	R252211LD_U_85.97.C3P
148	Motorola KRZR K1	✓	✓	✓	✓	✓	R4527_G_08.22.07R
149	Motorola KRZR K1m	✓	✓	✓	✓	✓	24.1_00.25.0C
150	Motorola RIZR Z3	✓	✓	✓	✓	✓	R452B_G_08.01.02R
151	Motorola RIZR Z8	✓	✓	✓		✓	ESPOO_U_46.03.E3G_0000053e
152	Motorola L2 (v270)	✓	✓	✓	✓	✓	R3511_G_0A..50.1BR
153	Motorola L6 (v280)	✓	✓	✓	✓	✓	R3511_G_0A..50.22BR
154	Motorola L7	✓	✓	✓	✓	✓	R4513_G_08.B7.54R_RB
155	Motorola Milestone 2	✓	✓	✓	✓	✓	Android 2.2
156	Motorola Motoluxe (XT615)	✓	✓	✓	✓	✓	Android 2.3.7 NK: 1_67C_4035
157	Motorola MPx220	✓	✓	✓	✓	✓	4.21.1088
158	Motorola RAZR i XT890	✓	✓	✓		✓	Android 4.1.2 9.8.21-50_SMI-26.1358455837
159	Motorola RAZR V3	✓	✓	✓	✓	✓	R374_G_0E40.3CR
160	Motorola RAZR V3i	✓	✓	✓	✓	✓	R479_G_08.B4.85R
161	Motorola RAZR V3x	✓	✓	✓	✓	✓	R252211LD_U_85.92.70R
162	Motorola RAZR V3xx	✓	✓	✓	✓	✓	R26111LD_U_96.67.32R
163	Motorola RAZR XT910	✓	✓	✓	✓	✓	Android 2.3.6 6.5.1-167_SPU-15-M2
164	Motorola RAZR2 V8	✓	✓	✓	✓	✓	R601_G_80.42.39R

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

No	Type	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
165	Motorola RAZR2 V9	✓	✓	✓	✓	✓	R263313_U_A0.01.10R31
166	Motorola U6	✓	✓	✓	✓	✓	R478_G_08.83.76R_A
167	Motorola W510 (PEMBA)	✓	✓	✓	✓	✓	R452G_G_08..00.02I
168	Motorola V500	✓	✓	✓	✓	✓	TRIPLETS_G_0B09.10R_VR
169	Motorola V525	✓	✓	✓	✓	✓	TRIPLETS_G0B09.1DR_VR
170	Motorola V550	✓	✓	✓	✓	✓	R376_G_0E.65.26R
171	Motorola V551	✓	✓	✓	✓	✓	R47_G08_17.OFR01
172	Motorola V600	✓	✓	✓	✓	✓	TRIPLETS_G_0B09.38R
173	Motorola V620	✓	✓	✓	✓	✓	R376_G_0E.65.25R
174	Motorola V635	✓	✓	✓	✓	✓	R474_G_08.48.24R_A
175	Motorola V80	✓	✓	✓	✓	✓	R37_G_0E.03.26R
176	Nokia 113	✓	✓	✓		✓	V03.32
177	Nokia 208.1	✓	✓	✓		✓	V06.01
178	Nokia 500	✓	✓	✓	✓	✓	Symbian Belle 111.020.0059
179	Nokia 515	✓	✓	✓		✓	V 07.01
180	Nokia 2323 classic	✓	✓	✓		✓	V 06.46
181	Nokia 2330 classic	✓	✓	✓		✓	V 06.46
182	Nokia 2700 classic	✓	✓	✓		✓	V 07.15
183	Nokia 2730 classic	✓	✓	✓		✓	V 10.40
184	Nokia 3109c	✓	✓	✓	✓	✓	V07.21
185	Nokia 3110c	✓	✓	✓	✓	✓	V04.91
186	Nokia 3120 classic	✓	✓	✓		✓	V 10.00
187	Nokia 3230	✓	✓	✓	✓	✓	V3.0505.2
188	Nokia 3250	✓	✓	✓	✓	✓	V03.24
189	Nokia 3650	✓	✓	✓	✓	✓	V4.13
190	Nokia 3710 fold	✓	✓	✓		✓	V03.80
191	Nokia 3720 classic	✓	✓	✓		✓	V09.10
192	Nokia 5200	✓	✓	✓	✓	✓	V03.92
193	Nokia 5230	✓	✓	✓	✓	✓	V 12.0.089
194	Nokia 5300	✓	✓	✓	✓	✓	V05.00
195	Nokia 5310 XpressMusic	✓	✓	✓		✓	V09.42
196	Nokia 5500	✓	✓	✓	✓	✓	V 03.18
197	Nokia 5530 XpressMusic	✓	✓	✓	✓	✓	V 11.0.054
198	Nokia 5630 XpressMusic	✓	✓	✓	✓	✓	V012.008
199	Nokia 5700	✓	✓	✓	✓	✓	V 03.83.1
200	Nokia 5730 XpressMusic	✓	✓	✓	✓	✓	100.48.122
201	Nokia 5800 XpressMusic	✓	✓	✓	✓	✓	V 20.0.012
202	Nokia 6021	✓	✓	✓	✓	✓	V03.87
203	Nokia 6103	✓	✓	✓	✓	✓	V04.90
204	Nokia 6110 Navigator	✓	✓	✓	✓	✓	V03.58
205	Nokia 6120c	✓	✓	✓	✓	✓	V03.83

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

No	Type	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
206	Nokia 6124c	✓	✓	✓	✓	✓	V04.34
207	Nokia 6125	✓	✓	✓	✓	✓	V03.71
208	Nokia 6131	✓	✓	✓	✓	✓	V03.70
209	Nokia 6151	✓	✓	✓	✓	✓	V03.56
210	Nokia 6210 Navigator	✓	✓	✓	✓	✓	V03.08
211	Nokia 6220 Classic	✓	✓	✓	✓	✓	V03.23
212	Nokia 6230	✓	✓	✓	✓	✓	V5.40
213	Nokia 6230i	✓	✓	✓	✓	✓	V3.30
214	Nokia 6234	✓	✓	✓	✓	✓	V3.50
215	Nokia 6270	✓	✓	✓	✓	✓	V03.66
216	Nokia 6280	✓	✓	✓	✓	✓	V4.25
217	Nokia 6288	✓	✓	✓	✓	✓	V05.92
218	Nokia 6300	✓	✓	✓	✓	✓	V 04.70
219	Nokia 6300i	✓	✓	✓		✓	V03.41
220	Nokia 6301	✓	✓	✓		✓	V 04.61
221	Nokia 6303 classic	✓	✓	✓		✓	V 08.90
222	Nokia 6303i classic	✓	✓	✓		✓	V 07.10
223	Nokia 6310	✓	✓	✓	✓	✓	V5.10
224	Nokia 6310i	✓	✓	✓	✓	✓	V5.51
225	Nokia 6500c	✓	✓	✓		✓	V 03.21
226	Nokia 6600	✓	✓	✓	✓	✓	V3.42.1
227	Nokia 6600i Slide	✓	✓	✓		✓	V 36.16
228	Nokia 6630	✓	✓	✓	✓	✓	V2.39.152
229	Nokia 6650 fold	✓	✓	✓	✓	✓	V 03.31
230	Nokia 6680	✓	✓	✓	✓	✓	V3.04.11
231	Nokia 6681	✓	✓	✓	✓	✓	V3.10.6
232	Nokia 6700 classic	✓	✓	✓		✓	V 07.60
233	Nokia 6710 Navigator	✓	✓	✓	✓	✓	021.013
234	Nokia 6720 classic	✓	✓	✓	✓	✓	012.008
235	Nokia 6760 slide	✓	✓	✓	✓	✓	V 03.38
236	Nokia 6810	✓	✓	✓	✓	✓	V03.30
237	Nokia 6820	✓	✓	✓	✓	✓	V04.25
238	Nokia 6820a	✓	✓	✓	✓	✓	
239	Nokia 6822	✓	✓	✓	✓	✓	V4.48
240	Nokia 7370	✓	✓	✓	✓	✓	V 04.13
241	Nokia 7380	✓	✓	✓	✓	✓	V03.80
242	Nokia 7710	✓	✓	✓	✓	✓	V03.04.2
243	Nokia 7900 Prism	✓	✓	✓		✓	V03.40
244	Nokia 8600 Luna	✓	✓	✓	✓	✓	V03.52
245	Nokia 8800	✓	✓	✓	✓	✓	V03.60
246	Nokia 8801	✓	✓	✓	✓	✓	V03.94

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

No	Type	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
247	Nokia 8910	✓	✓	✓	✓	✓	V04.02
248	Nokia 9300	✓	✓	✓		✓	V4.53
249	Nokia 9300i	✓	✓	✓		✓	V 05.50(00)
250	Nokia 9500	✓	✓	✓		✓	V4.44
251	Nokia Asha 300	✓	✓	✓		✓	V06.97
252	Nokia Asha 311	✓	✓	✓		✓	V05.92
253	Nokia C1-01	✓	✓	✓		✓	V 04.40
254	Nokia C1-02	✓	✓	✓		✓	V 04.40
255	Nokia C2-01	✓	✓	✓		✓	V 11.00
256	Nokia C3-00	✓	✓	✓		✓	V 04.60
257	Nokia C3-01 Touch and Type	✓	✓	✓		✓	V 05.65
258	Nokia C5	✓	✓	✓	✓	✓	V 031.022
259	Nokia C5-00 5MP	✓	✓	✓	✓	✓	V 073.001
260	Nokia C5-03	✓	✓	✓	✓	✓	V 21.0.003
261	Nokia C6	✓	✓	✓	✓	✓	V 11.0.029
262	Nokia C7-00	✓	✓	✓	✓	✓	V 012.003
263	Nokia E5-00	✓	✓	✓	✓	✓	V 042.010
264	Nokia E6-00	✓	✓	✓	✓	✓	V 021.014
265	Nokia E7-00	✓	✓	✓	✓	✓	V 013.016
266	Nokia E50	✓	✓	✓	✓	✓	V06.27.1.0
267	Nokia E51	✓	✓	✓	✓	✓	100.34.20
268	Nokia E52	✓	✓	✓	✓	✓	033.002
269	Nokia E55	✓	✓	✓	✓	✓	022.009
270	Nokia E60	✓	✓	✓	✓	✓	V.0610.02.15
271	Nokia E61	✓	✓	✓	✓	✓	V. 3.0633.09.04
272	Nokia E61i	✓	✓	✓	✓	✓	V 1.0633.22.05
273	Nokia E65	✓	✓	✓	✓	✓	V 1.0633.18.01
274	Nokia E66	✓	✓	✓	✓	✓	V 007.45.2
275	Nokia E70	✓	✓	✓	✓	✓	V1.0610.05.06
276	Nokia E71	✓	✓	✓	✓	✓	V 007.49.4
277	Nokia E72	✓	✓	✓	✓	✓	021.024
278	Nokia E75	✓	✓	✓	✓	✓	110.48.125
279	Nokia E90	✓	✓	✓	✓	✓	V07.24.0.3.0P
280	Nokia Lumia 520	✓	✓	✓	✓	✓	Windows Phone 8.0 SW 2.0.242020.8
281	Nokia Lumia 625	✓	✓	✓	✓	✓	Windows Phone 8.0 Radio sw:3.2.28060.7
281	Nokia Lumia 635	✓	✓	✓		✓	WinPhone 8.1 Update Radio sw:201c1.00401.0001
282	Nokia Lumia 820	✓	✓	✓	✓	✓	Windows Phone 8.0 Radio sw:1.0.202075.3
283	Nokia Lumia 920	✓	✓	✓	✓	✓	Windows Phone 8.0 Radio sw:1.0.202075.3
284	Nokia Lumia 925	✓	✓	✓	✓	✓	Windows Phone 8.0 Radio sw:3.2.04033.1
285	Nokia Lumia 930	✓	✓	✓	✓	✓	WinPhone 8.1 Update Radio sw:201c110.00039.0001
286	Nokia Lumia 1020 (909)	✓	✓	✓	✓	✓	Windows Phone 8.0 Radio sw:3.2.04047.1

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

No	Type	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
287	Nokia Lumia 1520	✓	✓	✓		✓	WinPhone 8.1 Update SW 02540.00019.15235.40004
288	Nokia N8	✓	✓	✓	✓	✓	V 011.012
289	Nokia N9	✓	✓	✓		✓	V 20.2011.40-4.341.01.1_PR_341
290	Nokia N70	✓	✓	✓	✓	✓	V2.0536.02
291	Nokia N71	✓	✓	✓	✓	✓	V 2.0613.1.12.1
292	Nokia N73	✓	✓	✓	✓	✓	V2.0628.0.0.1
293	Nokia N76	✓	✓	✓	✓	✓	V30.0.015
294	Nokia N78	✓	✓	✓	✓	✓	V10136
295	Nokia N79	✓	✓	✓	✓	✓	V 11.049
296	Nokia N80	✓	✓	✓	✓	✓	V 3.0617.0.6
297	Nokia N82	✓	✓	✓	✓	✓	V 10.0.046
298	Nokia N85	✓	✓	✓	✓	✓	V 11.047
299	Nokia N86 8MP	✓	✓	✓	✓	✓	11.043
300	Nokia N90	✓	✓	✓	✓	✓	V5.0607.7.3
301	Nokia N91	✓	✓	✓	✓	✓	V1.11.003
302	Nokia N93	✓	✓	✓	✓	✓	V10.0.025
303	Nokia N93i	✓	✓	✓	✓	✓	V11.0.009
304	Nokia N95	✓	✓	✓	✓	✓	V11.0.026
305	Nokia N95 3G	✓	✓	✓	✓	✓	V14.0.01
306	Nokia N95 (8GB)	✓	✓	✓	✓	✓	V20.0.016
307	Nokia N96	✓	✓	✓	✓	✓	10.024
308	Nokia N97	✓	✓	✓	✓	✓	V 20.0.019
309	Nokia N97 mini	✓	✓	✓	✓	✓	v 10.0.020
310	Nokia N900	✓	✓	✓		✓	V 3.2010.02-8
311	Nokia N-GAGE	✓	✓	✓	✓	✓	V3.30
312	Nokia X3	✓	✓	✓		✓	V 03.60
313	Nokia X6	✓	✓	✓	✓	✓	V 20.0.005
314	Nokia X7-00	✓	✓	✓	✓	✓	V 021.013
315	Palm Centro	✓	✓	✓		✓	Centro-1.02-ROW
316	Palm Pre	✓	✓	✓		✓	V1.0
317	Palm Treo 500V	✓	✓	✓		✓	Radio Ver. V 3.1.6.P4_2007-08-01
318	Palm Treo 650	✓					
319	Palm Treo 680	✓	✓	✓		✓	
320	Palm Treo 750	✓	✓	✓		✓	
321	Panasonic X70	✓	✓	✓		✓	
322	Sagem TIGR 350G	✓	✓	✓		✓	
323	Samsung Ace S5830	✓	✓	✓		✓	Android 2.3.3 sw S5830XWKP5
324	Samsung B550H Xcover 550	✓	✓	✓		✓	B550HXXUAOE6
325	Samsung B2100	✓	✓	✓		✓	B2100XXHL1
326	Samsung B2700	✓	✓	✓		✓	B2700XXIB2
327	Samsung B7330 OmniaPro	✓	✓	✓		✓	B7330XXIG2

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

No	Type	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
328	Samsung B7610 OmniaPro	✓	✓	✓		✓	B7610XXIK2
329	Samsung C6625	✓	✓	✓		✓	C6625BUIE1
330	Samsung i7500 Galaxy	✓	✓	✓		✓	I7500XXII5
331	Samsung I8000 Omnia II	✓	✓	✓		✓	I8000XXII6
332	Samsung I8150 Galaxy W	✓	✓	✓		✓	I8150XXLMB
333	Samsung I8160 Galaxy Ace 2	✓	✓	✓	✓	✓	I8160XXLI2
334	Samsung I8190 Galaxy S III mini	✓	✓	✓		✓	Android 4.1.2 I8190XXAMG4
335	Samsung i8910 Omnia HD	✓	✓	✓		✓	I8910XXIE7
336	Samsung I9001 Galaxy S Plus	✓	✓	✓		✓	Android 2.3.3 I9001XXKG3
337	Samsung I9100 Galaxy S II	✓	✓	✓		✓	I9100XWKE1
338	Samsung N7000 Galaxy Note	✓	✓	✓		✓	Android 4.0.3 sw: N7000XXLPT
339	Samsung N7100 Galaxy Note II	✓	✓	✓		✓	Android 4.1.1 sw: N7100XXALJ2
340	Samsung S3650 Corby	✓	✓	✓		✓	S3650XXII3
341	Samsung S5230 Avilla	✓	✓	✓		✓	S5230BVIE3
342	Samsung S5260 Star II	✓	✓	✓		✓	S5260XXKC4
343	Samsung S5360 Galaxy Y	✓	✓	✓		✓	Android 2.3.6 sw: S5360XXLE1
344	Samsung S5570i Galaxy Mini	✓	✓	✓		✓	Android 2.3.6 sw: S5570IXXLD6
345	Samsung S6500 Galaxy mini 2	✓	✓	✓		✓	Android 2.3.6 sw: S6500XXLD2
346	Samsung S7220	✓	✓	✓		✓	S7220XXIA2
347	Samsung S7500 Galaxy Ace Plus	✓	✓	✓		✓	S7500XXLH1
348	Samsung S7560 Galaxy Trend (Ace II X)	✓	✓	✓		✓	Android 4.0.4 S7560XXAMF1
349	Samsung S7710 Galaxy Xcover 2	✓	✓	✓		✓	Android 4.1.2 sw: S7710XXAMB5
350	Samsung S8000 Jet	✓	✓	✓		✓	S8000XXIF5
351	Samsung S8300V	✓	✓	✓		✓	S8300BUIE6
352	Samsung S8500 Wave	✓	✓	✓		✓	S8500XXJI4
353	Samsung S8530 Wave II	✓	✓	✓		✓	S8530XXJKA
354	Samsung S8600 Wave 3	✓	✓	✓		✓	S8600XXLD1
355	Samsung SCH-A930	✓	✓	✓		✓	
356	Samsung SGH-D307	✓	✓	✓		✓	
357	Samsung SGH-D357	✓	✓	✓	✓	✓	REV 1.4
358	Samsung SGH-D500	✓	✓	✓		✓	
359	Samsung SGH-D520	✓	✓	✓		✓	1.0c
360	Samsung SGH-D600	✓	✓	✓		✓	
361	Samsung SGH-D840	✓	✓	✓		✓	Rev 1.0a
362	Samsung SGH-D880	✓	✓	✓		✓	D880XAHB3
363	Samsung SGH-E250	✓	✓	✓		✓	LE250.09
364	Samsung SGH-E720	✓	✓	✓		✓	
365	Samsung SGH-F110	✓	✓	✓		✓	F110XAHB2
366	Samsung SGH-F300	✓	✓	✓		✓	Rev 1.1
367	Samsung SGH-F480	✓	✓	✓		✓	F480BOHE3
368	Samsung SGH-F700v	✓	✓	✓		✓	F700AMGJ8

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

No	Type	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
369	Samsung SGH-G600	✓	✓	✓		✓	
370	Samsung SGH-G800	✓	✓	✓		✓	G80LAKHB1
371	Samsung SGH-P900	✓	✓	✓		✓	Rev 1.1
372	Samsung SGH-U200	✓	✓	✓		✓	U200XXHD1
373	Samsung SGH-U600	✓	✓	✓		✓	Rev 0.2
374	Samsung SGH-U700v	✓	✓	✓		✓	U700V.002
375	Samsung SGH-U800	✓	✓	✓		✓	U800BRHL1
376	Samsung SGH-U900	✓	✓	✓		✓	U900BOHD2
377	Samsung SGH-i200	✓	✓	✓		✓	i200ACHH1
378	Samsung SGH-i550	✓	✓	✓		✓	i550AKHE2
379	Samsung SGH-i600	✓	✓	✓	✓	✓	FTA SW VERSION: i600.005
380	Samsung SGH-i900 OMNIA 8GB	✓	✓	✓		✓	i900XXIB2
381	Samsung SGH-i900 OMNIA 16GB	✓	✓	✓		✓	i900BOHH2
382	Samsung SGH-X820	✓	✓	✓		✓	0.3b
383	Samsung Xcover 271 (B2710)	✓	✓	✓		✓	B2710BOJJ3
384	SHARP GX15	✓	✓	✓		✓	
385	SHARP GX25	✓	✓	✓		✓	
386	SHARP GX30i	✓	✓	✓		✓	
387	Siemens CX75	✓	✓	✓		✓	SW:05
388	Siemens EL71	✓	✓	✓		✓	SW:31
389	Siemens M75	✓	✓	✓		✓	SW:05
390	Siemens S55	✓	✓	✓	✓	✓	SW:91
391	Siemens S65	✓	✓	✓		✓	SW:25
392	Siemens SK65	✓	✓	✓		✓	SW:42
393	Siemens S65v	✓	✓	✓		✓	SW:25
394	Siemens SP65	✓	✓	✓		✓	
395	Siemens SX1	✓	✓	✓	✓	✓	SW:14
396	Siemens SXG75	✓	✓	✓		✓	W6250C-MMTO-1.4.33_3
397	SONY Xperia E (C1505)	✓	✓	✓		✓	Android 4.1.1 sw 11.3.A.2.23
398	SONY Xperia J (ST26i)	✓	✓	✓		✓	Android 4.1.2 sw 11.2.A.0.31
399	SONY Xperia P (LT22i)	✓	✓	✓		✓	Android 4.0.4 sw 6.1.1.B.1.54
400	SONY Xperia S (LT26)	✓	✓	✓		✓	Android 4.0.4 sw 6.1.A.0.452
401	SONY Xperia SP (C5303)	✓	✓	✓		✓	Android 4.1.2 sw 12.0.A.1.257
402	SONY Xperia T (LT30p)	✓	✓	✓		✓	Android 4.1.2 sw 9.1.A.0.489
403	SONY Xperia Tipo (ST21i)	✓	✓	✓		✓	Android 4.0.4 sw 11.0.A.4.22
404	SONY Xperia U (ST25i)	✓	✓	✓		✓	Android 4.0.4 sw 6.1.1.B.1.10
405	SONY Xperia Z (C6603)	✓	✓	✓		✓	Android 4.2.2 sw 10.3.1.A.2.67
406	Sony Ericsson Aino	✓	✓	✓		✓	R1BA049
407	Sony Ericsson C510	✓	✓	✓		✓	R1FA035
408	Sony Ericsson C702	✓	✓	✓		✓	R3AA054
409	Sony Ericsson C902	✓	✓	✓	✓	✓	R3BA035

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

No	Type	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
410	Sony Ericsson C903	✓	✓	✓		✓	R1FA035
411	Sony Ericsson C905	✓	✓	✓	✓	✓	R1DA034
412	Sony Ericsson D750i	✓	✓	✓	✓	✓	R1N035
413	Sony Ericsson Elm	✓	✓	✓		✓	R7BA076
414	Sony Ericsson G502	✓	✓	✓	✓	✓	R1EA033
415	Sony Ericsson G900	✓	✓	✓	✓	✓	1.25.206.3 WWE
416	Sony Ericsson J105i Naite	✓	✓	✓		✓	R1HA035
417	Sony Ericsson K510i	✓	✓	✓		✓	R4CH003
418	Sony Ericsson K530i	✓	✓	✓	✓	✓	R6BC002
419	Sony Ericsson K550i	✓	✓	✓	✓	✓	R1JD001
420	Sony Ericsson K600i	✓	✓	✓	✓	✓	R2AC001
421	Sony Ericsson K610i	✓	✓	✓	✓	✓	
422	Sony Ericsson K700i	✓	✓	✓		✓	R2AY004
423	Sony Ericsson K750i	✓	✓	✓	✓	✓	R1A0044
424	Sony Ericsson K770i	✓	✓	✓	✓	✓	R8BA024
425	Sony Ericsson K800i	✓	✓	✓	✓	✓	
426	Sony Ericsson K810i	✓	✓	✓	✓	✓	R1JF001
427	Sony Ericsson M600i	✓	✓	✓			R1B01
428	Sony Ericsson P1i	✓	✓	✓	✓	✓	R9G007
429	Sony Ericsson P800i					✓	R4A005
430	Sony Ericsson P910i	✓	✓	✓	✓	✓	R4A006
431	Sony Ericsson P990i	✓	✓	✓	✓		CXC162037 R7A001
432	Sony Ericsson R520m	✓					R2K
433	Sony Ericsson Satio (Idou)	✓	✓	✓		✓	R1BB041
434	Sony Ericsson S312	✓	✓	✓		✓	R1DB002
435	Sony Ericsson S500i	✓	✓	✓	✓	✓	R6BC002
436	Sony Ericsson S700i	✓	✓	✓		✓	R3C002
437	Sony Ericsson T68i	✓	✓	✓	✓	✓	R5D007
438	Sony Ericsson T39m	✓					R2G
439	Sony Ericsson T610	✓	✓	✓	✓	✓	R3C002
440	Sony Ericsson T616	✓	✓	✓	✓	✓	R1A0044
441	Sony Ericsson T630	✓	✓	✓	✓	✓	R7A011
442	Sony Ericsson T650i	✓	✓	✓	✓	✓	R7AA024
443	Sony Ericsson W205	✓	✓	✓		✓	R1CA001
444	Sony Ericsson W550i	✓	✓	✓	✓	✓	R4BA041
445	Sony Ericsson W580i	✓	✓	✓	✓	✓	R8BA024
446	Sony Ericsson W595i	✓	✓	✓		✓	R3EA031
447	Sony Ericsson W600i	✓	✓	✓	✓	✓	R7B046
448	Sony Ericsson W610i	✓	✓	✓	✓	✓	R1JD001
449	Sony Ericsson W660i	✓	✓	✓	✓	✓	R6BC002
450	Sony Ericsson W700i	✓	✓	✓	✓	✓	R1CA021

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

No	Type	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
451	Sony Ericsson W705	✓	✓	✓		✓	R1DA034
452	Sony Ericsson W715	✓	✓	✓		✓	R1GA026
453	Sony Ericsson W800i	✓	✓	✓	✓	✓	R1L002
454	Sony Ericsson W810i	✓	✓	✓	✓	✓	R4DB005
455	Sony Ericsson W850i	✓	✓	✓	✓	✓	R1ED001
456	Sony Ericsson W880i	✓	✓	✓	✓	✓	R1JC002
457	Sony Ericsson W900i	✓	✓	✓	✓	✓	R5BC004
458	Sony Ericsson W910i	✓	✓	✓		✓	R1CA029
459	Sony Ericsson W950i	✓	✓	✓	✓		R9C001
460	Sony Ericsson W960i	✓	✓	✓	✓	✓	R6G04
461	Sony Ericsson W995	✓	✓	✓	✓	✓	R1EA032
462	Sony Ericsson Vivaz	✓	✓	✓		✓	1224-4699_R2AK006
463	Sony Ericsson V630i	✓	✓	✓	✓	✓	
464	Sony Ericsson V800	✓	✓	✓	✓	✓	R1J002
465	Sony Ericsson Xperia Arc (LT15i)	✓	✓	✓	✓	✓	Android 2.3.3 sw 3.0.1.A.0.145
466	Sony Ericsson Xperia ray	✓	✓	✓	✓	✓	Android 2.3.4 sw 4.0.2.A.0.69
467	Sony Ericsson Xperia X1	✓	✓	✓		✓	1.00.161.2
468	Sony Ericsson Xperia X2	✓	✓	✓		✓	R1AA035
469	Sony Ericsson Xperia X8	✓	✓	✓		✓	Android 2.1-update1
470	Sony Ericsson Xperia X10	✓	✓	✓		✓	Android 1.6 R1FA014
471	Sony Ericsson Xperia X10 mini (E10i)	✓	✓	✓		✓	Android 1.6
472	SonyEricsson XperiaX10mini pro(U20i)	✓	✓	✓		✓	Android 2.1-update1
473	Sony Ericsson Yari	✓	✓	✓		✓	R1BA049
474	Sony Ericsson Z520i	✓	✓	✓		✓	R3F015
475	Sony Ericsson Z530i	✓	✓	✓	✓	✓	R6BA030
476	Sony Ericsson Z600	✓	✓	✓	✓	✓	RE004
477	Sony Ericsson Z610i	✓	✓	✓	✓	✓	R1ED001
478	Sony Ericsson Z1010	✓	✓	✓	✓	✓	RG007
479	Toshiba TS921	✓	✓	✓		✓	
480	Toshiba G500	✓	✓	✓		✓	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓1 only from phone

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.