



Communication

Volkswagen Original Bluetooth Touch Adapter

Only in combination with UHV Standard (9W8)



Art.-Nr.:

3C0 051 435 TA

List of compatibility

This list will be updated at frequent intervals. Please understand that due to the range of mobile phones on market, we cannot maintain a description for every mobile phone and behaviour in detail. The proved software index of mobile phone is indicated. You will find further information about telephone menu settings by reading the user guide of your mobile phone.

For further questions or support please contact your local Volkswagen partner.

All data released by Volkswagen Zubehör GmbH. The content of this list has been compiled with due care and checked for correctness, but we do not accept liability for any mistakes, incompleteness or discrepancies that may occur.

For details of downloading Applets for Nokia Symbian S60 please browse over to
<http://www.bury.com/en/applet3rd>

- VW Polo (A05) 2010 ->
- VW Polo (A05) Cross Polo 2010 ->
- VW Polo (A05) Cross Polo 2010 ->
- VW Eos 2006/06 ->
- VW Golf (A5) 2006/06 ->
- VW Golf GT (A5) 2006/06 ->
- VW Golf GTI (A5) 2006/06 ->
- VW Golf R32 (A5) 2006/06 ->
- VW Golf Var. (A5) 2007 ->
- VW Golf Plus (A5) 2006/06 ->
- VW Cross Golf (A5) 2007 ->
- VW Golf Plus (A6) 2009 ->
- VW Golf Plus (A6) 2009 ->
- VW Golf Var. (A6) 2010 ->
- VW Golf (A6) 2009 ->
- VW Golf GTI (A6) 2009 ->
- VW Touran (A5-GP) 2006/10 ->
- VW Jetta (A5) 2006/06 ->
- VW Passat Lim. (B6) 2005/03 ->
- VW Passat Lim. R36 (B6) 2007 ->
- VW Passat Var. (B6) 2006 ->
- VW Passat CC (B6) 2009 ->
- VW Scirocco III 2008 ->
- VW Sharan 2008/05 ->
- VW Caddy Kasten (A5) 2006/06 ->
- VW Caddy Kombi (A5) 2006/06 ->
- VW Caddy Life (A5) 2006/06 ->
- VW Tiguan 2007 ->
- VW Touareg (GP) 2007 ->
- VW Touareg (GP) R50 2008 ->
- VW Multivan (T5) 2008 ->
- VW Transporter (T5) 2008 ->
- VW California (T5) 2008 ->
- VW Transporter Mittelhochdach (T5) 2008 ->
- VW Transporter Pritsche (T5) 2008 ->
- VW Multivan Startline (T5) 2008 ->
- VW Caravelle (T5) 2008 ->
- VW Multivan (T5-GP) 2010 ->
- VW California (T5-GP) 2010 ->
- VW Transporter (T5-GP) 2010 ->

No	Phone	Tested phone firmware	Display of battery status	GSM-signal strength	Provider	Redial	Set private mode via Touch Adapter	Play ring tone of phone	Hold first call	Accept / reject second call	Switch between two calls	Merge calls to conference	Answered calls	Missed calls	Dialled numbers	From SIM card	From phone	Show old text messages	Show new text messages	Comment
1	Nokia 2323 classic	v 06.46	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
2	Nokia 3109c	v 07.21	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
3	Nokia 3110c	v 04.91	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
4	Nokia 3120 classic	v 10.00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
5	Nokia 3230	v 5.0604.0	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		✓	✓		
6	Nokia 3250	v 03.24				✓	✓	✓		✓			✓ *	✓ *	✓ *		✓	✓ *	✓ *	Operate, but BURY Applet for Symbian S60 2nd is required
7	Nokia 3710 fold	v 03.80	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
8	Nokia 3720 classic	v 09.10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
9	Nokia 5200	v 03.92	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
10	Nokia 5230	v 12.0.089	✓	✓	✓	✓ **	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **		✓	✓ **	✓ **	
11	Nokia 5300	v 07.00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
12	Nokia 5500d	v 04.60				✓	✓	✓		✓			✓ *	✓ *	✓ *		✓	✓ *	✓ *	Operate, but BURY Applet for Symbian S60 2nd is required
13	Nokia 5530 XpressMusic	v 11.0.054	✓	✓	✓	✓ **	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
14	Nokia 5630 XpressMusic	v 012.008	✓	✓	✓	✓ **	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
15	Nokia 5700	v 03.83.1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ *	✓ *	✓ *		✓	✓ *	✓ *	Operate, but BURY Applet for Symbian S60 2nd is required
16	Nokia 6021	v 04.90	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
17	Nokia 6103	v 04.90	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
18	Nokia 6110 Navigator	v 03.58	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
19	Nokia 6111	v 03.58	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
20	Nokia 6120c	v 06.01	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
21	Nokia 6124c	v 04.34	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
22	Nokia 6125	v 05.43	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
23	Nokia 6151	v 04.10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
24	Nokia 6230	v05.50	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
25	Nokia 6230i	v 03.89	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	

Volkswagen Zubehör GmbH, An der Trift 67, D-63303 Dreieich, Postfach 10 22 70, D-63268 Dreieich
 Telefon: +49-6103-806-0, Telefax: +49-6103-806-211, E-Mail: info@volkswagen-zubehoer.de

✓ working

✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet2nd>

✓ 1 Only from phone

✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Tested phone firmware	Display of battery status	GSM-signal strength	Provider	Redial	Set private mode via Touch Adapter	Play ring tone of phone	Hold first call	Accept / reject second call	Switch between two calls	Merge calls to conference	Answered calls	Missed calls	Dialled numbers	From SIM card	From phone	Show old text messages	Show new text messages	Comment
26	Nokia 6233	v 05.60	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
27	Nokia 6234	v 05.60	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
28	Nokia 6270	v 03.81	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
29	Nokia 6280	v 06.43	✓	✓	✓	✓	✓	✓	✓	✓			✓	✓	✓	✓	✓			
30	Nokia 6288	v 06.10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
31	Nokia 6300	v 05.50	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
32	Nokia 6303 classic	v 08.90	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
33	Nokia 6303i classic	v 07.10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
34	Nokia 6500c	v 06.61	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
35	Nokia 6500 slide	v 06.61	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
36	Nokia 6680	v 5.04.40	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
37	Nokia 6681	v 6.09.00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
38	Nokia 6682	v 3.01.1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ *	✓ *	Operate, but BURY Applet for Symbian S60 2nd is required
39	Nokia 6710 Navigator	021.013	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
40	Nokia 6720 classic	012.008	✓	✓	✓	✓ **	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **	✓	✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
41	Nokia 7280	v 03.22	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
42	Nokia 7370	v 04.13	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
43	Nokia 7380	v 03.80	✓	✓	✓	✓	✓	✓		✓			✓	✓	✓	✓	✓			
44	Nokia 7710	v 03.04.2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓						✓		
45	Nokia 7900 Prism	v 04.84	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
46	Nokia 8600 Luna	v 03.52	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
47	Nokia 8800	v 04.10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
48	Nokia 9300i	v 5.50	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
49	Nokia C5	v 031.022	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
50	Nokia E50	v 07.36.0.0				✓	✓	✓		✓			✓ **	✓ **	✓ **	✓	✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required

Volkswagen Zubehör GmbH, An der Trift 67, D-63303 Dreieich, Postfach 10 22 70, D-63268 Dreieich
 Telefon: +49-6103-806-0, Telefax: +49-6103-806-211, E-Mail: info@volkswagen-zubehoer.de

✓ working

✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet2nd>

✓ 1 Only from phone

✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Tested phone firmware	Display of battery status	GSM-signal strength	Provider	Redial	Set private mode via Touch Adapter	Play ring tone of phone	Hold first call	Accept / reject second call	Switch between two calls	Merge calls to conference	Answered calls	Missed calls	Dialled numbers	From SIM card	From phone	Show old text messages	Show new text messages	Comment
51	Nokia E51	201.34.38	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
52	Nokia E52	033.002	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
53	Nokia E55	022.009	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
54	Nokia E60	3.0633.09.04				✓	✓	✓	✓				✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
55	Nokia E61	3.0633.09.05				✓	✓	✓					✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
56	Nokia E61i	3.0633.69.00				✓	✓						✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
57	Nokia E65	3.0633.69.00				✓	✓			✓			✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
58	Nokia E66	102.07.81	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
59	Nokia E70	3.0633.09.04				✓	✓	✓		✓			✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
60	Nokia E71	100.07.76	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
61	Nokia E72	021.024	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
62	Nokia E90	v 210.34.75	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
63	Nokia N70	v 5.0705.3.0.1				✓	✓	✓		✓			✓ **	✓ **	✓ **			✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
64	Nokia N71	v 4.06421.1.05				✓	✓	✓	✓	✓			✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
65	Nokia N73	v 4.0723.2.0.1				✓	✓	✓		✓			✓	✓	✓		✓	✓	✓	
66	Nokia N76	v 31.0.014	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
67	Nokia N79	v 11.049	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
68	Nokia N80	v 5.0719.0.2				✓	✓	✓	✓	✓			✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
69	Nokia N82	v 20.0.062	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
70	Nokia N85	v 11.047	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
71	Nokia N86 8MP	11.043	✓	✓	✓	✓ **	✓	✓	✓	✓	✓	✓			✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
72	Nokia N91	v 2.10.013				✓	✓	✓	✓	✓			✓	✓	✓		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
73	Nokia N93	v 20.0.058				✓	✓	✓	✓	✓			✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
74	Nokia N93i	v 30.0.013				✓	✓			✓			✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
75	Nokia N95	v 21.0.016	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required

Volkswagen Zubehör GmbH, An der Trift 67, D-63303 Dreieich, Postfach 10 22 70, D-63268 Dreieich
 Telefon: +49-6103-806-0, Telefax: +49-6103-806-211, E-Mail: info@volkswagen-zubehoer.de

✓ working

✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet2nd>

✓ 1 Only from phone

✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Tested phone firmware	Display of battery status	GSM-signal strength	Provider	Redial	Set private mode via Touch Adapter	Play ring tone of phone	Hold first call	Accept / reject second call	Switch between two calls	Merge calls to conference	Answered calls	Missed calls	Dialled numbers	From SIM card	From phone	Show old text messages	Show new text messages	Comment
76	Nokia N95 3G	v 10.2.006	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
77	Nokia N95 (8GB)	v 20.0.016	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
78	Nokia N96	10.024	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
79	Nokia N97	v 20.0.019	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
80	Nokia N97 mini	v 10.0.020	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
81	Nokia N900	v 3.2010.02-8	✓	✓	✓		✓	✓	✓	✓	✓	✓								
82	Nokia X3	v 03.60	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
83	Nokia X6	v 20.0.005	✓	✓	✓	✓ **	✓	✓	✓	✓	✓	✓	✓ **	✓ **	✓ **		✓	✓ **	✓ **	Operate, but BURY Applet for Symbian S60 3rd is required
84	Motorola E770v	r25221_u_85.83.e1p	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
85	Motorola E1070	r25221ld_u_85.97.c3p	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
86	Motorola KRZR K1	r4527_g_08.22.07r	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
87	Motorola KRZR Z3	r452b_g_08.01.02r	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
88	Motorola L2	r3511_g_0a.53.15r	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
89	Motorola RAZR V3i	r479_g_08.b4.85r	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
90	Motorola RAZR V3x	r25221ld_u_85.92.70r	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
91	Motorola RAZR V3xx	r2611rk_u_98.50.11r	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
92	Motorola RAZR2 V8	r601_g_80.42.39r	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
93	Motorola RAZR2 V9	r263313_u_a0.01.10r31	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
94	Motorola Z3	r452b_g_08.01.02r	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
95	Motorola Z8	esp00_u46.03e3g_0000053e	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
96	Sony Ericsson Aino	r1ba049	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
97	Sony Ericsson C510	r1fa035	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
98	Sony Ericsson C702	r3ca038	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
99	Sony Ericsson C902	r3ca038	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
100	Sony Ericsson C903	r1fa035	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	

Volkswagen Zubehör GmbH, An der Trift 67, D-63303 Dreieich, Postfach 10 22 70, D-63268 Dreieich
 Telefon: +49-6103-806-0, Telefax: +49-6103-806-211, E-Mail: info@volkswagen-zubehoer.de

✓ working

✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet2nd>

✓ 1 Only from phone

✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Tested phone firmware	Display of battery status	GSM-signal strength	Provider	Redial	Set private mode via Touch Adapter	Play ring tone of phone	Hold first call	Accept / reject second call	Switch between two calls	Merge calls to conference	Answered calls	Missed calls	Dialled numbers	From SIM card	From phone	Show old text messages	Show new text messages	Comment
101	Sony Ericsson C905	r1ea033	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
102	Sony Ericsson D750i	r1aa008	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
103	Sony Ericsson Elm	r7ba076	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
104	Sony Ericsson G502	r1fa031	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
105	Sony Ericsson G900	r9m003	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓		✓	
106	Sony Ericsson J105i Naite	r1ha035	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
107	Sony Ericsson K510i	r4ch003	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
108	Sony Ericsson K530i	r8bb001	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
109	Sony Ericsson K550i	r8ba024	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
110	Sony Ericsson K600i	r2ac001	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
111	Sony Ericsson K610i	r1j6001	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
112	Sony Ericsson K750i	r1n035	✓	✓	✓	✓	✓		✓	✓			✓	✓	✓	✓	✓	✓		
113	Sony Ericsson K770i	r8bc004	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
114	Sony Ericsson K800i	r1ed001	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
115	Sony Ericsson K810i	r1jf001	✓	✓	✓	✓	✓		✓	✓			✓	✓	✓	✓	✓	✓	✓	
116	Sony Ericsson K850i	r1fa035	✓	✓	✓	✓	✓						✓	✓	✓	✓	✓	✓	✓	
117	Sony Ericsson M600i	r9f011	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓		✓	
118	Sony Ericsson P1i	r9g007	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
119	Sony Ericsson Satio (Idou)	r1bb041	✓	✓	✓		✓		✓	✓	✓	✓				✓	✓			
120	Sony Ericsson S312	r3m008	✓	✓	✓		✓		✓	✓	✓	✓				✓	✓			
121	Sony Ericsson S700i	r3m008	✓	✓		✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
122	Sony Ericsson T650i	r8c004	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
123	Sony Ericsson Vivaz	1224-4699_r2ak006	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
124	Sony Ericsson V630i	r1ce001	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
125	Sony Ericsson V800	r1af005	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓				

Volkswagen Zubehör GmbH, An der Trift 67, D-63303 Dreieich, Postfach 10 22 70, D-63268 Dreieich
 Telefon: +49-6103-806-0, Telefax: +49-6103-806-211, E-Mail: info@volkswagen-zubehoer.de

✓ working

✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet2nd>

✓ 1 Only from phone

✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Tested phone firmware	Display of battery status	GSM-signal strength	Provider	Redial	Set private mode via Touch Adapter	Play ring tone of phone	Hold first call	Accept / reject second call	Switch between two calls	Merge calls to conference	Answered calls	Missed calls	Dialled numbers	From SIM card	From phone	Show old text messages	Show new text messages	Comment
126	Sony Ericsson W205	r1ca001	✓	✓	✓		✓		✓	✓	✓	✓				✓	✓			
127	Sony Ericsson W395	r1fa012	✓	✓	✓		✓		✓	✓	✓	✓					✓			
128	Sony Ericsson W580i	r8ba024	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
129	Sony Ericsson W595i	r1ea031	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
130	Sony Ericsson W610i	r1jd001	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
131	Sony Ericsson W660i	r8bb001	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
132	Sony Ericsson W705	r6bc003	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
133	Sony Ericsson W715	r1ga026	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
134	Sony Ericsson W810i	r4db005	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
135	Sony Ericsson W850i	r1jc002	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
136	Sony Ericsson W880i	r8ba024	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
137	Sony Ericsson W890i	r1fa035	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
138	Sony Ericsson W900i	r58c004	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
139	Sony Ericsson W910i	r1ea030	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
140	Sony Ericsson W950i	r9g007	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓			✓	
141	Sony Ericsson W960i	r6g04	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓			✓	
142	Sony Ericsson W995	r1ea032	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
143	Sony Ericsson XPERIA X1	5.2.19958	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
144	Sony Ericsson XPERIA X2	r1aa035	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
145	Sony Ericsson XPERIA X10	android 1.6r1fa014	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓		✓			
146	Sony Ericsson XPERIA X10 mini	android 1.6	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓		✓			
147	Sony Ericsson Yari	r1ba049	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
148	Sony Ericsson Z530i	r6da001	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
149	Sony Ericsson Z610i	r1ed001	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
150	Samsung B2100	b2100xxh1	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	

Volkswagen Zubehör GmbH, An der Trift 67, D-63303 Dreieich, Postfach 10 22 70, D-63268 Dreieich
 Telefon: +49-6103-806-0, Telefax: +49-6103-806-211, E-Mail: info@volkswagen-zubehoer.de

✓ working

✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet2nd>

✓ 1 Only from phone

✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Tested phone firmware	Display of battery status	GSM-signal strength	Provider	Redial	Set private mode via Touch Adapter	Play ring tone of phone	Hold first call	Accept / reject second call	Switch between two calls	Merge calls to conference	Answered calls	Missed calls	Dialled numbers	From SIM card	From phone	Show old text messages	Show new text messages	Comment
151	Samsung B2700	b2700xxib2	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓		✓			
152	Samsung B3410	b3410xxik4	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓		✓	✓			
153	Samsung B7330 OmniaPro	b7330xxig2	✓	✓	✓	✓	✓		✓	✓	✓	✓				✓	✓			
154	Samsung B7610 OmniaPro	b7610xxik2	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
155	Samsung C6625	c6625buie1	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
156	Samsung I8000 Omnia II	i8000xxii6	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
157	Samsung Vodafone 360 H1 (i8320)	i8320buik1	✓	✓			✓		✓	✓	✓	✓					✓			
158	Samsung i8910 Omnia HD	i8910xxie7	✓	✓	✓		✓		✓	✓	✓	✓					✓			
159	Samsung S3650 Corby	s3650xxii3	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
160	Samsung S5230 Avilla	s5230bvie3	✓	✓	✓	✓	✓		✓	✓	✓	✓					✓			
161	Samsung S8000 Jet	s8000xxif5	✓	✓	✓		✓			✓						✓	✓			
162	Samsung S8300V	s8300buic6	✓	✓	✓	✓	✓			✓			✓	✓	✓	✓	✓	✓	✓	
163	Samsung SGH-D520	d520xxf1		✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
164	Samsung SGH-D840	d840xxf1		✓	✓	✓	✓		✓	✓			✓	✓	✓	✓	✓			
165	Samsung SGH-D800	d800xxfa2		✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
166	Samsung SGH-D900	d900xega1	✓	✓	✓	✓			✓	✓	✓	✓								
167	Samsung SGH-E200	e200xagd3	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
168	Samsung SGH-E500	e500xafh7	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
169	Samsung SGH-E720	e720xxec6	✓	✓	✓	✓	✓						✓	✓	✓	✓	✓			
170	Samsung SGH-E730	e730xae1				✓	✓			✓			✓	✓	✓					
171	Samsung SGH-F300	f300xxgcg		✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
172	Samsung SGH-G600	g600xwge4	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
173	Samsung SGH-G800	g80lakhb1	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
174	Samsung SGH-i200	pi200achhi	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓					
175	Samsung SGH-i550	i550akhe2	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓		✓			

Volkswagen Zubehör GmbH, An der Trift 67, D-63303 Dreieich, Postfach 10 22 70, D-63268 Dreieich
 Telefon: +49-6103-806-0, Telefax: +49-6103-806-211, E-Mail: info@volkswagen-zubehoer.de

✓ working

✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet2nd>

✓ 1 Only from phone

✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Tested phone firmware	Display of battery status	GSM-signal strength	Provider	Redial	Set private mode via Touch Adapter	Play ring tone of phone	Hold first call	Accept / reject second call	Switch between two calls	Merge calls to conference	Answered calls	Missed calls	Dialled numbers	From SIM card	From phone	Show old text messages	Show new text messages	Comment
176	Samsung SGH-i600	i600xaf13				✓	✓			✓										
177	Samsung SGH-i900 OMNIA 16GB	i900xghh4	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
178	Samsung SGH-i900 OMNIA 8GB	i900xxib2	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
179	Samsung SGH-P900	p900xxfe2		✓	✓	✓	✓		✓				✓	✓	✓	✓	✓			
180	Samsung SGH-U200	v200xxhd1	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓		✓	✓	
181	Samsung SGH-U600	u900boh2		✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
182	Samsung SGH-U700v	v700bhhb1	✓	✓	✓	✓	✓		✓	✓			✓	✓	✓	✓	✓	✓		
183	Samsung SGH-U800	u800brhl1	✓	✓	✓	✓	✓		✓	✓	✓	✓					✓	✓	✓	
184	Samsung SGH-X820	x820nxxfj1		✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
185	LG BL20 New Chocolate	bl20 v10d	✓	✓	✓	✓	✓		✓	✓	✓	✓				✓	✓			
186	LG BL40 New Chocolate	bl40-mem70x-v10s-sep-21-2009-xx	✓	✓	✓	✓	✓		✓	✓	✓	✓				✓	✓			
187	LG GC900 Viewty Smart	gc900at_v10b	✓	✓	✓	✓	✓		✓	✓	✓	✓				✓	✓			
188	LG GD900 Crystal	gd900at_v10c	✓	✓	✓	✓	✓		✓	✓	✓	✓				✓	✓			
189	LG GM750	v10b	✓	✓	✓	✓	✓		✓	✓	✓	✓				✓	✓			
190	LG GT500	gt500-10i	✓	✓	✓	✓	✓		✓	✓	✓	✓				✓	✓			
191	LG KC550	ks55a-01-v10b-204-10-xx-may-28-2010	✓	✓	✓	✓	✓		✓							✓	✓			
192	LG KE 850 PRADA	ke850p40-eur-v10n-xxxx-xx	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓		✓	
193	LG KF 750 Secret	kf750-v10a-24042008	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
194	LG KM 900 Arena	km900_v10t	✓	✓	✓	✓	✓		✓	✓	✓	✓				✓	✓		✓	
195	LG KP500 Cookie	kp500at_v10d	✓	✓	✓	✓	✓		✓	✓	✓	✓				✓			✓	
196	HTC Desire	android 2.1 update fsw. nr. 1.15.101.1	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
197	HTC Hero / T-Mobile G2 Touch	1.51.0.0.a6288	✓	✓	✓	✓	✓		✓	✓	✓	✓				✓	✓			
198	HTC Legend	android os 2.1sw. nr. 1.23.161.1	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
199	HTC Magic	1.5	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
200	HTC Tattoo	sw 1.67.405.6	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			

Volkswagen Zubehör GmbH, An der Trift 67, D-63303 Dreieich, Postfach 10 22 70, D-63268 Dreieich
 Telefon: +49-6103-806-0, Telefax: +49-6103-806-211, E-Mail: info@volkswagen-zubehoer.de

✓ working

✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet2nd>

✓ 1 Only from phone

✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Tested phone firmware	Display of battery status	GSM-signal strength	Provider	Redial	Set private mode via Touch Adapter	Play ring tone of phone	Hold first call	Accept / reject second call	Switch between two calls	Merge calls to conference	Answered calls	Missed calls	Dialled numbers	From SIM card	From phone	Show old text messages	Show new text messages	Comment
201	HTC Touch Cruise	kl750-v10a-24042009	✓	✓	✓		✓		✓	✓	✓	✓				✓				
202	HTC Touch Diamond	1.93.407.1 ger	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
203	HTC Touch DIAMOND 2	radio.1.19.407.1 (51489) ger	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
204	HTC Touch	52.1238 (build17745.0.2.3)	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
205	HTC Touch2	1.28.407.4 (66092)	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓			✓	✓			
206	HTC Touch 3G	2.32.407.2 (44800)	✓	✓	✓		✓		✓	✓	✓	✓				✓	✓			
207	HTC Touch Dual	rom.1.31.407.09.pptokoh.2511.010h	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
208	HTC Touch HD	rom:1.14.407.3 (22273) ger	✓	✓	✓		✓		✓	✓	✓	✓				✓	✓			
209	HTC HD mini	rom:1.07.407.1 (65429) ger	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
210	HTC HD2	1.43.111.2 (70315) ger	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
211	HTC v1615 (Kaiser)	1.56.161.4	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓		✓			
212	HTC MDA Touch	4.1.13.42	✓	✓	✓	✓	✓			✓	✓		✓	✓	✓	✓	✓			
213	HTC MDA Vario III	1.56.110.4	✓	✓	✓	✓	✓			✓										
214	HTC S730	ce0s 5.2.1622	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
215	HTC SPV M-500	4.21.1088				✓	✓			✓			✓	✓	✓					
216	HTC SPV M-5000	os 5.1.1700 (build 14328.0.0.0)				✓	✓			✓			✓	✓	✓					
217	HTC XDA Orbit 2	v5.2.1623 (build 16128.0.4.5)	✓	✓	✓	✓	✓			✓			✓	✓	✓	✓	✓			
218	BlackBerry 8100 Pearl	v4.2.1.109	✓	✓	✓		✓	✓	✓	✓	✓						✓			
219	BlackBerry 8220 Pearl Flip	v4.6.0.64	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		✓			
220	BlackBerry 8300 Curve	v4.2.2.42	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		✓			
221	BlackBerry 8310 Curve	v 4.22146		✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓			✓	✓	
222	BlackBerry 8520 Curve	v4.6.1.286 pl 4.2.0.122	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		✓			
223	BlackBerry 8700g	4.1.0.308	✓	✓	✓	✓	✓	✓	✓	✓			✓	✓	✓		✓			
224	BlackBerry 8707v	v4.1.0.275	✓	✓	✓	✓	✓	✓	✓	✓			✓	✓	✓		✓			
225	BlackBerry 8700c	v4.1.0.170	✓	✓	✓	✓	✓	✓	✓	✓			✓	✓	✓		✓			

Volkswagen Zubehör GmbH, An der Trift 67, D-63303 Dreieich, Postfach 10 22 70, D-63268 Dreieich
 Telefon: +49-6103-806-0, Telefax: +49-6103-806-211, E-Mail: info@volkswagen-zubehoer.de

✓ working

✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet2nd>

✓ 1 Only from phone

✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Touch Adapter

Updated: 2010-08-31 / V282010-08-31 / V28

Device software version: SW: 0124SW: 0124

No	Phone	Tested phone firmware	Display of battery status	GSM-signal strength	Provider	Redial	Set private mode via Touch Adapter	Play ring tone of phone	Hold first call	Accept / reject second call	Switch between two calls	Merge calls to conference	Answered calls	Missed calls	Dialled numbers	From SIM card	From phone	Show old text messages	Show new text messages	Comment
226	BlackBerry 8900 Curve	v4.6.1.38	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		✓			
227	BlackBerry 9000 Bold	v4.6.0.111	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓		✓			
228	BlackBerry 9500 Storm	v4.7.0.78	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓		✓			
229	BlackBerry 9520 Storm2	v5.0.0.306	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓		✓			
230	BlackBerry 9530 Storm	v4.7.0.47	✓	✓	✓		✓		✓	✓	✓	✓					✓			
231	BlackBerry 9630	v4.7.1.20 pl 4.1.0.15	✓	✓	✓	✓	✓		✓	✓	✓		✓	✓	✓		✓			
232	BlackBerry 9700 Bold	v5.0.0.296 pl 5.1.0.83	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓		✓			
233	Palm Pre	v1.0	✓	✓	✓	✓	✓		✓	✓			✓	✓	✓		✓			
234	Palm Treo 500V	v 1.02	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
235	Apple iPhone	1.1.1 (3a109a)	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓			
236	Apple iPhone 3G	4.0.1 (8a306)	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓		✓			
237	Apple iPhone 3GS	4.0.1 (8a306)	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓		✓			
238	Apple iPhone 4	4.0.1 (8a306)	✓	✓	✓	✓	✓		✓				✓	✓	✓		✓			
239	ASUS Solaris V1520	5.2.1620	✓	✓	✓	✓	✓			✓			✓	✓	✓					
240	Sagem TiGR 350G	1.54.02				✓	✓	✓		✓			✓	✓	✓					

Volkswagen Zubehör GmbH, An der Trift 67, D-63303 Dreieich, Postfach 10 22 70, D-63268 Dreieich
 Telefon: +49-6103-806-0, Telefax: +49-6103-806-211, E-Mail: info@volkswagen-zubehoer.de

- ✓ working
- ✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet2nd>
- ✓ 1 Only from phone
- ✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles)
<http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.