

No	Phone	Set of tips	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
1	Apple iPhone	A	✓	07-0257-0c.01	3.0 (7a341)
2	Apple iPhone 3G	A	✓	07-0257-0c	4.0.1 (8a306)
3	Apple iPhone 3GS	A	✓	07-0257-0c.01	6.0 (10a403)
4	Apple iPhone 4	A	✓	07-0257-0c.01	7.0 (11a465)
5	Apple iPhone 4S	A	✓	07-0257-0c.01	7.0 (11a465)
6	Apple iPhone 5	A	✓	0-07-0258-0.06	7.0 (11a465)
7	Apple iPhone 5c	A	✓	0-07-0258-0.06	7.0.2 (11a501)
8	Apple iPhone 5s	A	✓	0-07-0258-0.06	7.0.3 (11b511)
9	BlackBerry 8300 Curve	D	✓	07-0257-0b	v4.2.2.27
10	BlackBerry 8310 Curve	D	✓	07-0257-0b	v4.2.2.146
11	BlackBerry 8520 Curve	A	✓	07-0257-0a	v4.6.1.286 pl 4.2.0.122
12	BlackBerry 8800	A	✓	07-0257-0b	v4.2.1.43
13	BlackBerry 8900 Curve	A	✓	07-0257-0a	v5.0.0.411 pl5.2.0.31
14	BlackBerry 9000 Bold	D	✓	07-0257-0b	v4.6.0.111(platform 4.0.0.129)
15	BlackBerry 9105 Pearl	A	✓	07-0257-0a	v5.0.0.623(platform 6.2.0.43)
16	BlackBerry 9300 Curve 3G	A	✓	07-0257-0a	v5.0.0.716(platform 6.3.0.13)
17	BlackBerry 9320 Curve	A	✓	07-0257-0a.01	v7.1.0.398(platform 9.49.0.31)
18	BlackBerry 9360 Curve	A	✓	07-0257-0a	v7.0.0.353(platform 8.0.0.388)
19	BlackBerry 9380 Curve	A	✓	07-0257-0a.01	v7.1.0.470(platform 9.32.0.108)
20	BlackBerry 9500 Storm	A	✓	07-0257-0a	v4.7.0.78 pl 4.0.0.98
21	BlackBerry 9520 Storm2	A	✓	07-0257-0a	v5.0.0.497 pl 4.2.0.220
22	BlackBerry 9630	A	✓	07-0257-0a	v4.7.1.20 pl 4.1.0.15
23	BlackBerry 9700 Bold	A	✓	07-0257-0a	v5.0.0.979 pl 5.1.0.177
24	BlackBerry 9780 Bold	A	✓	07-0257-0a	v6.0.0.359 pl 6.5.0.93
25	BlackBerry 9800 Torch	A	✓	07-0257-0a	v6.0.0.100 pl 6.4.0.47
26	BlackBerry 9810 Torch	A	✓	07-0257-0a	v7.0.0.261 pl 5.0.0.469
27	BlackBerry 9860 Torch	A	✓	07-0257-0a	v7.0.0.585 pl 5.0.0.734
28	BlackBerry 9900 Bold Touch	A	✓	07-0257-0a	v7.0.0.387(platform 5.0.0.572)
29	BlackBerry Q5	A	✓	07-0257-0a	v10.2.0.429
30	BlackBerry Q10	A	✓	07-0257-0a	v10.2.1.537
31	HTC 7 Mozart	A	✓	07-0257-0a	windows phone 7radio 5.50.09.18_22.24.50.09u
32	HTC 7 Pro	D	✓	07-0257-0a	windows phone 7radio 5.63.09.13_22.36.50.15u
33	HTC Desire	A	✓	07-0257-0a	android os 2.2sw. nr. 2.12.110.4
34	HTC Desire HD	A	✓	07-0257-0a.01	sw. nr. 2.50.405.2
35	HTC Desire S	A	✓	07-0257-0a.01	android os 2.3.3 1.47.401.4
36	HTC Desire X	A	✓	07-0257-0a.01	android os 4.1.1sw. nr. 2.23.118.2
37	HTC Desire Z	B	✓	07-0257-0a	android os 2.2.1sw. nr. 1.72.405.2
38	HTC EVO 3D X515m	A	✓	07-0257-0a.01	android os 2.3.4sw. nr. 1.20.401.2
39	HTC Incredible S	C	✓	07-0257-0a	android os 2.2.1sw. nr. 1.36.405.1
40	HTC Legend	A	✓	07-0257-0a	android os 2.1sw. nr. 1.23.161.1

BURY Technologies UK Enquiries Tel. +44 (0)1489 881 118
E-mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet2nd>
- ✓ 1 Only from phone
- ✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet3rd>
- ✓ 2 Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch) <http://www.bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Set of tips	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
41	HTC Magic	A	✓	07-0257-0b	1.5
42	HTC T-Mobile G1	B	✓	07-0257-0b	fw: 1.1
43	HTC Hero / T-Mobile G2 Touch	A	✓	07-0257-0b	fw: 1.51.0.0.a6288
44	HTC One S	A	✓	07-0257-0a.01	android 4.1.13.16.111.5
45	HTC One V	A	✓	07-0257-0a.01	android 4.0.32.22.111.1
46	HTC Sensation	A	✓	07-0257-0a	android os 2.3.4sw. nr. 1.45.111.2
47	HTC Tattoo	A	✓	07-0257-0b	sw 1.67.405.6
48	HTC Touch2	A	✓	07-0257-0b	1.28.407.4 (66092)
49	HTC Touch DIAMOND 2	B	✓	07-0257-0b	radio 1.19.407.1 (51489) ger
50	HTC Touch HD	A	✓	07-0257-0b	rom: 1.14.407.3 (22273) ger
51	HTC HD mini	D	✓	07-0257-0b	rom: 1.36.479.1 (94538) wwe
52	HTC HD2	A	✓	07-0257-0a	1.43.111.2 (70315) ger
53	HTC HD7	A	✓	07-0257-0a.01	windows phone 7radio sw:5.51.09.06a_22.30.50.09u
54	HTC Touch Pro	B	✓	07-0257-0b	1.60.161.1 wwe
55	HTC Touch Pro2	B	✓	07-0257-0b	radio 1.19.407.1 (51489) ger
56	HTC Wildfire	A	✓	07-0257-0a.01	android 2.2.12.24.162.1
57	LG BL20 New Chocolate	A	✓	07-0257-0a	bl20 v10d
58	LG BL40 New Chocolate	A	✓	07-0257-0a	bl40-msm76xx-v10a-sep-21-2009-xx
59	LG GT500	A	✓	07-0257-0a	gt500-v10i
60	LG KE 850 PRADA	C			ke850p40-eur-v10n-xxx-xx may 07 2007
61	LG KE 970	A			ke970p40-eur-v10n-xxx-xx apr 07 2007
62	LG KF 750 Secret	A			kf750-v10a-24042008
63	LG KM 900 Arena	C			km900at_v10t
64	LG KP500 Cookie	C			kp500at_v10d
65	LG KU 990	C			n.a.
66	LG P710 Optimus L7 II	A	✓	07-0257-0a.01	android 4.1.2 sw lg-p71010e-eur-xx
67	LG P970	A	✓	07-0257-0a.01	android 2.2.2 sw lg-p970-v10b
68	LG Optimus 2X (P990 Optimus Speed)	A	✓	07-0257-0a.01	android 2.2.2 sw lge lgp990-v10e
69	Motorola DEFY (MB525)	A	✓	07-0257-0a.01	android 2.1-update1r26ld?u?83.39.24i
70	Motorola Milestone	A	✓	07-0257-0a	2,0
71	Motorola Milestone 2	A	✓	07-0257-0a	android 2.2
72	Motorola Motoluxe (XT615)	A	✓	07-0257-0a.01	android 2.3.7nk: 1_67c_4035
73	Motorola RAZR i XT890	A	✓	07-0257-0a.01	android 4.1.29.8.21-50_smi-26.1358455837
74	Nokia 113	C			v03.32
75	Nokia 208.1	A			v06.01
76	Nokia 500	A	✓	07-0257-0a	symbian belle111.020.0059
77	Nokia 515	A			v 07.01
78	Nokia 2730 classic	D			v 10.40
79	Nokia 3720 classic	D			v09.10
80	Nokia 5530 XpressMusic	C	✓	07-0257-0d	v 11.0.054

BURY Technologies UK Enquiries Tel. +44 (0)1489 881 118
E-mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet2nd>
- ✓ 1 Only from phone
- ✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet3rd>
- ✓ 2 Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch) <http://www.bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Set of tips	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
81	Nokia 5630 XpressMusic	C			v 012.008
82	Nokia 5730 XpressMusic	B			100.48.122
83	Nokia 5800 XpressMusic	B			v 20.0.012
84	Nokia 6124c	D			v04.34
85	Nokia 6220 Classic	D	✓	07-0257-0d	v03.23
86	Nokia 6300	C			v 04.70
87	Nokia 6300i	C			v03.41
88	Nokia 6303 classic	C	✓	07-0257-0d	v 08.90
89	Nokia 6500c	C	✓	07-0257-0d	v 03.21
90	Nokia 6700 classic	C			v 07.60
91	Nokia 6710 Navigator	D	✓	07-0257-0d	021.013
92	Nokia 7900 Prism	C	✓	07-0257-0d	v03.40
93	Nokia 8600 Luna	D	✓	07-0257-0d	v03.52
94	Nokia Asha 300	A	✓	07-0257-0d.01	v 06.97
95	Nokia Asha 311	A	✓	07-0257-0a.01	v 05.92
96	Nokia C2-01	D			v 11.00
97	Nokia C3-00	A	✓	07-0257-0d	v 08.63
98	Nokia C3-01 Touch and Type	C			v 05.65
99	Nokia C5	C			v 031.022
100	Nokia C5-00 5MP	C	✓	07-0257-0a.01	v 073.001
101	Nokia C5-03	C			v 22.0.007
102	Nokia C6	D			v 42.0.004
103	Nokia C7-00	A			v 012.003
104	Nokia E5-00	C	✓	07-0257-0d	v 071.003
105	Nokia E6-00	A	✓	07-0257-0a	v 021.014
106	Nokia E7-00	A			v 022.014
107	Nokia E51	A	✓	07-0257-0a.01	411.34.001
108	Nokia E52	A	✓	07-0257-0a	033.002
109	Nokia E55	A	✓	07-0257-0a	034.001
110	Nokia E66	C			v 102.07.81
111	Nokia E71	C			v 007.49.4
112	Nokia E72	A			081.003
113	Nokia E75	D			110.48.125
114	Nokia Lumia 520	A	✓	07-0257-0a.01	windows phone 8.0sw 2.0.242020.8
115	Nokia Lumia 610	A			windows phone 7.5radio sw:1.0.66.00
116	Nokia Lumia 800	A	✓	07-0257-0a.01	windows phone 7.5radio sw:1.6.00.24
117	Nokia Lumia 820	A	✓	07-0257-0a.01	windows phone 8.0radio sw:1.0.202075.3
118	Nokia Lumia 900	A	✓	07-0257-0a.01	windows phone 7.5radio sw:2.1.75.25
119	Nokia N8	A	✓	07-0257-0a	symbian bellev 111.030.0609
120	Nokia N9	A	✓	07-0257-0a	v 20.2011.40-4.341.01.1_pr_341

BURY Technologies UK Enquiries Tel. +44 (0)1489 881 118
E-mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet2nd>
- ✓ 1 Only from phone
- ✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet3rd>
- ✓ 2 Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch) <http://www.bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Set of tips	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
121	Nokia N78	D	✓	07-0257-0d	v 12.26
122	Nokia N79	D	✓	07-0257-0d	v 11.049
123	Nokia N82	B	✓	07-0257-0d	v 10.0.046
124	Nokia N85	D			v 11.047
125	Nokia N96	B	✓	07-0257-0d	10.024
126	Nokia N97	D	✓	07-0257-0a	v 20.0.019
127	Nokia N97 mini	D	✓	07-0257-0a	v 30.0.004
128	Nokia N900	B	✓	07-0257-0a	v 3.2010.02-8
129	Nokia X3	D			v 03.60
130	Nokia X6	D	✓	07-0257-0a.01	v 40.0.002
131	Nokia X7-00	A			symbian bellev 111.030.0609
132	Palm Pre	D	✓	07-0257-0a	v1.0
133	Samsung Ace S5830	A	✓	07-0257-0a	android 2.3.3 sw s5830xwkp5
134	Samsung B2100	B			b2100xxh1
135	Samsung B2700	B	✓	07-0257-0a	b2700xxib2
136	Samsung B7330 OmniaPro	A	✓	07-0257-0a	b7330xxig2
137	Samsung B7610 OmniaPro	B	✓	07-0257-0a	b7610xxik2
138	Samsung C6625	A			c6625buie1
139	Samsung E2121B	C			e2121bxxkc1
140	Samsung i7500 Galaxy	A	✓	07-0257-0a	i7500xxii5
141	Samsung I8150 Galaxy W	A	✓	07-0257-0a	i8150xxlmb
142	Samsung I8160 Galaxy Ace 2	A	✓	07-0257-0a.01	i8160xxli2
143	Samsung I8190 Galaxy S III mini	A	✓	07-0257-0a.01	android 4.1.2i8190xxamg4
144	Samsung i8320 Vodafone 360 H1	A	✓	07-0257-0a	i8320buik1
145	Samsung I8700 Omnia 7	A	✓	07-0257-0a	windows phone 7radio sw:2424.10.10.3
146	Samsung i8910 Omnia HD	B	✓	07-0257-0a	i8910xxie7
147	Samsung I9000 Galaxy S	A	✓	07-0257-0a	i9000xxjvo
148	Samsung I9001 Galaxy S Plus	A	✓	07-0257-0a	android 2.3.6i9001xxkpk
149	Samsung I9100 Galaxy S II	A	✓	07-0257-0a	i9100xxke7
150	Samsung I9195 Galaxy S 4 mini	A	✓	07-0257-0a	android 4.2.2 i9195xxubmj7
151	Samsung S3650 Corby	A	✓	07-0257-0a	s3650xxii3
152	Samsung S5260 Star II	A			s5260xxkc4
153	Samsung S5360 Galaxy Y	A			android 2.3.6 sw: s5360xxle1
154	Samsung S5570i Galaxy Mini	A			android 2.3.6 sw: s5570ixxld6
155	Samsung S5690 Galaxy Xcover	A			android 2.3.6 sw: s5690xxle5
156	Samsung S6500 Galaxy mini 2	A	✓	07-0257-0a.01	android 2.3.6 sw: s6500xxld2
157	Samsung S7500 Galaxy Ace Plus	A	✓	07-0257-0a.01	s7500xxlh1
158	Samsung S7560 Galaxy Trend (Ace II X)	A	✓	07-0257-0a.01	android 4.0.4sw: s7560xxamf1
159	Samsung S7710 Galaxy Xcover 2	A			android 4.1.2 sw: s7710xxamb5
160	Samsung S8000 Jet	A	✓	07-0257-0a	s8000xxif5

BURY Technologies UK Enquiries Tel. +44 (0)1489 881 118
E-mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet2nd>
- ✓ 1 Only from phone
- ✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet3rd>
- ✓ 2 Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch) <http://www.bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Set of tips	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
161	Samsung S8300V	B	✓	07-0257-0a	s8300buic6
162	Samsung S8500 Wave	A	✓	07-0257-0a.01	s8500xxj4
163	Samsung S8530 Wave II	A	✓	07-0257-0a	s8530xxjka
164	Samsung S8600 Wave 3	A	✓	07-0257-0a.01	s8600xxla1
165	Samsung SGH-F480	A			f480bohe3
166	Samsung SGH-F700v	B	✓	07-0257-0a	f700amgj8
167	Samsung SGH-U800	C			u800brh1
168	Samsung SGH-i900 OMNIA 16GB	A			i900boh2
169	SONY Xperia E (C1505)	A	✓	07-0257-0a.01	android 4.1.1 sw 11.3.a.2.23
170	SONY Xperia J (ST26i)	A	✓	07-0257-0a.01	android 4.1.2 sw 11.2.a.0.31
171	SONY Xperia P (LT22i)	A			android 4.0.4 sw 6.1.1.b.1.54
172	SONY Xperia Tipo (ST21i)	A	✓	07-0257-0a.01	android 4.0.4 sw 11.0.a.22
173	SONY Xperia U (ST25i)	A			android 4.0.4 sw 6.1.1.b.1.10
174	Sony Ericsson Aino	B	✓	07-0257-0e	r1ba049
175	Sony Ericsson C702	B	✓	07-0257-0e.01	r3aa054
176	Sony Ericsson C902	C	✓	07-0257-0e	r3ba035
177	Sony Ericsson C903	D			r1fa035
178	Sony Ericsson C905	D	✓	07-0257-0e	r1da034
179	Sony Ericsson Elm	C	✓	07-0257-0e	r7ca061
180	Sony Ericsson G900	D	✓	07-0257-0e.01	1.25.206.3 wwe
181	Sony Ericsson K550i	D	✓	07-0257-0e	r1jd001
182	Sony Ericsson K770i	A	✓	07-0257-0e.01	r8ba024
183	Sony Ericsson K850i	B	✓	07-0257-0e	r1fa035
184	Sony Ericsson Satio (Idou)	B	✓	07-0257-0e	r1bb041
185	Sony Ericsson W595i	C			r3ea031
186	Sony Ericsson W705	D			r1da034
187	Sony Ericsson W890i	C			r1fa035
188	Sony Ericsson W950i	B	✓	07-0257-0e	r9c001
189	Sony Ericsson W995	D	✓	07-0257-0e	r1ea032
190	Sony Ericsson Vivaz	A			1224-4699_r2ak006
191	Sony Ericsson Xperia Arc (LT15i)	A			android 2.3.4 sw 4.0.2.a.0.62
192	Sony Ericsson Xperia ray	A			android 2.3.4 sw 4.0.2.a.0.69
193	Sony Ericsson Xperia X1	D	✓	07-0257-0a	1.00.161.2
194	Sony Ericsson Xperia X2	B	✓	07-0257-0e	r1aa035
195	Sony Ericsson Xperia X8	A			android 2.1-update1
196	Sony Ericsson Xperia X10	A			android 2.3.33.0.1.g.0.75
197	Sony Ericsson Yari	D			r1ba049

BURY Technologies UK Enquiries Tel. +44 (0)1489 881 118
E-mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet2nd>
- ✓ 1 Only from phone
- ✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet3rd>
- ✓ 2 Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch) <http://www.bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.