

| No | Phone                      | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comments |
|----|----------------------------|-------------|-------------------|------------------------|--|
| 1  | Apple iPhone               | A/E         | ✓                 | 0-07-0258-0.07         | 3.0 (7a341)                                      |
| 2  | Apple iPhone 3G            | E           | ✓                 | 0-07-0258-0.07         | 4.2.1 (8c148)                                    |
| 3  | Apple iPhone 3GS           | E           | ✓                 | 0-07-0258-0.07         | 6.1.2 (10b146)                                   |
| 4  | Apple iPhone 4             | A/E         | ✓                 | 0-07-0258-0.07         | 7.0 (11a465)                                     |
| 5  | Apple iPhone 4S            | A/E         | ✓                 | 0-07-0258-0.07         | 7.1.1 (11d201)                                   |
| 6  | Apple iPhone 5             | E           | ✓                 | 0-07-0258-0.08         | 7.0 (11a465)                                     |
| 7  | Apple iPhone 5c            | A'          | ✓                 | 0-07-0258-0.08         | 7.1.1 (11d201)                                   |
| 8  | Apple iPhone 5s            | A'          | ✓                 | 0-07-0258-0.08         | 7.1.1 (11d201)                                   |
| 9  | Apple iPhone 6             | A'          | ✓                 | 0-07-0258-0.08         | 8.0.2 (12a405)                                   |
| 10 | BlackBerry 8100 Pearl      | F           | ✓                 | 0-07-0258-0.02         | v4.5.0.69(pl2.7.0.72)                            |
| 11 | BlackBerry 8110 Pearl      | F           | ✓                 | 0-07-0258-0.02         | v4.5.0.55 (pl 2.7.0.68)                          |
| 12 | BlackBerry 8520 Curve      | F           | ✓                 | 0-07-0258-0.01         | v4.6.1.286 pl 4.2.0.122                          |
| 13 | BlackBerry 8800            | A'          | ✓                 | 0-07-0258-0.02         | v4.5.0.174 (pl 2.7.0.105)                        |
| 14 | BlackBerry 9100 Pearl      | E           | ✓                 | 0-07-0258-0.01         | v5.0.0.696(platform 6.2.0.57)                    |
| 15 | BlackBerry 9105 Pearl      | E           | ✓                 | 0-07-0258-0.01         | v5.0.0.696(platform 6.2.0.57)                    |
| 16 | BlackBerry 9320 Curve      | E           | ✓                 | 0-07-0258-0.01         | v7.1.0.714(platform 9.49.0.76)                   |
| 17 | BlackBerry 9360 Curve      | E           | ✓                 | 0-07-0258-0.01         | v7.1.0.234(platform 9.6.0.36)                    |
| 18 | BlackBerry 9500 Storm      | F           | ✓                 | 0-07-0258-0.01         | v4.7.0.41 pl 4.0.0.40                            |
| 19 | BlackBerry 9520 Storm2     | F           | ✓                 | 0-07-0258-0.01         | v5.0.0.497 pl 4.2.0.220                          |
| 20 | BlackBerry 9700 Bold       | F           | ✓                 | 0-07-0258-0.01         | v5.0.0.979 pl 5.1.0.178                          |
| 21 | BlackBerry 9780 Bold       | F           | ✓                 | 0-07-0258-0.01         | v6.0.0.668 pl 6.6.0.236                          |
| 22 | BlackBerry 9800 Torch      | F           | ✓                 | 0-07-0258-0.01         | v6.0.0.534 pl 6.6.0.200                          |
| 23 | BlackBerry 9860 Torch      | E           | ✓                 | 0-07-0258-0.01         | v7.1.0.746 pl 5.1.0.546                          |
| 24 | BlackBerry 9900 Bold Touch | E           | ✓                 | 0-07-0258-0.01         | v7.0.0.585(platform 5.0.0.734)                   |
| 25 | BlackBerry Q5              | A'          | ✓                 | 0-07-0258-0.01         | v10.2.1.537                                      |
| 26 | BlackBerry Q10             | E           | ✓                 | 0-07-0258-0.01         | v10.2.1.3175                                     |
| 27 | BlackBerry Z10             | A'          | ✓                 | 0-07-0258-0.01         | v10.2.1.2102                                     |
| 28 | BlackBerry Z30             | A'          | ✓                 | 0-07-0258-0.01         | 10.2.1.3062                                      |
| 29 | HTC 7 Mozart               | E           | ✓                 | 0-07-0258-0.01         | windows phone 7.5radio 5.71.09.02a_22.51.50.21u  |
| 30 | HTC 7 Pro                  | F           | ✓                 | 0-07-0258-0.01         | windows phone 7.5radio 5.71.09.02a_22.51.50.21u  |
| 31 | HTC Desire S               | E           | ✓                 | 0-07-0258-0.01         | android os 2.3.5 2.10.401.8                      |
| 32 | HTC Desire X               | E           | ✓                 | 0-07-0258-0.01         | android os 4.1.1sw. nr. 2.23.118.2               |
| 33 | HTC Desire Z               | F           | ✓                 | 0-07-0258-0.01         | android os 2.3.3sw. nr. 2.42.405.5               |
| 34 | HTC Desire 310             | A'          | ✓                 | 0-07-0258-0.01         | android os 4.2.2sw. nr. 1.00.118.4               |
| 35 | HTC EVO 3D X515m           | A'          | ✓                 | 0-07-0258-0.01         | android os 4.0.3sw. nr. 3.28.401.1               |
| 36 | HTC Incredible S           | A'          | ✓                 | 0-07-0258-0.01         | android os 4.0.4sw. nr. 4.10.405.1               |
| 37 | HTC Legend                 | E           | ✓                 | 0-07-0258-0.01         | android os 2.2sw. nr. 3.14.161.1                 |
| 38 | HTC Magic                  | F           | ✓                 | 0-07-0258-0.02         | 1.5  |
| 39 | HTC One                    | A'          | ✓                 | 0-07-0258-0.01         | android 4.2.24.20.111.21                         |
| 40 | HTC One S                  | A'          | ✓                 | 0-07-0258-0.01         | android 4.1.13.16.111.10                         |

BURY Technologies UK Enquiries Tel. +44 (0)1489 881 118  
E-mail: [infoline@bury.com](mailto:infoline@bury.com), Internet: [www.bury.com](http://www.bury.com)

- ✓ working
- ✓ \* Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet2nd>
- ✓ 1 Only from phone
- ✓ \*\* Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet3rd>
- ✓ 2 Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch) <http://www.bury.com/blackberrypatch/>

*The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.*

| No | Phone                              | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comments   |
|----|------------------------------------|-------------|-------------------|------------------------|--|
| 41 | HTC One V                          | A'          | ✓                 | 0-07-0258-0.01         | android 4.0.32.22.111.10                           |
| 42 | HTC Sensation                      | A'          | ✓                 | 0-07-0258-0.01         | android os 4.0.3sw. nr. 3.33.111.51                |
| 43 | HTC Touch2                         | E           | ✓                 | 0-07-0258-0.02         | 1.28.407.4 (66092)                                 |
| 44 | HTC Touch DIAMOND 2                | F           | ✓                 | 0-07-0258-0.02         | radio 1.19.407.1 (51489) ger                       |
| 45 | HTC Touch Dual                     | F           | ✓                 | 0-07-0258-0.02         | 1.31.407.09radio 1.58.16.27                        |
| 46 | HTC Touch HD                       | F           | ✓                 | 0-07-0258-0.02         | rom: 1.14.407.3 (22273) ger                        |
| 47 | HTC HD mini                        | E           | ✓                 | 0-07-0258-0.01         | rom: 1.36.479.1 (94538) wwe                        |
| 48 | HTC HD2                            | A'          | ✓                 | 0-07-0258-0.01         | 3.14.407.2 (04666) ger                             |
| 49 | HTC HD7                            | A'          | ✓                 | 0-07-0258-0.01         | windows phone 7.5radio sw:5.71.09.02a_22.51.50.21u |
| 50 | HTC Touch Pro2                     | B           | ✓                 | 0-07-0258-0.02         | radio 2.07.407.1 (80303) ger                       |
| 51 | HTC Wildfire                       | E           | ✓                 | 0-07-0258-0.01         | android 2.2.12.24.162.1                            |
| 52 | HTC Windows Phone 8X               | A'          | ✓                 | 0-07-0258-0.01         | windows phone 8radio sw:1.14b.32.19.06_15.42.32.19 |
| 53 | HUAWEI Ascend P1 U9200             | A'          | ✓                 | 0-07-0258-0.01         | android 4.0.3u9200-1v100r001c00b219                |
| 54 | LG E960 Nexus 4                    | A'          | ✓                 | 0-07-0258-0.01         | android 4.4.3ktu84l                                |
| 55 | LG Nexus 5                         | A'          | ✓                 | 0-07-0258-0.01         | android 4.4.4ktu84p                                |
| 56 | LG G2 D802                         | A'          | ✓                 | 0-07-0258-0.01         | android 4.2.2d80210a-262-01                        |
| 57 | LG KM 900 Arena                    | E           |                   |                        | km900at_v10t                                       |
| 58 | LG P710 Optimus L7 II              | A'          | ✓                 | 0-07-0258-0.01         | android 4.1.2 sw lg-p71010e-eur-xx                 |
| 59 | LG P760 Optimus L9                 | A'          | ✓                 | 0-07-0258-0.01         | android 4.1.2 sw lg-p76020c-eur-xx                 |
| 60 | LG P880 Optimus 4X HD              | A'          | ✓                 | 0-07-0258-0.01         | android 4.1.2 sw lg-p88020c-232-10                 |
| 61 | LG P970                            | A'          | ✓                 | 0-07-0258-0.01         | android 2.3.4sw lg-p970-v20h                       |
| 62 | LG Optimus 2X (P990 Optimus Speed) | A'          | ✓                 | 0-07-0258-0.01         | android 2.2.2 sw lge lgp990-v10e                   |
| 63 | Motorola DEFY (MB525)              | F           | ✓                 | 0-07-0258-0.01         | 34.906.1.mb525.t-mobile.en.de                      |
| 64 | Motorola DEFY+ (MB526)             | F           | ✓                 | 0-07-0258-0.01         | android 2.3.645.0.2310.mb526.retail.en.de          |
| 65 | Motorola Milestone                 | F           | ✓                 | 0-07-0258-0.01         | android 2.2.1                                      |
| 66 | Motorola Motoluxe (XT615)          | E           | ✓                 | 0-07-0258-0.01         | android 2.3.7nk: 1_67c_4035                        |
| 67 | Motorola RAZR i XT890              | A'          | ✓                 | 0-07-0258-0.01         | android 4.1.29.8.21-50_smi-26.1358455837           |
| 68 | Nokia 208.1                        | E           |                   |                        | v06.01   |
| 69 | Nokia 500                          | E           |                   |                        | symbian belle111.020.0059                          |
| 70 | Nokia 515                          | E           |                   |                        | v 07.01  |
| 71 | Nokia Asha 300                     | E           |                   |                        | v 07.57  |
| 72 | Nokia Asha 311                     | E           | ✓                 | 0-07-0258-0.01         | v 05.92  |
| 73 | Nokia C2-01                        | E           | ✓                 | 0-07-0258-0.04         | v 11.40  |
| 74 | Nokia C3-00                        | E           | ✓                 | 0-07-0258-0.04         | v 08.63  |
| 75 | Nokia C3-01 Touch and Type         | E           |                   |                        | v 07.15  |
| 76 | Nokia C5-00 5MP                    | E           |                   |                        | v 073.001  |
| 77 | Nokia C5-03                        | E           |                   |                        | v 23.0.015   |
| 78 | Nokia C6                           | F           |                   |                        | v 42.0.004   |
| 79 | Nokia C7-00                        | E           |                   |                        | v 012.003  |
| 80 | Nokia E5-00                        | E           | ✓                 | 0-07-0258-0.04         | v 071.003  |

BURY Technologies UK Enquiries Tel. +44 (0)1489 881 118  
E-mail: [infoline@bury.com](mailto:infoline@bury.com), Internet: [www.bury.com](http://www.bury.com)

- ✓ working
- ✓ \* Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet2nd>
- ✓ 1 Only from phone
- ✓ \*\* Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet3rd>
- ✓ 2 Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch) <http://www.bury.com/blackberrypatch/>

*The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.*

| No  | Phone                           | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comments |
|-----|---------------------------------|-------------|-------------------|------------------------|--|
| 81  | Nokia E6-00                     | E           | ✓                 | 0-07-0258-0.01         | symbian bellev 111.140.0058                      |
| 82  | Nokia E7-00                     | A'          |                   |                        | symbian bellev 111.030.0609                      |
| 83  | Nokia E72                       | E           |                   |                        | 081.003  |
| 84  | Nokia Lumia 520                 | A'          | ✓                 | 0-07-0258-0.01         | windows phone 8.0sw 2.0.242020.8                 |
| 85  | Nokia Lumia 610                 | F           | ✓                 | 0-07-0258-0.01         | windows phone 7.5radio sw:1.0.66.00              |
| 86  | Nokia Lumia 625                 | A'          | ✓                 | 0-07-0258-0.01         | windows phone 8.0radio sw:3.2.28038.7            |
| 87  | Nokia Lumia 820                 | A'          | ✓                 | 0-07-0258-0.01         | windows phone 8.0radio sw:1.0.202158.3           |
| 88  | Nokia Lumia 900                 | A'          | ✓                 | 0-07-0258-0.01         | windows phone 7.5radio sw:2.1.75.25              |
| 89  | Nokia Lumia 920                 | A'          | ✓                 | 0-07-0258-0.01         | windows phone 8.0radio sw:1.0.202158.3           |
| 90  | Nokia Lumia 925                 | A'          | ✓                 | 0-07-0258-0.01         | windows phone 8.0radio sw:3.2.04033.1            |
| 91  | Nokia Lumia 1020 (909)          | A'          | ✓                 | 0-07-0258-0.01         | windows phone 8.0radio sw:3.2.04047.1            |
| 92  | Nokia N8                        | F           | ✓                 | 0-07-0258-0.01         | symbian bellev 111.040.1511                      |
| 93  | Nokia N9                        | E           | ✓                 | 0-07-0258-0.01         | v 40.2012.21-3.342.01.1_pr_342                   |
| 94  | Nokia N78                       | F           | ✓                 | 0-07-0258-0.04         | v 12.26  |
| 95  | Nokia N79                       | F           | ✓                 | 0-07-0258-0.04         | v 11.049   |
| 96  | Nokia N97                       | F           | ✓                 | 0-07-0258-0.01         | v 22.0.110                                       |
| 97  | Nokia N900                      | F           | ✓                 | 0-07-0258-0.01         | v21.2011.38-1                                    |
| 98  | Nokia X6                        | F           | ✓                 | 0-07-0258-0.01         | v 40.0.002                                       |
| 99  | Nokia X7-00                     | A'          |                   |                        | symbian bellev 111.040.1511                      |
| 100 | Samsung B2100                   | F           |                   |                        | b2100xxh1  |
| 101 | Samsung B2700                   | F           |                   |                        | b2700xxib2                                       |
| 102 | Samsung B7330 OmniaPro          | E           | ✓                 | 0-07-0258-0.01         | b7330xxig2                                       |
| 103 | Samsung B7610 OmniaPro          | F           | ✓                 | 0-07-0258-0.01         | b7610xxik2                                       |
| 104 | Samsung C6625                   | E           |                   |                        | c6625buie1                                       |
| 105 | Samsung G386F Galaxy Core LTE   | A'          | ✓                 | 0-07-0258-0.01         | android 4.2.2jdtq39.g386fxuanb4                  |
| 106 | Samsung G800F Galaxy S5 mini    | A'          | ✓                 | 0-07-0258-0.01         | android 4.4.2kot49h.g800fxu1anj2                 |
| 107 | Samsung G900F Galaxy S5         | A'          | ✓                 | 0-07-0258-0.01         | android 4.4.2kot49h.g900fxu1ance                 |
| 108 | Samsung i7500 Galaxy            | E           | ✓                 | 0-07-0258-0.01         | i7500xxmc3                                       |
| 109 | Samsung I8000 Omnia II          | F           | ✓                 | 0-07-0258-0.01         | i8000xxii6                                       |
| 110 | Samsung I8150 Galaxy W          | E           | ✓                 | 0-07-0258-0.01         | android 2.3.6i8150xxlmi                          |
| 111 | Samsung I8160 Galaxy Ace 2      | E           | ✓                 | 0-07-0258-0.01         | i8160xxll2                                       |
| 112 | Samsung I8190 Galaxy S III mini | A'          | ✓                 | 0-07-0258-0.01         | android 4.1.2i8190xxamg4                         |
| 113 | Samsung i8320 Vodafone 360 H1   | F           | ✓                 | 0-07-0258-0.01         | i8320bulk1                                       |
| 114 | Samsung I8700 Omnia 7           | A'          |                   |                        | windows phone 7.5radio sw:2424.13.5.1            |
| 115 | Samsung I8750 Ativ S            | A'          | ✓                 | 0-07-0258-0.01         | windows phone 8.0radio sw: 2424.13.5.1           |
| 116 | Samsung i8910 Omnia HD          | B           | ✓                 | 0-07-0258-0.01         | i8910xxja1                                       |
| 117 | Samsung I9000 Galaxy S          | A'          | ✓                 | 0-07-0258-0.01         | i9000xxjw4                                       |
| 118 | Samsung I9001 Galaxy S Plus     | A'          | ✓                 | 0-07-0258-0.01         | android 2.3.6i9001xxkpo                          |
| 119 | Samsung I9100 Galaxy S II       | A'          | ✓                 | 0-07-0258-0.01         | android 4.1.2i9100xxms2                          |
| 120 | Samsung I9195 Galaxy S 4 mini   | A'          | ✓                 | 0-07-0258-0.01         | android 4.2.2 i9195xxubmj7                       |

BURY Technologies UK Enquiries Tel. +44 (0)1489 881 118  
E-mail: [infoline@bury.com](mailto:infoline@bury.com), Internet: [www.bury.com](http://www.bury.com)

- ✓ working
- ✓ \* Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet2nd>
- ✓ 1 Only from phone
- ✓ \*\* Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet3rd>
- ✓ 2 Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch) <http://www.bury.com/blackberrypatch/>

*The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.*

| No  | Phone                                 | Set of tips | Charger available | Article code (Charger) | Version of phone software used to test/ Comments |
|-----|---------------------------------------|-------------|-------------------|------------------------|--|
| 121 | Samsung I9300 Galaxy S III            | A'          | ✓                 | 0-07-0258-0.01         | android 4.3i9300xxugna8                          |
| 122 | Samsung I9505 Galaxy S4               | A'          | ✓                 | 0-07-0258-0.01         | android 4.2.2 jdq39.i9505xxuamdm                 |
| 123 | Samsung S5230 Avilla                  | E           |                   |                        | s5230bvie3                                       |
| 124 | Samsung S5260 Star II                 | E           |                   |                        | s5260xxkc4                                       |
| 125 | Samsung S5570i Galaxy Mini            | F           | ✓                 | 0-07-0258-0.01         | android 2.3.6 sw: s5570ixld6                     |
| 126 | Samsung S5690 Galaxy Xcover           | A'          |                   |                        | android 2.3.6 sw: s5690xll1                      |
| 127 | Samsung S6500 Galaxy mini 2           | E           | ✓                 | 0-07-0258-0.01         | android 2.3.6 sw: s6500xllk2                     |
| 128 | Samsung S7220                         | E           | ✓                 | 0-07-0258-0.01         | s7220xxib7                                       |
| 129 | Samsung S7500 Galaxy Ace Plus         | E           | ✓                 | 0-07-0258-0.01         | android 2.3.6 s7500xxmc2                         |
| 130 | Samsung S7560 Galaxy Trend (Ace II X) | A'          | ✓                 | 0-07-0258-0.01         | android 4.0.4s7560xxamea                         |
| 131 | Samsung S7710 Galaxy Xcover 2         | A'          |                   |                        | android 4.1.2 s7710xxamb5                        |
| 132 | Samsung S8000 Jet                     | E           | ✓                 | 0-07-0258-0.01         | s8000xxif5                                       |
| 133 | Samsung S8300V                        | E           | ✓                 | 0-07-0258-0.01         | s8300buic6                                       |
| 134 | Samsung S8500 Wave                    | E           | ✓                 | 0-07-0258-0.01         | s8500xxla1                                       |
| 135 | Samsung S8530 Wave II                 | A'          |                   |                        | s8530xxla1                                       |
| 136 | Samsung S8600 Wave 3                  | A'          | ✓                 | 0-07-0258-0.01         | s8600xxld1                                       |
| 137 | Samsung SGH-i900 OMNIA 8GB            | F           |                   |                        | i900xxib2  |
| 138 | Samsung Xcover 271 (B2710)            | F           | ✓                 | 0-07-0258-0.01         | b2710bojj3                                       |
| 139 | SONY Xperia E (C1505)                 | E           | ✓                 | 0-07-0258-0.01         | android 4.1.1 sw 11.3.a.2.23                     |
| 140 | SONY Xperia J (ST26i)                 | A'          | ✓                 | 0-07-0258-0.01         | android 4.1.2 sw 11.2.a.0.31                     |
| 141 | SONY Xperia P (LT22i)                 | A'          |                   |                        | android 4.1.2 sw 6.2.a.1.100                     |
| 142 | SONY Xperia S (LT26)                  | A'          | ✓                 | 0-07-0258-0.01         | android 4.0.4 sw 6.1.a.2.45                      |
| 143 | SONY Xperia SP (C5303)                | A'          | ✓                 | 0-07-0258-0.01         | android 4.3 sw 12.1.a.1.201                      |
| 144 | SONY Xperia T (LT30p)                 | A'          | ✓                 | 0-07-0258-0.01         | android 4.3 sw 9.2.a.1.205                       |
| 145 | SONY Xperia U (ST25i)                 | E           |                   |                        | android 4.0.4 sw 6.1.1.b.1.10                    |
| 146 | SONY Xperia Z (C6603)                 |             |                   |                        | android 4.2.2 sw 10.3.1.a.2.87                   |
| 147 | SONY Xperia Z1 Compact (D5503)        | A'          |                   |                        | android 4.4.4 sw 14.4.a.0.118                    |
| 148 | Sony Ericsson Aino                    | F           | ✓                 | 0-07-0258-0.05         | r7ba084  |
| 149 | Sony Ericsson C902                    | E           | ✓                 | 0-07-0258-0.05         | r3e004   |
| 150 | Sony Ericsson Elm                     | E           | ✓                 | 0-07-0258-0.05         | r7ca061  |
| 151 | Sony Ericsson Satio (Idou)            | F           | ✓                 | 0-07-0258-0.05         | r1bb041  |
| 152 | Sony Ericsson Xperia Arc (LT15i)      | A'          |                   |                        | android 4.0.4 sw 4.1.b.0.587                     |
| 153 | Sony Ericsson Xperia Arc S (LT18i)    | A'          |                   |                        | android 4.0.4 sw 4.1.b.0.587                     |
| 154 | Sony Ericsson Xperia neo V (MT11i)    | E           |                   |                        | android 4.0.4 sw 4.1.b.0.587                     |
| 155 | Sony Ericsson Xperia ray              | E           |                   |                        | android 4.0.4 sw 4.1.b.0.587                     |
| 156 | Sony Ericsson Xperia X10              | A'          |                   |                        | android 2.3.33.0.1.g.0.75                        |

BURY Technologies UK Enquiries Tel. +44 (0)1489 881 118  
E-mail: [infoline@bury.com](mailto:infoline@bury.com), Internet: [www.bury.com](http://www.bury.com)

- ✓ working
- ✓ \* Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet2nd>
- ✓ 1 Only from phone
- ✓ \*\* Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet3rd>
- ✓ 2 Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch) <http://www.bury.com/blackberrypatch/>

*The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.*