

No	Phone	Set of tips	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
1	Apple iPhone 6	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.08	9.3.2 (13F69)
2	Apple iPhone 6s	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.08	10.0.1 (14A403)
3	Apple iPhone 6 Plus	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.08	9.3.2 (13F69)
4	Apple iPhone 6s Plus	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.08	9.3.2 (13F69)
5	Apple iPhone 7	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.08	10.0.3 (14A551)
6	Apple iPhone 7 Plus	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.08	10.0.3 (14A551)
6	BlackBerry Leap (STR100-1)	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	BB OS 10.3.2.2836
7	BlackBerry Priv STV100-4	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 AAF518
8	BlackBerry Q20 Classic	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	BB OS v10.3.2.2836
9	BlackBerry Z10	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	BB OS v10.3.2.2836
10	BlackBerry Z30	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	BB OS 10.3.2.2836
11	HTC Desire 310	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android OS 4.2.2 sw. Nr. 1.00.118.4
12	HTC One	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 4.2.2 4.20.111.21
13	HTC One M9	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0 3.35.111.14
14	HTC ONE mini	E	✓	✓	✓	✓ ¹			Android 4.0.3 2.22.111.1
15	HTC One Max	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 5.0.2 4.14.111.11
16	HTC One X								Android 4.0.4 sw. Nr. 2.17.401.2
17	HTC Windows Phone 8X	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	WinPhone 8Radio sw:1.20b.32.19.04_15.67b.32.19
18	HUAWEI Ascend P1 U9200	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 4.0.3 U9200-1V100R001C00B219
19	HUAWEI Mate 8 (NXT-L29)	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0 NXT-L29C432B192
20	HUAWEI Mate 9 (MHA-L29)	A'	✓	✓	✓	✓ ¹			Android 7.0 MHA-L29C432B156
21	HUAWEI P9 (EVA-L09)	A'	✓	✓	✓	✓ ¹			Android 6.0 EVA-L09C432B170
22	HUAWEI P 10 (VTR-L29)	A'	✓	✓	✓	✓ ¹			Android 7.0 VTR-L29C432B112
23	LG E960 Nexus 4	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 5.1.1 LMY48T
24	LG Nexus 5	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 MOB30M
25	LG Nexus 5X	A'	✓	✓	✓	✓ ¹			Android 7.0 NRD90R
26	LG G2 D802	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 4.4.2 KOT49I.D80220d
27	LG G3 (D855)	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 5.0 V21a-260-01
28	LG G4 (H815)	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0 V20d-260-02
29	LG G5 (H850)	A'	✓	✓	✓	✓ ¹			Android 6.0.1 V10d-EUR-XX
30	LG G6 (H870)	A'	✓	✓	✓	✓ ¹			Android 7.0 V10f-EUR-XX
31	LG G Flex (D955)	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 4.4.2 KOT49I.D95520b
32	LG P760 Optimus L9	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 4.1.2 P76020h-EUR-XX
33	LG P880 Optimus 4X HD	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 4.1.2 SW LG-P88020b-232-10
34	LG V10 (H961N)	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 SW V10a-EUR_XX
35	LG X Power (K220)	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 SW V10a-EUR_XX
36	Microsoft Lumia 535	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	WP 8.1 Update 02074.00000.15234.28006
37	Microsoft Lumia 950	A'	✓	✓	✓	✓ ¹			Win Phone 10Mobile 01078.00038.16025.39025
38	Motorola Nexus 6	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 NK: MOB31E
39	Nokia Lumia 625	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Win Phone 8.0 Radio sw:3.2.28060.7
40	Nokia Lumia 635	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	WinPhone8.1 Update Radio sw:201c1.00401.0001
41	Nokia Lumia 900	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	WinPhone 7.5 Radio sw:2.1.75.25
42	Nokia Lumia 920	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	WinPhone 8.0 Radio sw:1.0.202158.3

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓¹ only from phone

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Set of tips	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
43	Nokia Lumia 925	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	WinPhone 8.0 Radio sw:3.2.04033.1
44	Nokia Lumia 930	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	WinPhone 8.1 Update 02540.00019.14484.37006
45	Nokia Lumia 909/1020	F	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	WinPhone 8.1 Update 3051.50009.1451.1010
46	Nokia Lumia 909/1020	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	WinPhone 8.1 Update SW 02540.00019.15235.40004
47	OnePlus 2 (ONE A2003)	A'	✓	✓	✓	✓ ¹			Android 6.0.1 ONE A2003_24_161227
48	Samsung A510F Galaxy A5 (2016)	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 5.1.1 LMY47X.A510FXXS2APE2
49	Samsung A520F Galaxy A5 (2017)	A'	✓	✓	✓	✓ ¹			Android 6.0.1 sw MMB29K.A520FXXU1APLP
50	Samsung G900F Galaxy S5	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G900FXXU1CPPEM
51	Samsung G903 F Galaxy S5 Neo	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G903FXXU1BPF4
52	Samsung G920F Galaxy S6	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G920FXXU3DPFB
53	Samsung G925F Galaxy S6 edge	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G925FXXU3DPCA
54	Samsung G930F Galaxy S7	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G930FXXU1APEQ
55	Samsung G935F Galaxy S7 edge	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G935FXXU1APD1
56	Samsung G950F Galaxy S8	E	✓	✓	✓	✓ ¹			Android 7.0 NRD90M.G950FXXU1AQDG
57	Samsung G955F Galaxy S8+	A'	✓	✓	✓	✓ ¹			Android 7.0 NRD90M.G955FXXU1AQDG
52	Samsung I8750 Ativ S	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Windows Phone 8.1 Update 2424.15.3.2
53	Samsung I9300 Galaxy S III	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 4.3 JSS15J.I9300XXUGNG3
54	Samsung I9305 Galaxy S III Lte	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 4.4.4 KTU84P.I9305XXUFOA1
55	Samsung I9505 Galaxy S4	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 4.4.2 I9505XXUFNB8
56	Samsung J320F Galaxy J3 (2016)	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 5.1.1 LMY47V.J320FXXS0AQA1
57	Samsung J510 FN Galaxy J5(2016)	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 MMB29M.J510FNXXU2APK6
58	Samsung N7000 Galaxy Note	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 4.1.2 JZO54K.N7000XLT4
59	Samsung N9005 Galaxy Note 3	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 5.0 LRX21V.N9005XXUGBOK6
60	Samsung N910F Galaxy Note 4	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 MMB29M.N910FXXU1DPI1
61	Samsung N915FY Galaxy Note Edge	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 MMB29M.N915FYXXS1DPI1
62	SONY Xperia S (LT26)	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 4.1.2 6.2.B.1.96
63	SONY Xperia SP (C5303)	E	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 4.3 sw 12.1.A.1.201
64	SONY Xperia XZ (F8331)	A'	✓	✓	✓	✓ ¹			Android 7.0 sw 39.2.A.0.417
65	SONY Xperia Z3 (D6603)	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 5.1.1 23.4.A.1.264
66	SONY Xperia Z3+ (C6553)	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 32.2.A.0.305
67	SONY Xperia Z3 Compact (D5803)	E	✓	✓	✓	✓ ¹			Android 6.0.1 23.5.A.1.29
68	SONY Xperia Z5 (E6653)	A'	✓	✓	✓	✓ ¹	✓	0-07-0258-0.01	Android 6.0.1 32.2.A.0.253

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓¹ only from phone

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.