

No	Phone	Set of tips	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
1	Apple iPhone	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.07	3.0 (7A341)
2	Apple iPhone 3G	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.07	4.0.1 (8A306)
3	Apple iPhone 3GS	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.07	6.0 (10A403)
4	Apple iPhone 4	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.07	7.0 (11A465)
5	Apple iPhone 4S	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.07	7.0 (11A465)
6	Apple iPhone 5	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.08	7.0 (11A465)
7	Apple iPhone 5c	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.08	7.0.2 (11A501)
8	Apple iPhone 5s	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.08	7.0.3 (11B511)
9	Apple iPhone SE	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.08	9.3.2 (13F69)
10	BlackBerry 8300 Curve	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	V4.2.2.27
11	BlackBerry 8310 Curve	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	V4.2.2.146
12	BlackBerry 8520 Curve	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V4.6.1.286 PI 4.2.0.122
13	BlackBerry 8800	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	V4.2.1.43
14	BlackBerry 8900 Curve	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V5.0.0.411 PL5.2.0.31
15	BlackBerry 9000 Bold	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	V4.6.0.111 (Platform 4.0.0.129)
16	BlackBerry 9105 Pearl	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v5.0.0.623 (Platform 6.2.0.43)
17	BlackBerry 9300 Curve 3G	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v5.0.0.716 (Platform 6.3.0.13)
18	BlackBerry 9320 Curve	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v7.1.0.398 (Platform 9.49.0.31)
19	BlackBerry 9360 Curve	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v7.0.0.353 (Platform 8.0.0.388)
20	BlackBerry 9380 Curve	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v7.1.0.470 (Platform 9.32.0.108)
21	BlackBerry 9500 Storm	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v4.7.0.78 PI 4.0.0.98
22	BlackBerry 9520 Storm2	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V5.0.0.497 PI 4.2.0.220
23	BlackBerry 9630	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v4.7.1.20 PI 4.1.0.15
24	BlackBerry 9700 Bold	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v5.0.0.979 PI 5.1.0.177
25	BlackBerry 9780 Bold	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v6.0.0.359 PI 6.5.0.93
26	BlackBerry 9800 Torch	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v6.0.0.100 PI 6.4.0.47
27	BlackBerry 9810 Torch	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V7.0.0.261 PL 5.0.0.469
28	BlackBerry 9860 Torch	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V7.0.0.585 PL 5.0.0.734
29	BlackBerry 9900 Bold Touch	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v7.0.0.387 (Platform 5.0.0.572)
30	BlackBerry Q5	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v10.2.0.429
31	BlackBerry Q10	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v10.2.1.537
32	CAT (Caterpillar) B15	A	✓	✓	✓	✓ ₁			Android 4.1.2 1375548110
33	HTC 7 Mozart	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WinPhone 7 Radio 5.50.09.18_22.24.50.09U
34	HTC 7 Pro	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WinPhone 7 Radio 5.63.09.13_22.36.50.15U
35	HTC Desire	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 2.2 sw. Nr. 2.12.110.4
36	HTC Desire HD	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	sw. Nr. 2.50.405.2
37	HTC Desire S	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 2.3.3 1.47.401.4
38	HTC Desire X	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 4.1.1 sw. Nr. 2.23.118.2
39	HTC Desire Z	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 2.2.1 sw. Nr. 1.72.405.2
40	HTC EVO 3D X515m	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 2.3.4 sw. Nr. 1.20.401.2
41	HTC Incredible S	C	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 2.2.1 sw. Nr. 1.36.405.1
42	HTC Legend	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 2.1 sw. Nr. 1.23.161.1

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* (20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓₁ only from phone

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Set of tips	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
43	HTC Magic	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	1.5
44	HTC T-Mobile G1	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	FW: 1.1
45	HTC Hero / T-Mobile G2 Touch	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	FW: 1.5 1.0.0.A6288
46	HTC One S	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.1.1 3.16.111.5
47	HTC One V	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.0.3 2.22.111.1
48	HTC Sensation	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 2.3.4 sw. Nr. 1.45.111.2
49	HTC Tattoo	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	SW 1.67.405.6
50	HTC Touch2	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	1.28.407.4 (66092)
51	HTC Touch DIAMOND 2	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	Radio 1.19.407.1 (51489) GER
52	HTC Touch HD	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	ROM: 1.14.407.3 (22273) GER
53	HTC HD mini	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	ROM: 1.36.479.1 (94538) WWE
54	HTC HD2	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	1.43.111.2 (70315) GER
55	HTC HD7	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WinPhone7 Radio sw:5.51.09.06a_22.30.50.09U
56	HTC Touch Pro	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	1.60.161.1 WWE
57	HTC Touch Pro2	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	Radio 1.19.407.1 (51489) GER
58	HTC Wildfire	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.2.1 2.24.162.1
59	LG BL20 New Chocolate	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	BL20 V10d
60	LG BL40 New Chocolate	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	BL40-MSM76XX-V10a-SEP-21-2009-XX
61	LG G2 mini LTE (D620r)	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.4.2 V10c-260-01
62	LG GT500	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	GT500-V10i
63	LG KE 850 PRADA	C	✓	✓	✓	✓ ₁			KE850P40-EUR-V10n-XXX-XX MAY 07 2007
64	LG KE 970	A	✓	✓	✓	✓ ₁			KE970P40-EUR-V10n-XXX-XX APR 07 2007
65	LG KF 750 Secret	A	✓	✓	✓	✓ ₁			KF750-V10a-24042008
66	LG KM 900 Arena	C	✓	✓	✓	✓ ₁			KM900AT_V10t
67	LG KP500 Cookie	C	✓	✓	✓	✓ ₁			KP500AT_V10d
68	LG KU 990	C	✓	✓	✓	✓ ₁			n.a.
69	LG P710 Optimus L7 II	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.1.2 SW LG-P71010e-EUR-XX
70	LG P970	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.2.2 SW LG-P970-V10b
71	LG Optimus2X P990 Optimus-Speed	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.2.2 SW LGE LGP990-V10e
72	Motorola DEFY (MB525)	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.1-update1 R26LD?U?83.39.24I
73	Motorola Milestone	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	2,0
74	Motorola Milestone 2	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.2
75	Motorola Motoluxe (XT615)	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.3.7 NK: 1_67C_4035
76	Motorola RAZR i XT890	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.1.2 9.8.21-50_SMI-26.1358455837
77	Nokia 113	C	✓	✓	✓	✓ ₁			V03.32
78	Nokia 208.1	A	✓	✓	✓	✓ ₁			V06.01
79	Nokia 500	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Symbian Belle 111.020.0059
80	Nokia 515	A	✓	✓	✓	✓ ₁			V 07.01
81	Nokia 2730 classic	D	✓	✓	✓	✓ ₁			V 10.40
82	Nokia 3720 classic	D	✓	✓	✓	✓ ₁			V09.10

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓₁ only from phone

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Set of tips	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
83	Nokia 5530 XpressMusic	C	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	V 11.0.054
84	Nokia 5630 XpressMusic	C	✓	✓	✓	✓ ₁			V 012.008
85	Nokia 5730 XpressMusic	B	✓	✓	✓	✓ ₁			100.48.122
86	Nokia 5800 XpressMusic	B	✓	✓	✓	✓ ₁			V 20.0.012
87	Nokia 6124c	D	✓	✓	✓	✓ ₁			V04.34
88	Nokia 6220 Classic	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	V03.23
89	Nokia 6300	C	✓	✓	✓	✓ ₁			V 04.70
90	Nokia 6300i	C	✓	✓	✓	✓ ₁			V03.41
91	Nokia 6303 classic	C	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	V 08.90
92	Nokia 6500c	C	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	V 03.21
93	Nokia 6700 classic	C	✓	✓	✓	✓ ₁			V 07.60
94	Nokia 6710 Navigator	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	021.013
95	Nokia 7900 Prism	C	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	V03.40
96	Nokia 8600 Luna	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	V03.52
97	Nokia Asha 300	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	V 06.97
98	Nokia Asha 311	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V 05.92
99	Nokia C2-01	D	✓	✓	✓	✓ ₁			V 11.00
100	Nokia C3-00	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	V 08.63
101	Nokia C3-01 Touch and Type	C	✓	✓	✓	✓ ₁			V 05.65
102	Nokia C5	C	✓	✓	✓	✓ ₁			V 031.022
103	Nokia C5-00 5MP	C	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V 073.001
104	Nokia C5-03	C	✓	✓	✓	✓ ₁			V 22.0.007
105	Nokia C6	D	✓	✓	✓	✓ ₁			V 42.0.004
106	Nokia C7-00	A	✓	✓	✓	✓ ₁			V 012.003
107	Nokia E5-00	C	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	V 071.003
108	Nokia E6-00	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V 021.014
109	Nokia E7-00	A	✓	✓	✓	✓ ₁			V 022.014
110	Nokia E51	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	411.34.001
111	Nokia E52	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	033.002
112	Nokia E55	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	034.001
113	Nokia E66	C	✓	✓	✓	✓ ₁			V 102.07.81
114	Nokia E71	C	✓	✓	✓	✓ ₁			V 007.49.4
115	Nokia E72	A	✓	✓	✓	✓ ₁			081.003
116	Nokia E75	D	✓	✓	✓	✓ ₁			110.48.125
117	Nokia Lumia 520	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WinPhone 8.0 SW 2.0.242020.8
118	Nokia Lumia 610	A	✓	✓	✓	✓ ₁			WinPhone 7.5 Radio sw:1.0.66.00
119	Nokia Lumia 800	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WinPhone 7.5 Radio sw:1.6.00.24
120	Nokia Lumia 820	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WinPhone 8.0 Radio sw:1.0.202075.3
121	Nokia Lumia 900	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Windows Phone 7.5 Radio sw:2.1.75.25
122	Nokia N8	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Symbian Belle V 111.030.0609
123	Nokia N9	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V 20.2011.40-4.341.01.1_PR_341

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓₁ only from phone

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Set of tips	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
124	Nokia N78	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	V 12.26
125	Nokia N79	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	V 11.049
126	Nokia N82	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	V 10.0.046
127	Nokia N85	D	✓	✓	✓	✓ ₁			V 11.047
128	Nokia N96	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	10.024
129	Nokia N97	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V 20.0.019
130	Nokia N97 mini	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v 30.0.004
131	Nokia N900	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V 3.2010.02-8
132	Nokia X3	D	✓	✓	✓	✓ ₁			V 03.60
133	Nokia X6	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V 40.0.002
134	Nokia X7-00	A	✓	✓	✓	✓ ₁			Symbian Belle V 111.030.0609
135	Palm Pre	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V1.0
136	Samsung Ace S5830	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.3.3 sw S5830XWKP5
137	Samsung B2100	B	✓	✓	✓	✓ ₁			B2100XXHL1
138	Samsung B2700	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	B2700XXIB2
139	Samsung B7330 OmniaPro	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	B7330XXIG2
140	Samsung B7610 OmniaPro	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	B7610XXIK2
141	Samsung C6625	A	✓	✓	✓	✓ ₁			C6625BUIE1
142	Samsung E2121B	C	✓	✓	✓	✓ ₁			E2121BXXKC1
143	Samsung i7500 Galaxy	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	I7500XXII5
144	Samsung I8150 Galaxy W	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	I8150XXLMB
145	Samsung I8160 Galaxy Ace 2	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	I8160XXLI2
146	Samsung I8190 Galaxy S III mini	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.1.2 I8190XXAMG4
147	Samsung i8320 Vodafone 360 H1	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	i8320BUJK1
148	Samsung I8700 Omnia 7	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Windows Phone 7 Radio sw:2424.10.10.3
149	Samsung i8910 Omnia HD	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	I8910XXIE7
150	Samsung I9000 Galaxy S	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	I9000XXJVO
151	Samsung I9001 Galaxy S Plus	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.3.6 I9001XXKPK
152	Samsung I9100 Galaxy S II	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	I9100XXKE7
153	Samsung I9195 Galaxy S 4 mini	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.2.2 I9195XXUBM7
154	Samsung S3650 Corby	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	S3650XXII3
155	Samsung S5260 Star II	A	✓	✓	✓	✓ ₁			S5260XXKC4
156	Samsung S5360 Galaxy Y	A	✓	✓	✓	✓ ₁			Android 2.3.6 sw: S5360XXLE1
157	Samsung S5570i Galaxy Mini	A	✓	✓	✓	✓ ₁			Android 2.3.6 sw: S5570IXXLD6
158	Samsung S5690 Galaxy Xcover	A	✓	✓	✓	✓ ₁			Android 2.3.6 sw: S5690XXLE5
159	Samsung S6500 Galaxy mini 2	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.3.6 sw: S6500XXLD2
160	Samsung S7500 Galaxy Ace Plus	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	S7500XXLH1
161	Samsung S7560 Galaxy Trend (Ace II X)	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.0.4 sw: S7560XXAMF1
162	Samsung S7580 Galaxy Trend Plus	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.2.2 JDQ39.S7580XXUBOA1
163	Samsung S7710 Galaxy Xcover 2	A	✓	✓	✓	✓ ₁			Android 4.1.2 sw: S7710XXAMB5
164	Samsung S8000 Jet	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	S8000XXIF5

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓₁ only from phone

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Phone	Set of tips	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone s REDIAL activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
165	Samsung S8300V	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	S8300BUIC6
166	Samsung S8500 Wave	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	S8500XXJ14
167	Samsung S8530 Wave II	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	S8530XXJKA
168	Samsung S8600 Wave 3	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	S8600XXLA1
169	Samsung SGH-F480	A	✓	✓	✓	✓ ₁			F480BOHE3
170	Samsung SGH-F700v	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	F700AMG38
171	Samsung SGH-U800	C	✓	✓	✓	✓ ₁			U800BRHL1
172	Samsung SGH-I900 OMNIA 16GB	A	✓	✓	✓	✓ ₁			i900BOHH2
173	SONY Xperia E (C1505)	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.1.1 sw 11.3.A.2.23
174	SONY Xperia J (ST26i)	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.1.2 sw 11.2.A.0.31
175	SONY Xperia M (C1905)	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.3 sw 15.4.A.1.9
176	SONY Xperia P (LT22i)	A	✓	✓	✓	✓ ₁			Android 4.0.4 sw 6.1.1.B.1.54
177	SONY Xperia Tipo (ST21i)	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.0.4 sw 11.0.A.22
178	SONY Xperia U (ST25i)	A	✓	✓	✓	✓ ₁			Android 4.0.4 sw 6.1.1.B.1.10
179	SONY Xperia Z1Compact (D5503)	A	✓	✓	✓	✓ ₁			Android 4.4.4 sw 14.4.A.0.118
180	SONY Xperia Z3Compact (D5803)	A	✓	✓	✓	✓ ₁			Android 6.0.1 sw 23.5.A.1.29
181	Sony Ericsson Aino	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R1BA049
182	Sony Ericsson C702	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R3AA054
183	Sony Ericsson C902	C	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R3BA035
184	Sony Ericsson C903	D	✓	✓	✓	✓ ₁			R1FA035
185	Sony Ericsson C905	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R1DA034
186	Sony Ericsson Elm	C	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R7CA061
187	Sony Ericsson G900	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	1.25.206.3 WWE
188	Sony Ericsson K550i	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R1JD001
189	Sony Ericsson K770i	A	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R8BA024
190	Sony Ericsson K850i	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R1FA035
191	Sony Ericsson Satio (Idou)	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R1BB041
192	Sony Ericsson W595i	C	✓	✓	✓	✓ ₁			R3EA031
193	Sony Ericsson W705	D	✓	✓	✓	✓ ₁			R1DA034
194	Sony Ericsson W890i	C	✓	✓	✓	✓ ₁			R1FA035
195	Sony Ericsson W950i	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R9C001
196	Sony Ericsson W995	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R1EA032
197	Sony Ericsson Vivaz	A	✓	✓	✓	✓ ₁			1224-4699_R2AK006
198	Sony Ericsson Xperia Arc (LT15i)	A	✓	✓	✓	✓ ₁			Android 2.3.4 sw 4.0.2.A.0.62
199	Sony Ericsson Xperia ray	A	✓	✓	✓	✓ ₁			Android 2.3.4 sw 4.0.2.A.0.69
200	Sony Ericsson Xperia X1	D	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	1.00.161.2
201	Sony Ericsson Xperia X2	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R1AA035
202	Sony Ericsson Xperia X8	A	✓	✓	✓	✓ ₁			Android 2.1-update1
203	Sony Ericsson Xperia X10	A	✓	✓	✓	✓ ₁			Android 2.3.3 3.0.1.G.0.75
204	Sony Ericsson Yari	D	✓	✓	✓	✓ ₁			R1BA049

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓₁ only from phone

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.