

Compatibility list CC 9056 Plus

Updated: 2020-12-15 / V. 59
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
1	Apple iPhone	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.07	3.0 (7A341)
2	Apple iPhone 3G	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.07	4.2.1 (8C148)
3	Apple iPhone 3GS	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.07	6.1.3 (10B329)
4	Apple iPhone 4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.07	7.0.4 (11B554a)
5	Apple iPhone 4S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.07	7.0.4 (11B554a)
6	Apple iPhone 5	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	8.1 (12B411)
7	Apple iPhone 5c	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	8.1 (12B411)
8	Apple iPhone 5s	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	8.1 (12B411)
9	Apple iPhone 6	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	8.0.2 (12A405)
10	Apple iPhone 6s	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	10.0.1 (14A403)
11	Apple iPhone 6 Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	8.0.2 (12A405)
12	Apple iPhone 6s Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	9.1 (13B143)
13	Apple iPhone 7	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	10.0.3 (14A551)
14	Apple iPhone 7 Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	10.0.3 (14A551)
15	Apple iPhone 8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	11.0.3 (15A432)
16	Apple iPhone 8 Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	11.0.3 (15A432)
17	Apple iPhone SE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	9.3.2 (13F69)
18	Apple iPhone X	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	11.1.2 (15B202)
19	Apple iPhone 11	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	13.1.2 (17A860)
20	Apple iPhone 12	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	14.3 (18C66)
21	Apple iPhone 12 mini	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	14.2.1 (18B121)
22	Apple iPhone 12 Pro	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	14.3 (18C66)
23	Apple iPhone 12 Pro Max	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.08	14.3 (18C66)
24	ASUS Solaris V1520	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	5.2.1620(Build 18125.0.4.2)
25	BlackBerry 8110 Pearl	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	V4.5.0.55
26	BlackBerry 8220 Pearl Flip	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v4.6.0.94
27	BlackBerry 8300 Curve	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	V4.5.0.182
28	BlackBerry 8310	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	V4.5.0.180

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓¹ only from phone
- ✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2020-12-15 / V. 59
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
29	BlackBerry 8520 Curve	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	V4.6.1.286 PI 4.2.0.122	
30	BlackBerry 8800	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	V4.5.1.174	
31	BlackBerry 9000 Bold	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	V4.6.0.40	
32	BlackBerry 9100 Pearl	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v5.0.0.696 (Platform 6.2.0.57)	
33	BlackBerry 9105 Pearl	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v5.0.0.696 (Platform 6.2.0.57)	
34	BlackBerry 9320 Curve	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v7.1.0.398 (Platform 9.49.0.31)	
35	BlackBerry 9360 Curve	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v7.1.0..234 (Platform 9.16.0.57)	
36	BlackBerry 9380 Curve	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v7.1.0.470 (Platform 9.32.0.108)	
37	BlackBerry 9500 Storm	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v4.7.0.41 PI 4.0.0.40	
38	BlackBerry 9520 Storm2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	V5.0.0.497 PI 4.2.0.220	
39	BlackBerry 9700 Bold	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v5.0.0.979 PI 5.1.0.178	
40	BlackBerry 9780 Bold	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v6.0.0.668 PI 6.6.0.236	
41	BlackBerry 9790 Bold	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v7.0.0.528	
42	BlackBerry 9800 Torch	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v6.0.0.534 PI 6.6.0.200	
43	BlackBerry 9810 Torch	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v7.1.0.342 PI 5.4.0.276	
44	BlackBerry 9860 Torch	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	V7.1.0.746	
45	BlackBerry 9900 Bold Touch	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v7.0.0.585 (Platform 5.0.0.734)	
46	BlackBerry Leap (STR100-1)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	BB OS 10.3.2.2836	
47	BlackBerry Passport (SQW100-1)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	BB OS 10.3.2.2836	
48	BlackBerry Priv STV100-4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		Android 6.0.1 AAF518	
49	BlackBerry Q5	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v10.2.0.429	
50	BlackBerry Q10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v10.2.1.537	
51	BlackBerry Q20 Classic	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v10.3.2.2836	
52	BlackBerry Z10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v10.2.0.429	
53	BlackBerry Z30	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	10.2.1.3062	
54	CAT (Caterpillar) B15	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		Android 4.1.2 1375548110	
55	HTC 7 Mozart	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win7.5 Radio5.71.09.02a_22.51.50.21U	
56	HTC 7 Pro	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win 7.5 Radio 5.71.09.02a_22.51.50.21U	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone
✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2020-12-15 / V. 59
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
57	HTC Desire	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android OS 2.2.2 sw. Nr. 2.29.110.6
58	HTC Desire HD	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android OS 2.3.5 sw. Nr. 3.12.405.1
59	HTC Desire S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android OS 2.3.5 2.10.401.8
60	HTC Desire X	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android OS 4.1.1 sw. Nr. 2.23.118.2
61	HTC Desire Z	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android OS 2.3.3 sw. Nr. 2.42.405.4
62	HTC Desire 310	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android OS 4.2.2 sw. Nr. 1.00.118.4
63	HTC EVO 3D X515m	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android OS 4.0.3 sw. Nr. 3.28.401.1
64	HTC Incredible S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android OS 4.0.4 sw. Nr. 4.10.405.1
65	HTC Legend	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	FW: 2.2 sw. Nr. 3.14.161.1
66	HTC Hero / T-Mobile G2 Touch	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	Android 2.1-update1 3.31.111.1
67	HTC Magic	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	Android 1.5 CRB43
68	HTC One	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.3 3.63.111.3
69	HTC One M8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.4.3 2.22.401.5
70	HTC One M9	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 6.0 3.35.111.14
71	HTC One Max	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.4.2 3.18.111.3
72	HTC ONE mini	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.4.2 3.10.401.6
73	HTC One S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.1.1 3.16.111.10
74	HTC One V	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.0.3 sw. Nr. 2.22.111.1
75	HTC One X	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.0.4 sw. Nr. 2.17.401.2
76	HTC Sensation	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android OS 4.0.3 sw. Nr. 3.33.111.51
77	HTC Tattoo	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	Android 1.6 SW 1.67.405.70
78	HTC Touch Diamond	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	Windows Mobile 6.1 OS 5.2.19965
79	HTC Touch DIAMOND 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	Windows Mobile 6.5 OS 5.2.21887
80	HTC Touch	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	Windows Mobile 6 OS 5.2.1238
81	HTC Touch2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	Windows Mobile 6.5 OS 5.2.21854
82	HTC Touch Cruise	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	3.13.407.0 GER
83	HTC Touch Dual	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	1.31.407.09
84	HTC Touch HD	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	ROM: 1.56.407.2 (43972) GER

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch) <http://bury.com/blackberrypatch/>
- ✓¹ only from phone

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2020-12-15 / V. 59
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
85	HTC HD mini	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	ROM: 1.07.407.1 (85429) GER
86	HTC HD2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	1.43.111.2 (70315) GER
87	HTC HD7	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.01	Win7.5 Radio sw:5.71.09.02a_22.51.50.21U	
88	HTC Touch Pro	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.02	19960.1.2.2	
89	HTC TyTN II	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.02	3.28.405.0 WWE Radio 1.65.16.25	
90	HTC U11	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 8.0.0 2.33.401.10	
91	HTC Wildfire	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 2.2.1 2.24.162.1	
92	HTC Windows Phone 8X	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Win 8 Radio sw:1.17b.32.19.14_15.52b.32.19	
93	HTC S730	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.02	CE OS 5.2.1622 (Build 18128.0.4)	
94	HUAWEI Ascend P1 U9200	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.01	Android 4.0.3 U9200-1V100R001C00B219	
95	HUAWEI G8 or GX8 (RIO-L01)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 5.1 RIO-L01C432B180	
96	HUAWEI Mate 8 (NXT-L29)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 6.0 NXT-L29C432B192	
97	HUAWEI Mate 9 (MHA-L29)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 7.0 MHA-L29C432B156	
98	HUAWEI Mate 10 Pro (BLA-L29)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 8.0.0 BLA-L29 8.0.0.142(C432)	
99	HUAWEI P8 (GRA-L9)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 5.0 GRA-L09V100R001C900B151	
100	HUAWEI P8 lite (ALE-L21)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 5.0.1 EMUI 3.1	
101	HUAWEI P9 (EVA-L09)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 6.0 EVA-L09C432B170	
102	HUAWEI P9 Lite (VNS-L21)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 6.0 VNS-L21C432B160	
103	HUAWEI P10 (VTR-L29)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 7.0 VTR-L29C432B112	
104	HUAWEI P10 Plus (VKY-L29)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 7.0 VKY-L29C432B150	
105	LG BL20 New Chocolate	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	BL20 V10j	
106	LG BL40 New Chocolate	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	BL40-MSM76XX-V10b-NOV-06-2009-DE	
107	LG E960 Nexus 4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.4.2 KOT49H	
108	LG Nexus 5	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.4.4 KTU84P	
109	LG Nexus 5X	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓					Android 7.0 NRD90R
110	LG G2 D802	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓					Android 4.2.2 D80210a-262-01
111	LG G2 mini LTE (D620r)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android 4.4.2 V10c-260-01	
112	LG G3 (D855)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android 4.4.2 V10i-260-01	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone
✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2020-12-15 / V. 59
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments	
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)		
113	LG G4 (H815)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 6.0 V20d-260-02	
114	LG G5 (H850)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 6.0.1 V10d-EUR-XX	
115	LG G6 (H870)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 7.0 V10F-EUR-XX	
116	LG G Flex (D955)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.4.2 D95520a-262-02	
117	LG GT500	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	GT500-10i	
118	LG KF 750 Secret	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓							KF750-V10a-24042008
119	LG KM 900 Arena	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓									KM900AT_V10t
120	LG P710 Optimus L7 II	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.1.2 SW LG-P71010e-EUR-XX	
121	LG P760 Optimus L9	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.1.2 SW LG-P76020h-EUR-XX	
122	LG P880 Optimus 4X HD	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.1.2 SW LG-P88020b-232-10	
123	LG Optimus 2X (P990 Optimus Speed)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 2.3.4 SW LGE LGP990-V20e	
124	LG V10 (H961N)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓					Android 5.1.1 SW V10c-SEA-XX
125	LG X power (K220)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓					Android 6.0.1 SW V10a-EUR_XX
126	Microsoft Lumia 532 Dual SIM	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Win8.1 Update SW 20c9.00076.0001	
127	Microsoft Lumia 535	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Win8.1 Update SW 20c9.00076.0001	
128	Microsoft Lumia 535 Dual SIM	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Win8.1 Update SW 20c9.00076.0001	
129	Microsoft Lumia 550	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Win10 Mobile SW 01078.00037.16082.41022	
130	Microsoft Lumia 640 Dual SIM	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Win8.1 Update 2 SW 20c9.00072.0001	
131	Microsoft Lumia 640 XL	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Win8.1 Update 2 SW 401c3.00009.0001	
132	Microsoft Lumia 650	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Win10 Mobile SW 01078.00037.16082.41010	
133	Microsoft Lumia 950	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Win10 Mobile SW 01078.00038.16025.39025	
134	Microsoft Lumia 950 XL	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓					Win10 Mobile SW 01078.00038.16082.36021
135	Motorola DEFY (MB525)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 2.2.2 JOREM_U33.4.2_179-6.1	
136	Motorola DEFY+ (MB526)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓				Android 2.3.6 4.5.1-134_DFP-231
137	Motorola Milestone	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 2.2.1 NK: SHOLS_U2_05.26.0	
138	Motorola Milestone 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓				Android 2.2 NK: MILS2_U6_4.1-22
139	Motorola Motoluxe (XT615)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 2.3.7 NK: 1_67C_4035	
140	Motorola Nexus 6	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 6.0.1 NK: MOB31E	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone
✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
141	Motorola RAZR i XT890	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓		✓		✓	0-07-0258-0.01	Android4.1.2 9.8.21-50_SMI-26.1358455837	
142	Motorola RAZR XT910	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓		✓	✓			Android 4.0.4 6.7.2-180_SPU-19-TA-11.6	
143	Nokia 6 (TA-1021)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓				Android 7.1.1 00WW_3_24A_SP03	
144	Nokia 8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	07-0257-0F.01	Android 7.1.1 00WW_3_09A	
145	Nokia 113	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓				✓	0-07-0258-0.04	V 03.24	
146	Nokia 208.1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓				✓	0-07-0258-0.01	V 06.01	
147	Nokia 500	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Symbian Belle Refresh 111.021.0028	
148	Nokia 515	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	0-07-0258-0.01	V 07.01	
149	Nokia 5230	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-10-04-0069-0	V 51.0.002	
150	Nokia 5530 XpressMusic	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-10-04-0069-0	V 11.0.054	
151	Nokia 6210 Navigator	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-10-04-0069-0	V 05.16	
152	Nokia 6300	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	0-10-04-0069-0	V07.30	
153	Nokia 6500c	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓			V09.48	
154	Nokia 6600i Slide	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	V 36.16	
155	Nokia 6700 classic	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	V 13.21	
156	Nokia Asha 300	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	0-07-0258-0.01	V07.65	
157	Nokia Asha 311	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	0-07-0258-0.01	V07.36.0.0	
158	Nokia C3-01 Touch and Type	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	0-07-0258-0.01	V 07.15	
159	Nokia C5	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	V 073.001	
160	Nokia C5-03	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	V 23.0.015	
161	Nokia C6	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-10-04-0069-0	V 42.0.004	
162	Nokia C7-00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Nokia Belle Refresh 111.040.1511	
163	Nokia E5-00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	0-10-04-0069-0	V 081.004	
164	Nokia E6-00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	Nokia Belle Refresh 111.140.0058	
165	Nokia E7-00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-10-04-0069-0	Symbian Belle 111.030.0609	
166	Nokia E51	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-10-04-0069-0	V411.34.001	
167	Nokia E52	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	033.002	
168	Nokia E55	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	022.009	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone

✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2020-12-15 / V. 59
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
169	Nokia E66	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓	✓	✓	0-10-04-0069-0	501.21.001
170	Nokia E71	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-10-04-0069-0	500.21.009
171	Nokia E72	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓	✓	✓	0-07-0258-0.01	091.003
172	Nokia Lumia 520	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓	✓	✓	0-07-0258-0.01	Win 8.0 SW 2.0.242020.8
173	Nokia Lumia 610	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓	✓	✓	0-07-0258-0.01	Win 7.8 Radio sw:1.0.66.00
174	Nokia Lumia 625	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓	✓	✓	0-07-0258-0.01	Win 8.0 Radio sw:3.2.28060.7
175	Nokia Lumia 635	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓	✓	✓	0-07-0258-0.01	Win 8.1 Radio sw:201c1.00401.0001
176	Nokia Lumia 800	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.01	Win 7.5 Radio sw:7.10.8107.79
177	Nokia Lumia 820	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓	✓	✓	0-07-0258-0.01	Win 8.0 sw: 1.0.202132.3
178	Nokia Lumia 920	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓	✓	✓	0-07-0258-0.01	Win 8.0 sw: 1.0.202132.3
179	Nokia Lumia 925	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓	✓	✓	0-07-0258-0.01	Win 8.0 Radio sw:3.2.04033.1
180	Nokia Lumia 930	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓	✓	✓	0-07-0258-0.01	Win8.1Radio sw:201c110.00039.0001
181	Nokia Lumia 1020 (909)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓	✓	✓	0-07-0258-0.01	Win 8.0 Radio sw:3.2.04047.1
182	Nokia Lumia 1520	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓	✓	✓	0-07-0258-0.01	Win8.1SW 02540.00019.15235.40004
183	Nokia N8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓	✓			✓	✓	✓	0-07-0258-0.01	Nokia Belle Refresh 111.040.1511
184	Nokia N9	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓	✓	✓	0-07-0258-0.01	V 40.2012.21-3.342.01.1_PR_342
185	Nokia N900	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓	✓	✓	0-07-0258-0.01	V 21.2011.38-1
186	Nokia X6	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓	✓	✓	0-10-04-0069-0	V 40.0.002
187	Nokia X7-00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓	✓	✓	0-07-0258-0.01	V 111.040.1511
188	OnePlus 2 (ONE A2003)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓		Android 6.0.1 ONE A2003_24_161227
189	RugGear LM802B	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓								78
190	RugGear P860 Explorer	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓		0-07-0258-0.01	78
191	Samsung A510F Galaxy A5 (2016)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓	✓	✓	0-07-0258-0.01	Android 5.1.1 swLMY47X.A510FXXS2APE2
192	Samsung A520F Galaxy A5 (2017)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓	✓	✓	07-0257-0F.01	Android 6.0.1 sw MMB29K.A520FXXU1APLP
193	Samsung Ace S5830	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓	✓	✓	0-07-0258-0.01	Android 2.3.6 sw S5830XWKU
194	Samsung B550H Xcover 550	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓	✓	✓	0-07-0258-0.01	B550HXXUAE6
195	Samsung B2700	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓							B2700XXIB2
196	Samsung E2121B	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓							E2121BXXKC1

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone
✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2020-12-15 / V. 59
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
197	Samsung G386F Galaxy Core LTE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.01	Android 4.2.2 JDQ39.G386FXXUANB4
198	Samsung G388F Galaxy Xcover 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.4.4 KTU84P.G388FXXU1AOG4
199	Samsung G800F Galaxy S5 mini	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.4.2 KOT49H.G800FXXU1IANJ2
200	Samsung G900F Galaxy S5	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓				Android 4.4.2 KOT49H.G900FXXU1ANCE
201	Samsung G903F Galaxy S5 Neo	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G903FXXU1BPF4
202	Samsung G920F Galaxy S6	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓				Android 5.0.2 LRX22G.G920FXXU1AOCV
203	Samsung G925F Galaxy S6 edge	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓				Android 5.0.2 LRX22G.G925FXXU1AOCV
204	Samsung G930F Galaxy S7	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓				Android 6.0.1 MMB29K.G930FXXU1APC8
205	Samsung G935F Galaxy S7 edge	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓				Android 6.0.1 MMB29K.G935FXXU1APC8
206	Samsung G950F Galaxy S8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓				Android 7.0 NRD90M.G950FXXU1AQDG
207	Samsung G955F Galaxy S8+	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓				Android 7.0 NRD90M.G955FXXU1AQDG
208	Samsung G973F Galaxy S10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓				Android9 PPR1.180610.011.G973FXXU1ASD5
209	Samsung G7105 Galaxy Grand 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	0-07-0258-0.01	Android 4.3 JLS36C.G7105XXUANF4
210	Samsung I8000 Omnia II	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓				I8000XXII6
211	Samsung I8150 Galaxy W	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	0-07-0258-0.01	Android 2.3.6 I8150XXLMI
212	Samsung I8160 Galaxy Ace 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	0-07-0258-0.01	I8160XXLI2
213	Samsung I8190 Galaxy S III mini	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	Android 4.1.2 I8190XXAMG4
214	Samsung i8320 Vodafone 360 H1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	0-07-0258-0.01	i8320BUIK1
215	Samsung I8700 Omnia 7	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win 7.5 Radio sw:2424.11.9.1
216	Samsung I8750 Ativ S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	Win 8.0 Radio sw: 2424.13.5.1
217	Samsung i8910 Omnia HD	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	0-07-0258-0.01	I8910XXJA2
218	Samsung I9000 Galaxy S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	0-07-0258-0.01	Android 2.3.6 I9000BOJW6
219	Samsung I9001 Galaxy S Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	0-07-0258-0.01	Android 2.3.6 I9001XXKPK
220	Samsung I9100 Galaxy S II	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	Android 4.1.2 I9100XXWLSS
221	Samsung I9195 Galaxy S 4 mini	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	Android 4.2.2 I9195XXUBMJ7
222	Samsung I9300 Galaxy S III	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	Android 4.1.2 sw: I9300XXAMG4
223	Samsung I9305 Galaxy S III Lte	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	Android 4.4.4 KTU84P.I9305XXUFOA1
224	Samsung I9505 Galaxy S4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓				Android 4.3 sw: J5S15J.I9505XXUEMKF

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone
✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2020-12-15 / V. 59
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments	
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)		
225	Samsung J320F Galaxy J3 (2016)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 5.1.1 LMY47V.J320FXXS0AQA1	
226	Samsung J510FN Galaxy J5 (2016)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android6.0.1 sw MMB29M.J510FNXXU2APK6	
227	Samsung N7000 Galaxy Note	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.01	Android 4.1.2 sw: N7000XLT4	
228	Samsung N7100 Galaxy Note II	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.01	Android 4.1.2 sw: N7100XXDME6	
229	Samsung N9005 Galaxy Note 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓			Android 4.3 JSS15J.N9005XXUDMJ7	
230	Samsung N910F Galaxy Note 4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓				Android 6.0.1 MMB29M.N910FXXU1DPI1	
231	Samsung N915FY Galaxy Note Edge	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓				Android 6.0.1 MMB29M.N915FYXXS1DPI1	
232	Samsung N950F Galaxy Note 8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 7.1.1 NMF26X.N950FXXU1AQ11	
233	Samsung S3650 Corby	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓				✓			S3650XXI13	
234	Samsung S5260 Star II	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	S5260XXKC4	
235	Samsung S5360 Galaxy Y	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 2.3.6 sw: S5360XXMK1	
236	Samsung S5570i Galaxy Mini	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓				Android 2.3.6 sw: S5570IXXLD6	
237	Samsung S5690 Galaxy Xcover	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓				Android 2.3.6 sw: S5690XXLJ2	
238	Samsung S6500 Galaxy mini 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 2.3.6 sw: S6500XXLK2	
239	Samsung S7220	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	S7220XXIB7
240	Samsung S7500 Galaxy Ace Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 2.3.6 S7500XXLK1	
241	Samsung S7560 Galaxy Trend (Ace II X)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.0.4 S7560XXAMF1	
242	Samsung S7580 Galaxy Trend Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.2.2 JDQ39.S7580XXUBOA1	
243	Samsung S7710 Galaxy Xcover 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓			Android 4.1.2 sw: S7710XXAMB5	
244	Samsung S8000 Jet	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	S8000XXIF5	
245	Samsung S8300V	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	S8300BUIC6	
246	Samsung S8500 Wave	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	S8500XXLA1
247	Samsung S8530 Wave II	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	S8530XXJKA	
248	Samsung S8600 Wave 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	S8600XXLD1	
249	Samsung SGH-i900 OMNIA 8GB	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓				i900XXIB2	
250	Samsung SGH-i900 OMNIA 16GB	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓								i900BOHH2	
251	Samsung Xcover 271 (B2710)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	B2710BOLL1
252	SONY Xperia E (C1505)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.1.1 sw 11.3.A.2.23	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone
✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2020-12-15 / V. 59
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
253	SONY Xperia J (ST26i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.1.2 sw 11.2.A.0.31
254	SONY Xperia M (C1905)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.3 sw 15.4.A.1.9
255	SONY Xperia P (LT22i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.1.2 sw 6.2.A.1.100
256	SONY Xperia S (LT26)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.1.2 sw 6.2.B.1.96
257	SONY Xperia SP (C5303)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.1.2 sw 12.0.A.2.254
258	SONY Xperia T (LT30p)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.1.2 sw 9.1.A.1.140
259	SONY Xperia T2 Ultra (D5303)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.4.3 sw 19.1.1.A.0.165
260	SONY Xperia Tipo (ST21i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.0.4 sw 11.0.A.22
261	SONY Xperia U (ST25i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.0.4 sw 6.1.1.B.1.54
262	SONY Xperia X Performance (F8131)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓								Android 7.1.1 sw 41.2.A.7.53
263	SONY Xperia XZ (F8331)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	07-0257-0F.01	Android 7.0 sw 39.2.A.0.417
264	SONY Xperia XZ Premium (G8142)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	07-0257-0F.01	Android 7.1.1 sw 45.0.A.7.137
265	SONY Xperia Z (C6603)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.2.2 sw 10.3.1.A.2.67
266	SONY Xperia Z Ultra (C6833)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓				Android 4.4.4 sw 14.4.A.0.108
267	SONY Xperia Z1 (C6903)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓				Android 4.4.2 sw 14.3.A.0.757
268	SONY Xperia Z1 Compact (D5503)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.4.4 sw 14.4.A.0.118
269	SONY Xperia Z2 (D6503)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓				Android 4.4.2 sw 17.1.A.2.55
270	SONY Xperia Z3 (D6603)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 5.0.2 sw 23.1.A.0.726
271	SONY Xperia Z3+ (C6553)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓				Android 6.0.1 sw 32.2.A.0.305
272	SONY Xperia Z3 Compact (D5803)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓				Android 6.0.1 sw 23.5.A.1.291
273	SONY Xperia Z5 (E6653)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓				Android 6.0.1 sw 32.2.A.0.253
274	Sony Ericsson C902	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.05	R3EG004
275	Sony Ericsson Elm	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.05	R7CA061
276	Sony Ericsson J105i Naite	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.05	R1GA026
277	Sony Ericsson K770i	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.05	R8BC004
278	Sony Ericsson Satio (Idou)	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.05	R2AK006
279	Sony Ericsson Vivaz	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	R2EA023
280	Sony Ericsson W610i	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	R6BC002

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone
✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2020-12-15 / V. 59
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
281	Sony Ericsson W890i	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	R1FA035
282	Sony Ericsson Xperia active (ST17)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.0.4 sw 4.1.B.0.587
283	Sony Ericsson Xperia Arc (LT15i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.0.4 sw 4.1.B.0.587
284	Sony Ericsson Xperia Arc S (LT18i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.0.4 sw 4.1.B.0.587
285	Sony Ericsson Xperia neo V (MT11i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.0.4 sw 4.1.B.0.587
286	Sony Ericsson Xperia ray	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.0.4 sw 4.1.B.0.587
287	Sony Ericsson Xperia X1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	ROM ver1.05.111.13 R3AA013
288	Sony Ericsson Xperia X8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 2.1-update1 2.1.1.C.0.0
289	Sony Ericsson Xperia X10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 2.3.3 3.0.1.G.0.75
290	Sony Ericsson Xperia X10 mini (E10i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 2.1-update1 2.1.1.C.0.0
291	Sony Ericsson Xperia X10 mini pro (U20i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 2.1-update1 2.1.1.A.0.6
292	Xiaomi Mi 4 LTE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	
293	Xiaomi Mi 5	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	07-0257-0F.01	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓¹ only from phone
- ✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.